

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

CAA-AD-025/2000

Datum vydání: 10. března 2000

LETADLO - DODÁVACÍ PALIVOVÉ ČERPADLO HLAVNÍ NÁDRŽE - KONTROLA/VÝMĚNA

Týká se: letadel Boeing 737-100, -200, -300, -400 a -500 pořadových čísel na výrobní lince 1 až 3002, certifikovaných v kterékoliv kategorii.

Datum účinnosti: 20. dubna 2000

Provést v termínech: Jak je popsáno v FAA AD 2000-04-02 (příloha tohoto PZZ).

Postup provedení prací: Dle FAA AD 2000-04-02.

Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát - Ing. Toman. Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě FAA AD 2000-04-02.

Ing. Pavel MATOUŠEK
Ředitel technického inspektorátu
Úřad pro civilní letectví

2000-04-02 BOEING: Amendment 39-11584. Docket 98-NM-150-AD.

Applicability: Model 737-100, -200, -300, -400, and -500 series airplanes; line numbers 1 through 3002 inclusive; certificated in any category.

NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fuel suction feed operation on both engines without flight crew indication, and possible consequent multiple engine power loss, accomplish the following:

Requirements for Airplanes Equipped with GEC Boost Pumps:

(a) For airplanes equipped with one or more main tank fuel boost pumps manufactured by the General Electric Company (GEC), of the United Kingdom: Accomplish paragraphs (a)(1), (a)(2), (a)(3), and (a)(4) of this AD.

(1) As of the effective date of this AD, no airplane shall be dispatched with any main tank fuel boost pump inoperative unless the initial testing and any follow-on corrective actions required by paragraph (a)(2) of this AD have been accomplished on the operative pump in that main tank.

(2) Test each GEC-manufactured main tank fuel boost pump to determine the output pressure, in accordance with Boeing Alert Service Bulletin 737-28A1114, Revision 1, dated April 2, 1998; at the later of the times specified in paragraphs (a)(2)(i) and (a)(2)(ii) of this AD. If the fuel boost pump output pressure measured during the testing required by this paragraph is less than 23 pounds per square inch gauge (psig), as measured at the input to the engine fuel pump; or less than 36 psig, as measured at the fuel boost pump low pressure switch; prior to further flight, replace the fuel boost pump with a new or serviceable fuel pump, in accordance with the alert service bulletin.

(i) Prior to the accumulation of 3,000 total flight hours, or within 1 year since date of manufacture of the airplane, whichever occurs first; or

(ii) Within 90 days after the effective date of this AD.

(3) Repeat the testing required by paragraph (a)(2) of this AD thereafter at intervals not to exceed 6 months, until accomplishment of the requirements of paragraph (a)(4) of this AD.

(4) Within 2 years after the effective date of this AD, replace all four low pressure switches installed downstream of the main tank fuel boost pumps with higher threshold low pressure switches, in accordance with Boeing Alert Service Bulletin 737-28A1114, Revision 1, dated April 2, 1998. Accomplishment of this replacement constitutes terminating action for the requirements of paragraphs (a)(1), (a)(2), and (a)(3) of this AD.

Requirements for Airplanes Equipped with non-GEC boost pumps:

(b) For airplanes other than those identified in paragraph (a) of this AD: Within 2 years after the effective date of this AD, replace all four low pressure switches installed downstream of the main tank fuel boost pumps with higher threshold low pressure switches, in accordance with Boeing Alert Service Bulletin 737-28A1114, Revision 1, dated April 2, 1998.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

NOTE 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The tests and replacements shall be done in accordance with Boeing Alert Service Bulletin 737-28A1114, Revision 1, dated April 2, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(f) This amendment becomes effective on March 29, 2000.

FOR FURTHER INFORMATION CONTACT:

Dorr Anderson, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2684; fax (425) 227-1181.

Issued in Renton, Washington, on February 14, 2000.

Donald L. Riggan, Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.