



ÚŘAD PRO CIVILNÍ LETECTVÍ
ČESKÁ REPUBLIKA
Sekce technická

letišťe Ruzyně, 160 08 Praha 6
tel: 233320922, fax: 220562270

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

Číslo: CAA-AD-041/2003

Datum vydání: 24. dubna 2003

BOEING

737-100, -200, -200C, -300, -400, -500

LETOUN - PODVOZEK - KONTROLA

Týká se: letadel Boeing 737-100, -200, -200C, -300, -400 a -500 certifikovaných v kterékoliv kategorii, pořadových čísel na výrobní lince 1 až 3132 včetně.

Datum účinnosti: 12. června 2003

Provést v termínech:

Jak je popsáno v FAA AD 2003-07-12, od data účinnosti tohoto PZZ.

Postup provedení prací:

Dle FAA AD 2003-07-12 (příloha tohoto PZZ).

Poznámky:

- Provedení tohoto PZZ musí být zapsáno do letadlové knihy.
- Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická - Ing. Toman.
- Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla.
- Tento PZZ byl vypracován na základě FAA AD 2003-07-12.

Ing. Pavel MATOUŠEK
ředitel

2003-07-12 Boeing: Amendment 39-13108. Docket 2000-NM-343-AD.

Applicability: Model 737-100, -200, -200C, -300, -400, and -500 series airplanes; certificated in any category; line numbers 1 through 3132 inclusive.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (g) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of landing gear parts, which could lead to landing gear collapse, accomplish the following:

Inspection of Parts and/or Records

(a) Within 10 years from the effective date of this AD, examine records and/or landing gear parts per Boeing Service Bulletin 737-32-1322, Revision 1, excluding Evaluation Form, dated September 27, 2001, to determine whether parts have serial numbers and whether the number of flight cycles for each part has been tracked. If landing gear parts have serial numbers, as listed in the service bulletin, and the number of flight cycles has been tracked, no further action is necessary for paragraphs (a), (b), or (c) of this AD.

Assignment of Serial Numbers and Flight Cycles

(b) If any part examined, as mandated in paragraph (a) of this AD, does not have a serial number, within 10 years from the effective date of this AD, do the actions required by paragraphs (b)(1) and (b)(2) of this AD.

(1) Assign a serial number to each part per Part 1.B. of the Accomplishment Instructions of Boeing Service Bulletin 737-32-1322, Revision 1, excluding Evaluation Form, dated September 27, 2001; or per a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA.

(2) Mark the serial number on each part per Boeing Service Bulletin 737-32-1322, Revision 1, excluding Evaluation Form, dated September 27, 2001.

(c) If flight cycles for any part examined, as mandated in paragraph (a) of this AD, have not been tracked, within 10 years from the effective date of this AD, assign a number of lifetime flight cycles to that part per Part 2.B. of the Accomplishment Instructions of Boeing Service Bulletin 737-32-1322, Revision 1, excluding Evaluation Form, dated September 27, 2001.

Removal From Service at Life Limit

(d) When any landing gear part has reached its life-limit number of flight cycles, as described in Part 2.B. of the Accomplishment Instructions of Boeing Service Bulletin 737-32-1322, Revision 1, excluding Evaluation Form, dated September 27, 2001, before further flight, remove that part from service and replace it with a landing gear part having a serial number and a lifetime flight cycle number per the service bulletin.

Parts Installation

(e) As of the effective date of this AD, no person shall install on any airplane a life-limited landing gear part unless it has been assigned a serial number and a lifetime flight cycle number per the requirements of this AD.

(f) As of the effective date of this AD, no person shall install on any airplane a life-limited landing gear part that has reached its life limit of flight cycles, per Boeing Service Bulletin 737-32-1322, Revision 1, excluding Evaluation Form, dated September 27, 2001.

Alternative Methods of Compliance

(g) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(h) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(i) Unless otherwise provided in this AD, the actions shall be done in accordance with Boeing Service Bulletin 737-32-1322, Revision 1, excluding Evaluation Form, dated September 27, 2001. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(j) This amendment becomes effective on May 20, 2003.