



ÚŘAD PRO CIVILNÍ LETECTVÍ
ČESKÁ REPUBLIKA
Sekce technická
letišťe Ruzyně, 160 08 Praha 6
tel: 233320922, fax: 220562270

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

Číslo: CAA-AD-047/2003

Datum vydání: 23. května 2003

The New Piper Aircraft, Inc.
PA-23, PA-23-160, PA-23-235, PA-23-
250, PA-E23-250

LETOUN – OVLÁDÁNÍ KLAPEK – KONTROLA/VÝMĚNA

Týká se: následujících letadel vyrobených firmou The New Piper Aircraft, Inc. certifikovaných ve kterékoliv kategorii, na kterých nejsou nainstalovány torzní tyče klapek katalogových čísel (P/N) 17634-002, nebo sestavy torzních tyčí klapek P/N 104622-002 nebo 104622-004.

Model	Výrobní číslo
PA-23 a PA-23-160	23-1 až 23-2046.
PA-23-235	27-505 až 27-622.
PA-23-250	27-1 až 27-504 a 27-2000 až 27-8154030.
PA-E23-250	27-2505 až 27-4916 a 27-7304917 až 27-7554168.

Důvod vydání: objevit a opravit poškození torzních tyčí klapek, což může vést k poruše funkce klapek. Jestliže k této poruše dojde během přistání nebo startu, může dojít ke ztrátě říditelnosti letounu.

Datum účinnosti: 10. července 2003.

Provést v termínech:

Jak je popsáno v FAA AD 2003-09-13 od data účinnosti tohoto PZZ.

Postup provedení prací:

Dle FAA AD 2003-09-13 (příloha tohoto PZZ).

Poznámky:

- Provedení tohoto PZZ musí být zapsáno do letadlové knihy.
- Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická – Ing. Shrbený.
- Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla.
- Tento PZZ byl vypracován na základě FAA AD 2003-09-13.

Ing. Pavel MATOUŠEK
ředitel

2003-09-13 The New Piper Aircraft, Inc.: Amendment 39-13142; Docket No. 2002-CE-44-AD.

(a) *What airplanes are affected by this AD?* This AD affects the following airplane models and serial numbers that are certificated in any category and do not incorporate a part number (P/N) 17634-002 flap control torque tube; or a P/N 104622-002 or 104622-004 flap control torque tube assembly:

Model	Serial numbers
PA-23 and PA-23-160	23-1 through 23-2046.
PA-23-235	27-505 through 27-622.
PA-23-250	27-1 through 27-504 and 27-2000 through 27-8154030.
PA-E23-250	27-2505 through 27-4916 and 27-7304917 through 27-7554168.

(b) *Who must comply with this AD?* Anyone who wishes to operate any of the airplanes identified in paragraph (a) of this AD must comply with this AD.

(c) *What problem does this AD address?* The actions specified by this AD are intended to detect and correct damage to the flap control torque tube, which could result in failure of the flap operating system. If such failure occurred during landing or takeoff, then a split flap condition could occur with potential loss of control of the airplane.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following:

Actions	Compliance	Procedures
(1) Inspect the flap control torque tube for cracks, corrosion, wear, or elongation of the attachment bolt holes (referred to as damage).	Initially inspect upon accumulating 2,500 hours time-in-service (TIS) on the flap control torque tube or within the next 100 hours TIS after June 23, 2003 (the effective date of this AD), whichever occurs later. Repetitively inspect thereafter at intervals not to exceed 500 hours TIS until a replacement flap control torque tube or flap control torque tube assembly specified in paragraph (d)(2) of this AD is installed.	In accordance with sections 3 through 10 of the ACCOMPLISHMENT INSTRUCTIONS section of Piper Mandatory Service Bulletin No. 1051B, dated November 5, 2002.
(2) Replace any damaged flap control torque tube and replace any wooden end plugs with new plastic end plugs, P/N 17631-002. Replace the flap control torque tubes with either a P/N 17634-002 flap control torque tube or a P/N 104622-002 or 104622-004 flap control torque tube assembly. (i) The P/N 17631-002 end plugs are part of the P/N 104622-002 and 104622-004 flap control torque tube assemblies, but must be obtained for the P/N 17634-002 installation. (ii) You do not have to inspect the existing wooden end plugs as	Prior to further flight after the inspection where damage is found.	In accordance with sections 3 through 10 of the ACCOMPLISHMENT INSTRUCTIONS section of Piper Mandatory Service Bulletin No. 1051B, dated November 5, 2002.

specified in the service bulletin since this AD requires the installation of plastic end plugs.		
(3) The repetitive inspections required by this AD may be terminated after installation of a replacement flap control torque tube or flap control torque tube assembly as specified in paragraph (d)(2) of this AD.	You may replace the flap control torque tube assembly at any time, but must replace prior to further flight if damage is found during an inspection.	In accordance with sections 3 through 10 of the ACCOMPLISHMENT INSTRUCTIONS section of Piper Mandatory Service Bulletin No. 1051B, dated November 5, 2002.

(e) *Can I comply with this AD in any other way?* To use an alternative method of compliance or adjust the compliance time, use the procedures in 14 CFR 39.19. Send these requests to the Manager, Atlanta Aircraft Certification Office. For information on any already approved alternative methods of compliance, contact Hassan Amini, Aerospace Engineer, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, Suite 450, Atlanta, Georgia 30349; telephone: (770) 703-6080; facsimile: (770) 703-6097.

(f) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Piper Mandatory Service Bulletin No. 1051B, dated November 5, 2002. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You may get copies from The New Piper Aircraft, Inc., Customer Services, 2926 Piper Drive, Vero Beach, Florida 32960; telephone: (561) 567-4361; facsimile: (772) 978-6573. You may view copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(g) *When does this amendment become effective?* This amendment becomes effective on June 23, 2003.