

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

CAA-AD-T-061/2000

Datum vydání: 12.července 2000

LETADLO - protipožární systém (ATA 26) - KONTROLA

Týká se: letadel ATR 42-200/-300/-320/-400 a -500, na kterých jsou namontovány páky požárních kohoutů vyrobené společností LABINAL P/N 19-51-41 a P/N 19-51-51 následujících S/N od 1330 až do 1526 kromě 1376, 1426, 1435, 1456, 1458, 1460 až 1463, 1465, 1467, 1470, 1478, 1479, 1484, až 1486, 1499, 1510 až 1519 a 1521 až 1525.

Datum účinnosti: 13. července 2000

Provést v termínech: Jak je popsáno v DGAC AD 2000-281-078(B) (příloha tohoto PZZ).

Postup provedení prací: Dle DGAC AD 2000-281-078(B).

Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát - Ing. Stibůrek. Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě DGAC AD 2000-281-078(B).

Ing. Pavel MATOUŠEK

Ředitel technického inspektorátu

Úřad pro civilní letectví

DGAC AD ref.: 2000-281-078(B)

AEROSPATIALE MATRA ATR

ATR 42 aircraft

Fire protection - Fire handles (ATA 26)

1. APPLICABILITY:

Models ATR 42-200/-300/-320/-400/-500 series airplanes equipped with LABINAL engine fire handles P/N 19-51-41 and P/N 19-51-51 the serial numbers of which are between 1330 and 1526 inclusive except S/N: 1376, 1426, 1435, 1456, 1458, 1460 to 1463, 1465, 1467, 1470, 1478, 1479, 1484 to 1486, 1499, 1510 to 1519 and 1521 to 1525.

2. REASONS:

During assembly line functional tests, random operation of certain fire handles, due to intermittent failure to switch of a part of the micro-switch assemblies, was observed.

The quality enquiry revealed that one production batch could have a control shaft guide bore machining defect leading to misalignment with respect to the micro-switch

assemblies.

The steps rendered mandatory by this Airworthiness Directive (AD) are intended to guarantee correct operation of the fire handles in the event of operation.

3. ACTIONS:

The following measures are rendered mandatory from the effective date of this AD.

A. Within 3 days after the effective date of this AD, insert a copy of this AD in the normal procedures chapter of the approved AFM and, before each flight and pending accomplishment of Service Bulletin (SB) ATR 42-26-0023, perform the engine fire protection test in accordance with the following procedure:

Engine 2 fire protection:

Depress SQUIB TEST pushbutton and check both AGENT SQUIB light illuminate.

Engine 1 fire protection:

Depress SQUIB TEST pushbutton and check both AGENT SQUIB light illuminate.

B. At the first opportunity, and at the latest before April 30, 2002, remove and replace the fire handles identified previously by handles that comply or have been inspected and repaired as necessary in accordance with the instruction of SB ATR 42-26-0023.

Application of the prescriptions of paragraph 3B cancels the engine fire protection pre-flight test required by paragraph 3A, and is the terminating action of this AD.

REF.: Service Bulletin ATR 42-26-0023

Any further approved revision of this SB is acceptable.

EFFECTIVE DATE: JULY 08, 2000