



ÚŘAD PRO CIVILNÍ LETECTVÍ  
ČESKÁ REPUBLIKA  
Sekce technická  
letišť Ruzyně, 160 08 Praha 6  
tel: 233320922, fax: 220562270

## PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

Číslo: CAA-AD-094/2003 - oprava

Datum vydání: 13. ledna 2004

Cessna Aircraft Company  
172R, 172S, 182S, 182T, T182T, 206H,  
T206H

### LETOUN - AUTOPILOT - MODIFIKACE

**Týká se:** letounů vyrobených firmou Cessna Aircraft Company vybavených počítačem autopilota KAP 140, katalogových čísel (P/N) 065-00176-2602, P/N 065-00176-5402, nebo P/N 065-00176-7702, následujících typů a výrobních čísel certifikovaných ve kterékoliv kategorii:

Typ	Výrobní čísla.
172R	17280001 až 17281073, 17281075 až 17281127, a 17281130
172S	172S8001 až 172S9195, 172S9197, 172S9198, a 172S9200 až 172S9203
182S	18280001 až 18280944
182T	18280945 až 18281064, 18281067 až 18281145, 18281147 až 18281163, 18281165 až 18281167, a 18281172
T182T	T18208001 až T18208109, a T18208111 až T18208177
206H	20608001 až 20608183, 20608185, 20608187, a 20608188
T206H	T20608001 až T20608039, T20608041 až T20608367, T20608369 až T20608379, T20608381, T20608382, a T20608385.

**Důvod vydání:** předejít neúmyslnému zapnutí systému autopilota KAP 140, což může vést k nepatřičné reakci pilota letounu.

**Datum účinnosti:** 19. února 2004.

**Provést v termínech:**

Jak je popsáno v FAA Correction AD 2003-24-13 od data účinnosti tohoto PZZ.

**Postup provedení prací:**

Dle FAA Correction AD 2003-24-13 (příloha tohoto PZZ).

*Poznámky:*

- Provedení tohoto PZZ musí být zapsáno do letadlové knihy.
- Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická – Ing. Shrbený.
- Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla.
- Tento PZZ byl vypracován na základě FAA Correction AD 2003-24-13.

**Ing. Pavel MATOUŠEK**  
ředitel

**2003-24-13 Cessna Aircraft Company:** Amendment 39-13382; Docket No. 2003-CE-28-AD.

*When Does This AD Become Effective?*

(a) This AD becomes effective on January 20, 2004.

*What Other ADs Are Affected by This Action?*

(b) None.

*What Airplanes Are Affected by This AD?*

(c) This AD affects the following airplane models and serial numbers that are:

(1) equipped with a KAP 140 autopilot computer system, part number (P/N) 065-00176-2602, P/N 065-00176-5402, or P/N 065-00176- 7702; and

(2) certificated in any category;

Model	Serial No.
172R	17280001 through 17281073, 17281075 through 17281127, and 17281130
172S	172S8001 through 172S9195, 172S9197, 172S9198, and 172S9200 through 172S9203
182S	18280001 through 18280944
182T	18280945 through 18281064, 18281067 through 18281145, 18281147 through 18281163,
	18281165 through 18281167, and 18281172
T182T	T18208001 through T18208109, and T18208111 through T18208177
206H	20608001 through 20608183, 20608185, 20608187, and 20608188
T206H	T20608001 through T20608039, T20608041 through T20608367, T20608369 through T20608379, T20608381, T20608382, and T20608385.

*What Is the Unsafe Condition Presented in This AD?*

(d) This AD is the result of reports of inadvertent and undetected engagement of the autopilot system. The actions specified in this AD are intended to prevent unintentionally engaging the KAP 140 autopilot computer system, which could cause the pilot to take inappropriate actions.

*What Must I Do To Address This Problem?*

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
(1) Install and update the KC 140 autopilot computer system operating software.	Within the next 100 hours time-in-service (TIS) after January 20, 2004 (the effective date of this AD), unless already done.	Follow Honeywell Service Bulletin No: KC 140-M1, dated August 2002, as specified in Cessna Service Bulletin SB02-22-01, dated November 25, 2002.
(2) Do the following: (i) Change the unit part number by attaching flavor sticker, part number (P/N) 057-02203-0003, on the unit's serial tag;. (ii) Attach an M decal, P/N 057-02984-0501, in front of the unit serial number (this indicates that the unit's P/N has been changed); and (iii) Attach a software mod tag. P/N	Prior to further flight after installing the update to the KC 140 autopilot computer system operating software, unless already done.	Follow Honeywell Service Bulletin No: KC 140-M1, dated August 2002, as specified in Cessna Service Bulletin SB02-22-01, dated November 25, 2002.

057-05287-0301, in place of the old tag to indicate the software change to SW MOD 03/01.		
(3) Only install KC 140 autopilot computer systems, P/Ns 065-00176-2602, 065-00176-5402, and 065-00176-7702, that have been modified as specified in paragraphs (d)(1) and (d)(2) of this AD).	As of January 20, 2004 (the effective date of this AD).	Not applicable.

(f) You may request a revised flight manual supplement from Cessna or Honeywell at the address specified in paragraph (h) of this AD.

**May I Request an Alternative Method of Compliance?**

(g) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.13. Send your request to the Manager, Wichita Aircraft Certification Office (ACO), FAA. For information on any already approved alternative methods of compliance, contact Dan Withers, Aerospace Engineer, Wichita Aircraft Certification Office, FAA, 1801 Airport Road, Wichita, Kansas 67209; telephone: (316) 946-4196; facsimile: (316) 946-4107.

**Does This AD Incorporate Any Material by Reference?**

(h) You must do the actions required by this AD per Honeywell Service Bulletin No: KC 140-M1, dated August 2002, as specified in Cessna Service Bulletin SB02-22-01, dated November 25, 2002. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. You may get a copy from Cessna Aircraft Company, Product Support, P.O. Box 7706, Wichita, Kansas 67277; telephone: (316) 517-5800; facsimile: (316) 942-9006 and Honeywell, Business, Regional, and General Aviation, 23500 W. 105th Street, Olathe, Kansas 66061. You may review copies at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**▼ Footer Information**

Issued in Kansas City, Missouri, on November 25, 2003.  
Michael Gallagher,  
Manager, Small Airplane Directorate,  
Aircraft Certification Service.  
[FR Doc. 03-30075 Filed 12-3-03; 8:45 am]