

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

CAA-AD-104/2000

Datum vydání: 15. listopadu 2000

LETOUN - LETOVÁ PŘÍRUČKA (AFM) - ZMĚNA

Týká se: letadel Boeing 737, certifikovaných v kterékoliv kategorii.

Datum účinnosti: 28. prosince 2000

Provést v termínech: Jak je popsáno v FAA AD 2000-22-02 (příloha tohoto PZZ).

Postup provedení prací: Dle FAA AD 2000-22-02.

Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát - Ing. Toman. Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě FAA AD 2000-22-02, který nahrazuje FAA AD 96-26-07.

Ing. Pavel MATOUŠEK
Ředitel technického inspektorátu
Úřad pro civilní letectví

2000-22-02 BOEING: Amendment 39-11948. Docket 2000-NM-325-AD. Supersedes AD 96-26-07, Amendment 39-9871.

Applicability: All Model 737 series airplanes, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To ensure that the flight crew is advised of the procedures necessary to address a condition involving a jammed or restricted rudder, accomplish the following:

RESTATEMENT OF CERTAIN REQUIREMENTS OF AD 96-26-07:

(a) Within 30 days after January 17, 1997 (the effective date of AD 96-26-07, amendment 39-9871): Revise the Emergency Procedures Section of the FAA-approved Airplane Flight Manual (AFM) to include the following recall item, which will enable the flight crew to take appropriate action to maintain control of the airplane during an uncommanded yaw or roll condition. This may be accomplished by inserting a copy of this AD in the AFM.

"UNCOMMANDED YAW OR ROLL

RECALL

Maintain control of the airplane with all available flight controls. If roll is uncontrollable, immediately reduce angle of attack and increase airspeed. Do not attempt to maintain altitude until control is recovered. If engaged, disconnect autopilot and autothrottle."

NEW REQUIREMENTS OF THIS AD:

(b) Within 30 days after the effective date of this AD: Revise the Normal Procedures Section of the FAA-approved AFM for Model 737-100 and -200 series airplanes or the Non-Normal Procedures Section of the FAA-approved AFM for Model 737-300, -400, -500, -600, -700, and -800 series airplanes, as applicable, to include the following procedure. This may be accomplished by inserting a copy of this AD in the AFM and removing the existing copy (inserted as required by AD 96-26-07), entitled "Jammed Flight Controls."

"UNCOMMANDED RUDDER

Condition: Uncommanded rudder pedal displacement or pedal kicks.

AUTOPILOT(if engaged) DISENGAGE

Maintain control of the airplane with all available flight controls. If roll is uncontrollable, immediately reduce pitch/angle of attack and increase airspeed. Do not attempt to maintain altitude until control is recovered.

AUTOTHROTTLE (if engaged) DISENGAGE

Verify thrust is symmetrical.

YAW DAMPER SWITCH OFF

RUDDER TRIM CENTER

RUDDER PEDALS FREE & CENTER

Use maximum force including a combined effort of both pilots, if required to free and center the rudder pedals.

If rudder pedal position or movement is not normal and the condition is not the result of rudder trim:

SYSTEM B FLIGHT CONTROL SWITCH STBY RUD

A slight rudder deflection may remain, but continued rudder pedal pressure may help maintain an in-trim condition.

Sufficient directional control is available on landing using differential braking and nose wheel steering.

Crosswind capability may be reduced.

Do not use autobrakes.

Consider checking rudder freedom of movement at a safe altitude using slow rudder inputs while in the landing configuration and at approach speed.

If condition was the result of rudder trim or environmental factors:

YAW DAMPER SWITCH. ON

Accomplish the normal DESCENT – APPROACH and LANDING checklists."

(c) It is acceptable to modify the format of the above procedure to reflect the format used by individual carriers. However, the procedural sequence, memory items, and/or associated text may not be modified, except by submitting a request for an alternative method of compliance (AMOC) as specified in paragraph (d) of this AD.

Alternative Methods of Compliance

(d) An AMOC or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Operations Inspector, who may add comments and then send it to the Manager, Seattle ACO.

NOTE 1: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Effective Date

(f) This amendment becomes effective on November 13, 2000.

FOR FURTHER INFORMATION CONTACT: Steve O’Neal, Aerospace Engineer, Flight Test Branch, ANM-160S, Seattle Aircraft Certification Office, FAA, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2699; fax (425) 227-1181.

Issued in Renton, Washington, on October 20, 2000.

John J. Hickey, Manager, Transport Airplane Directorate, Aircraft Certification Service.

