

# PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

**CAA-AD-1-018/98**

Datum vydání: 12. března 1998

## LETADLO - ZMĚNA V LETOVÉ PŘÍRUČCE

**Týká se:** letadel vyrobených Raytheon Aircraft Company následujících typů a verzí: E55, E55A, 58, 58A, 58P, 58PA, 58TC, a 58TCA a 60, 65-B80, 65-B90, 90, F90, 100, 300 a B300 všech výrobních čísel, certifikovaných v kterékoliv kategorii.

### Důvod vydání:

- 1) Přezkoumání certifikačních podmínek výše uvedených letadel pro lety v podmínkách námrazy, nové informace a zkušenosti s provozováním těchto letadel v prostředí, ve kterém se vyskytuje nebezpečí námrazy.
- 2) Minimalizovat potenciální nebezpečí spojené s provozem těchto letadel v podmínkách silné námrazy.

**Datum účinnosti:** 19.03.1998

**Provést v termínech:** jak je popsáno v části "Compliance" FAA AD 98-04-24 (příloha tohoto PZZ).

**Postup provedených prací:** dle části "Compliance" FAA AD 98-04-24 (příloha tohoto PZZ).

*Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát - Ing. Příhoda. Pokud to vyžaduje povaha tohoto PZZ musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě FAA AD 98-04-24.*

**Ing. Pavel MATOUŠEK**

**Ředitel technického inspektorátu**

**Úřad pro civilní letectví**

## 98-04-24 RAYTHEON AIRCRAFT COMPANY

Amendment 39-10336; Docket No. 97-CE-58-AD.

**Applicability:** Models E55, E55A, 58, 58A, 58P, 58PA, 58TC, and 58TCA Airplanes and 60, 65-B80, 65-B90, 90, F90, 100, 300, and B300 series airplanes (all serial numbers), certificated in any category.

NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless already accomplished.

To minimize the potential hazards associated with operating the airplane in severe icing conditions by providing more clearly defined procedures and limitations associated with such conditions, accomplish the following:

a. Within 30 days after the effective date of this AD, accomplish the requirements of paragraphs (a)(1) and (a)(2) of this AD.

NOTE 2: Operators should initiate action to notify and ensure that flight crewmembers are apprised of this change

(1) Revise the FAA-approved Airplane Flight Manual (AFM) by incorporating the following into the Limitations Section of the AFM. This may be accomplished by inserting a copy of this AD in the AFM.

## **“WARNING**

Severe icing may result from environmental conditions outside of those for which the airplane is certificated. Flight in freezing rain, freezing drizzle, or mixed icing conditions (supercooled liquid water and ice crystals) may result in ice build-up on protected surfaces exceeding the capability of the ice protection system, or may result in ice forming aft of the protected surfaces. This ice may not be shed using the ice protection systems, and may seriously degrade the performance and controllability of the airplane.

- During flight, severe icing conditions that exceed those for which the airplane is certificated shall be determined by the following visual cues. If one or more of these visual cues exists, immediately request priority handling from Air Traffic Control to facilitate a route or an altitude change to exit the icing conditions.

1. Unusually extensive ice accumulation on the airframe and windshield in areas not normally observed to collect ice.

2. Accumulation of ice on the upper surface of the wing, aft of the protected area.

- Accumulation of ice on the engine nacelles and propeller spinners farther aft than normally observed.
- Since the autopilot, when installed and operating, may mask tactile cues that indicate adverse changes in handling characteristics, use of the autopilot is prohibited when any of the visual cues specified above exist, or when unusual lateral trim requirements or autopilot trim warnings are encountered while the airplane is in icing conditions.
- All wing icing inspection lights must be operative prior to flight into known or forecast icing conditions at night. [NOTE: This supersedes any relief provided by the Master Minimum Equipment List (M MEL).]

(2) Revise the FAA-approved AFM by incorporating the following into the Normal Procedures Section of the AFM. This may be accomplished by inserting a copy of this AD in the AFM

## **.”THE FOLLOWING WEATHER CONDITIONS**

### **MAY BE CONDUCTIVE TO SEVERE**

## IN-FLIGHT ICING:

- Visible rain at temperatures below 0 degrees Celsius ambient air temperature.
- Droplets that splash or splatter on impact at temperatures below 0 degrees Celsius ambient air temperature.

## PROCEDURES FOR EXITING

### THE SEVERE ICING ENVIRONMENT:

These procedures are applicable to all flight phases from takeoff to landing. Monitor the ambient air temperature. While severe icing may form at temperatures as cold as -18 degrees Celsius, increased vigilance is warranted at temperatures around freezing with visible moisture present. If the visual cues specified in the Limitations Section of the AFM for identifying severe icing conditions are observed, accomplish the following:

- Immediately request priority handling from Air Traffic Control to facilitate a route or an altitude change to exit the severe icing conditions in order to avoid extended exposure to flight conditions more severe than those for which the airplane has been certificated.
  - Avoid abrupt and excessive maneuvering that may exacerbate control difficulties.
  - Do not engage the autopilot.
  - If the autopilot is engaged, hold the control wheel firmly and disengage the autopilot.
  - If an unusual roll response or uncommanded roll control movement is observed, reduce the angle-of-attack.
  - Do not extend flaps when holding in icing conditions. Operation with flaps extended can result in a reduced wing angle-of-attack, with the possibility of ice forming on the upper surface further aft on the wing than normal, possibly aft of the protected area.
  - If the flaps are extended, do not retract them until the airframe is clear of ice.
  - Report these weather conditions to Air Traffic Control.”
- a. Incorporating the AFM revisions, as required by this AD, may be performed by the owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7), and must be entered into the aircraft records showing compliance with this AD in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).
  - b. Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.
  - c. An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Small Airplane Directorate, FAA, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

NOTE 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

- d. All persons affected by this directive may examine information related to this AD at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12<sup>th</sup> Street, Kansas City, Missouri 64106.
- e. This amendment (39-10339) becomes effective on March 13, 1998.

**FOR FURTHER INFORMATION CONTACT:** Mr. John P. Dow, Sr., Aerospace Engineer, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas

City, Missouri 64106; telephone (816) 426-6932; facsimile (816) 426-2169.