



ÚŘAD PRO CIVILNÍ LETECTVÍ
ČESKÁ REPUBLIKA
Sekce technická
letišťe Ruzyně, 160 08 Praha 6
tel: 233320922, fax: 220562270

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

Číslo: 2008-0139

Datum účinnosti: 07. srpna 2008

Diamond Aircraft Industries GmbH
DA 42


Tento PZZ je vydáván pro výrobek transferovaný pod působnost EASA

Na základě rozhodnutí EASA je následující Příkaz k zachování letové způsobilosti závazný pro všechny výrobky provozované v EU, na které se daný PZZ vztahuje.

Provedení PZZ, který se vztahuje podle typu a výrobního čísla na výrobek je pro provozovatele/vlastníka letadla zapsaného do leteckého rejstříku závazné. Neprovedením PZZ ve stanoveném termínu dojde ke ztrátě letové způsobilosti výrobku.

Poznámky:

- Provedení tohoto PZZ musí být zapsáno do provozní dokumentace letadla.
- Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická.
- Pokud to vyžaduje povaha tohoto PZZ, musí být zpracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla.

EASA	AIRWORTHINESS DIRECTIVE	
	<p>AD No.: 2008-0139</p> <p>Date: 24 July 2008</p> <p>Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>	
<p>This AD is issued in accordance with EC 1702/2003, Part 21A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].</p>		
<p>Type Approval Holder's Name :</p> <p>Diamond Aircraft Industries GmbH</p>	<p>Type/Model designation(s) :</p> <p>DA 42 aircraft</p>	
<p>TCDS Number : EASA.A.005</p>		
<p>Foreign AD : Not applicable</p>		
<p>Supersedure: None</p>		
<p>ATA 71</p>	<p>Power Plant – Rear Engine Support Bracket Mounting Bolts – Inspection / Replacement</p>	
<p>Manufacturer(s): Diamond Aircraft Industries GmbH (DAI)</p>		
<p>Applicability:</p>	<p>DA 42 aircraft, all serial numbers, if Thielert TAE125-01 engines are installed. The engines identified by serial number in DAI Mandatory Service Bulletin MSB-42-058 have been installed on the aircraft with wedge locking washers and bonded-in bolts and are therefore not affected by this AD.</p>	
<p>Reason:</p>	<p>In-service experience indicates that the powder coating of the rear right hand (RH) engine support bracket degrades over time, leading to a reduced torque of the engine mountings bolts. In some cases, bolts had fully unscrewed and fell into the engine cowling. One case was reported where the pilot had to shut down an engine in flight because of a failed V-belt, the cause of failure assumed to be one of these bolts. This condition, if not corrected, may lead to further cases of loose bolts and subsequent damage to the engine or accessories in the engine compartment, possibly resulting in in-flight engine shut-down and reduced control of the aircraft.</p> <p>To address and correct this situation, DAI has published MSB-42-058, providing instructions to accomplish repetitive inspections and correction of the fastening torque of the affected engine mounting bolts and replacement of the bolts with wire-secured bolts Part Number (P/N) D60-9071-26-01, after which the repetitive torque checks are no longer required.</p> <p>For the reasons described above, this EASA AD requires the accomplishment of repetitive torque checks of the affected engine mounting bolts and replacement of the bolts with wire-secured bolts.</p>	
<p>Effective Date:</p>	<p>07 August 2008</p>	

Required action(s) and Compliance Time(s):	<p>Required as indicated, unless accomplished previously:</p> <ol style="list-style-type: none"> (1) Within 100 flight hours (FH) after the effective date of this AD and thereafter at intervals not to exceed 100 FH, perform the inspection and correction of the fastening torque of the RH rear engine support bracket mounting bolts in accordance with DAI MSB-42-058 and the associated Work Instruction WI-MSB-42-058 (Action 1). (2) Not later than 30 April 2009, replace all RH rear engine support bracket mounting bolts with wire-secured bolts P/N D60-9071-26-01 in accordance with DAI MSB-42-058 and the associated Work Instruction WI-MSB-42-058 (Action 2). (3) After installation of wire-secured bolts P/N D60-9071-26-01 as required by paragraph (2) of this AD, the repetitive torque checks of paragraph (1) of this AD are no longer required. (4) After 30 April 2009, no person shall install spare RH rear engine support bracket mounting bolts as replacement parts on any aircraft to which this AD applies, except wire-secured bolts identified by P/N D60-9071-26-01.
Ref. Publications:	<p>Diamond Aircraft Industries GmbH Mandatory Service Bulletin MSB-42-058 dated 21 May 2008 and the associated Work Instruction WI-MSB-42-058 dated 12 March 2008.</p> <p>The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.</p>
Remarks :	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD. 2. This AD was posted on 25 June 2008 as PAD 08-072 for consultation until 23 July 2008. No comments were received during the consultation period. 3. Enquiries regarding this AD should be referred to the Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA; E-mail ADs@easa.europa.eu. 4. For any question concerning the technical content of the requirements in this AD, please contact: Diamond Aircraft Industries GmbH, Austria. Telephone +43 2622 26700, Facsimile +43 2622 26780, E-mail office@diamond-air.at