



ÚŘAD PRO CIVILNÍ LETECTVÍ

SEKCE TECHNICKÁ

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

Číslo: 2009-0235

Účinnost od: 12. listopadu 2009

AIRBUS

A318, A319, A320, A321

Tento PZZ je vydáván pro výrobek transferovaný pod působnost EASA.

Na základě rozhodnutí EASA je následující Příkaz k zachování letové způsobilosti závazný pro všechny výrobky provozované v EU na které se daný PZZ vztahuje.

Provedení PZZ, který se vztahuje podle typu a výrobního čísla na výrobek je pro provozovatele/vlastníka letadla zapsaného do leteckého rejstříku závazné. Neprovedením PZZ ve stanoveném termínu dojde ke ztrátě letové způsobilosti výrobku.

Poznámky:

- Provedení tohoto PZZ musí být zapsáno do provozní dokumentace letadla.
- Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická.
- Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla.

| | | |
|---|--|--|
| EASA | AIRWORTHINESS DIRECTIVE | |
|  | AD No.: 2009 - 0235 | |
| | Date: 29 October 2009 | |
| <p>Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p> | | |
| <p>This AD is issued in accordance with EC 1702/2003, Part 21A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].</p> | | |
| Type Approval Holder's Name : | Type/Model designation(s) : | |
| AIRBUS | A318, A319, A320 and A321 aeroplanes | |
| TCDS Number : | EASA.A.064 | |
| Foreign AD : | Not applicable | |
| Supersedure : | None | |
| ATA 24 | Electrical Power – AC and DC ESS BUS Power Supply - Modification | |
| Manufacturer(s): | Airbus (formerly Airbus Industrie) | |
| Applicability: | Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-111, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231 and A321-232 aeroplanes, all manufacturer serial numbers, except aeroplanes that have received Airbus modification (MOD) 37317 in production. | |
| Reason: | <p>Several occurrences of loss of the AC BUS 1 have been reported which led in some instances to the loss of the AC ESS BUS and DC ESS BUS and connected systems. The affected systems include multiple flight deck Display Units (Primary Flight Display, Navigation Display and Upper Electronic Centralised Aircraft Monitoring display).</p> <p>The reasons for these events have been investigated but have not been fully established for all cases.</p> <p>Due to the range of system losses some crews reported difficulty in establishing the failure cause during the events and, consequently, the appropriate actions to be taken may not be completed in a timely manner.</p> <p>The loss of multiple display units, if not corrected expediently during a high workload period, potentially affects the capability of the flight crew and could contribute to a loss of situational awareness and consequent control</p> | |

| | |
|--|--|
| | <p>of the aeroplane, which would constitute an unsafe condition.</p> <p>This AD therefore mandates the modification of the electrical network configuration management logic consisting in adding an automatic switching of the AC and DC ESS BUS power supply such that upon the loss of the AC BUS 1, the AC BUS 2 will automatically take over the power supply. On pre-MOD aeroplanes, this power supply switching can only be accomplished manually from the cockpit and is covered by an Electronic Centralized Aircraft Monitoring (ECAM) procedure.</p> |
| Effective Date: | 12 November 2009 |
| Required action(s) and Compliance Time(s): | <p>Required as indicated, unless accomplished previously:</p> <p>(1) Within 48 months after the effective date of this AD, modify the Electrical Power Distribution System in accordance with the instructions of Airbus Service Bulletin (SB) A320-24-1120 Revision 3.</p> <p>(2) For aeroplanes previously modified in accordance with SB A320-24-1120 at any previous revision, no further action is required by this AD.</p> |
| Ref. Publications: | <p>Airbus Service Bulletin A320-24-1120 Revision 3 dated 10 July 2009.</p> <p>The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.</p> |
| Remarks: | <ol style="list-style-type: none"> 1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD. 2. This AD was posted on 29 June 2009 as PAD 09-086 for consultation until 29 July 2009. The Comment Response Document can be found at http://ad.easa.europa.eu. 3. Enquiries regarding this AD should be referred to the Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA. E-mail: ADs@easa.europa.eu . 4. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – EAS, Fax +33 5 61 93 44 51, E-mail: account.airworth-eas@airbus.com . |