

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

CAA-AD-4-097/98

Datum vydání: 29. prosince 1998

LETADLO - TURBÍNA POHÁNĚNÁ NÁPOROVÝM VZDUCHEM (RAT)- KONTROLA

Týká se: letadel Airbus A300, A310 a A300-600 uvedených v DGAC AD 95-163-182(B) R4 (příloha tohoto PZZ).

Datum účinnosti: 28. ledna 1999

Provést v termínech: jak je popsáno v DGAC AD 95-163-182(B) R4.

Postup provedených prací: dle DGAC AD 95-163-182(B) R4.

Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát - Ing. Toman. Pokud to vyžaduje povaha tohoto PZZ musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě DGAC AD 95-163-182(B) R4 a nahrazuje AD 95-163-182(B) R3.

Ing. Pavel MATOUŠEK
Ředitel technického inspektorátu
Úřad pro civilní letectví

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 95-163-182(B) R4

In case of any difficulty, reference should be made to the French original issue.

AIRBUS INDUSTRIE

A300 A300-600 A310 Aircraft

Ram Air Turbine (RAT) uplock pin - Corrosion inspection

This Airworthiness Directive applies to AIRBUS INDUSTRIE A300, A310 and A300-600 aircraft, all certified models and all serial numbers, on which series modifications 11527 or AIRBUS INDUSTRIE Service Bulletins A300-29-0109, A310-29-2077 or A300-29-6038 have not been embodied.

Undetected corrosion of the RAT uplock pin/shaft and the needle bearing supporting the feedthrough from the RAT uplock unit to the lever which is actuated by control cable, may prevent the RAT from extending.

Consequently, the following measures are rendered mandatory from the effective date of this Airworthiness Directive :

1) Before the aircraft reaches 30 months of service after delivery or before July 20, 1996, whichever occurs later, perform on ground, a ram air turbine extension test and remove the lever assy and perform a visual inspection in accordance with the instructions of AIRBUS INDUSTRIE Service Bulletins A300-29-0108, A310-29-2076 or A300-29-6037.

Note 1: The aircraft which have already been inspected as per the instructions of AIRBUS INDUSTRIE A.O.T. 29-16 of June 28, 1995, or A.O.T. 29-16 revision 1 dated January 10, 1996, are not concerned by the requirements of paragraph 1 of this Airworthiness Directive.

2) Repeat the inspections in accordance with the instructions of AIRBUS INDUSTRIE Service Bulletins A300-29-0108, A310-29-2076 of A300-29-6037 every 30 months or modify the RAT uplock unit in accordance with the instructions of AIRBUS INDUSTRIE Service Bulletins A300-29-0109, A310-29-2077 or A300-29-6038.

Note 2 : Should corroded parts be found, they must be scrapped and replaced by airworthy parts within the following 12 months. If they are re-used temporarily, they must be cleaned and greased before reinstallation.

Note 3 : Inform AIRBUS INDUSTRIE of all inspection findings, whatever they may be.

Note 4 : No further action in accordance with the Airworthiness Directive is required after accomplishment of AIRBUS INDUSTRIE Service Bulletins A300-29-0109, A310-29-2077 or A300-29-6038.

Ref. : AIRBUS INDUSTRIE A.O.T. 29-16 dated June 28, 1995
AIRBUS INDUSTRIE A.O.T. 29-16 Rev.1 dated January 10, 1996
AIRBUS INDUSTRIE Service Bulletin A300-29-0108
AIRBUS INDUSTRIE Service Bulletin A310-29-2076
AIRBUS INDUSTRIE Service Bulletin A300-29-6037
AIRBUS INDUSTRIE Service Bulletin A300-29-0109
AIRBUS INDUSTRIE Service Bulletin A310-29-2077
AIRBUS INDUSTRIE Service Bulletin A300-29-6038
(or any later approved revision).

This Revision 4 replaces AD 95-163-182(B) R3 dated May 07, 1997.

EFFECTIVE DATES :

Original AD . AUGUST 26, 1995

Revision 1 . APRIL 20, 1996

Revision 2 . JUNE 15, 1996

Revision 3 . MAY 17, 1997

Revision 4 . NOVEMBER 28, 1998