



ÚŘAD PRO CIVILNÍ LETECTVÍ
ČESKÁ REPUBLIKA
Sekce technická
letišťe Ruzyně, 160 08 Praha 6
tel: 233320922, fax: 220562270

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

Číslo: 2006-0077

Datum účinnosti: 12. dubna 2006

AIRBUS SAS
A310, A300-600


Tento PZZ je vydáván pro výrobek transferovaný pod působnost EASA

Na základě rozhodnutí EASA je následující Příkaz k zachování letové způsobilosti závazný pro všechny výrobky provozované v EU na které se daný PZZ vztahuje.

Provedení PZZ, který se vztahuje podle typu a výrobního čísla na výrobek je pro provozovatele/vlastníka letadla zapsaného do leteckého rejstříku závazné. Neprovedením PZZ ve stanoveném termínu dojde ke ztrátě letové způsobilosti výrobku.

Poznámky:

- Provedení tohoto PZZ musí být zapsáno do provozní dokumentace letadla.
- Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická.
- Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla.

EASA	AIRWORTHINESS DIRECTIVE	
	<p>AD No: 2006 - 0077</p> <p>Date: 03 April 2006</p>	
<p>No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry.</p>		
<p>Type Approval Holder's Name:</p> <p>AIRBUS SAS</p>	<p>Type/Model designations:</p> <p>A310 and A300-600 aircraft</p>	
<p>TCDS Number: France No 145</p>		
<p>Foreign AD: None</p>		
<p>Supersedure: None</p>		
ATA 33	Lights - BRUCE Floor Proximity Emergency Escape Path Marking System FPEEPMS	
<p>Manufacturer(s):</p>	<p>AIRBUS SAS, AIRBUS INDUSTRIES.</p>	
<p>Applicability:</p>	<p>AIRBUS aircraft, models A310-308, A310-324, A310-325, A300B4-605R, all serial numbers on which one of the two AIRBUS modifications, No. 06810 or 06934 (Bruce Floor Proximity Emergency Escape Path Marking System - FPEEPMS) has been embodied in production and on which AIRBUS Service Bulletin (SB) A310-33-2045 Revision 1 or A300-33-6047 Revision 1 as applicable (AIRBUS modifications n° 12751 and 13084) has not been embodied in service.</p>	
<p>Reason:</p>	<p>A study has shown that the architecture of the BRUCE FPEEPMS is not in compliance with regulatory requirement FAR 25.812 as, in case of vertical segregation of the fuselage forward of door 1, the FPEEPMS and the EXIT signs do not come on.</p> <p>Airworthiness Directive (AD) 2004-102, which dealt with the same subject, rendered mandatory modifications to the FPEEPMS to ensure its operation in compliance with the regulatory requirements. SBs A310-33-2045 and A300-33-6047 at original issue were issued for this purpose.</p> <p>However, it turns out that the instructions given in the original issues of these SBs were not fully satisfactory. This is the reason why AD 2004-102 had been cancelled and this AD renders mandatory the embodiment of revision 1 of these SBs.</p>	
<p>Effective Date:</p>	<p>12 April 2006.</p>	

Compliance:	Before July 31st, 2007, unless already accomplished, carry out the electrical modifications to the BRUCE FPEEPMS in accordance with the instructions of SB A310-33-2045 Revision 1 or A300-33-6047 Revision 1.
Ref. Publications:	AIRBUS Service Bulletins: A310-33-2045 Revision 1 A300-33-6047 Revision 1 or later approved revisions.
Remarks:	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated the responsible EASA manager for the related product has the authority to accept Alternative Methods of Compliance (AMOCs) for this AD. 2. This AD was posted as PAD 06-036 for consultation on 15 February 2006 with a comment period until 14 March 2006. The Comment Response Document can be found at http://www.easa.eu.int/home/aw_dir_en.html. 3. Enquiries regarding this Airworthiness Directive should be referred to Mr. M. Capaccio, Airworthiness Directive Focal Point - Certification Directorate, EASA. E-mail: ADs@easa.eu.int. 4. For any question concerning the technical content of the requirements in this AD, please contact AIRBUS SAS - EAW (Airworthiness Office, Ph.: + 33 5 61 93 36 96; Fax: + 33 5 61 93 44 51).