



ÚŘAD PRO CIVILNÍ LETECTVÍ
ČESKÁ REPUBLIKA
Sekce technická
letišťe Ruzyně, 160 08 Praha 6
tel: 233320922, fax: 220562270

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

Číslo: CF-2007-16

Datum účinnosti: 17. září 2007

Bell Helicopter Textron Canada
vrtulník řada 206, 206L

Tento PZZ je vydáván pro výrobek transferovaný pod působnost EASA

Na základě rozhodnutí EASA je následující Příkaz k zachování letové způsobilosti závazný pro všechny výrobky provozované v EU, na které se daný PZZ vztahuje.

Provedení PZZ, který se vztahuje podle typu a výrobního čísla na výrobek je pro provozovatele/vlastníka letadla zapsaného do leteckého rejstříku závazné. Neprovedením PZZ ve stanoveném termínu dojde ke ztrátě letové způsobilosti výrobku.

Poznámky:

- Provedení tohoto PZZ musí být zapsáno do provozní dokumentace letadla.
- Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická.
- Pokud to vyžaduje povaha tohoto PZZ, musí být zpracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla.



No.	CF-2007-16	1/2
Issue Date	24 August 2007	

AIRWORTHINESS DIRECTIVE

The following airworthiness directive (AD) may be applicable to an aircraft which our records indicate is registered in your name. ADs are issued pursuant to **Canadian Aviation Regulation (CAR) 593**. Pursuant to **CAR 605.84** and the further details of **CAR Standard 625, Appendix H**, the continuing airworthiness of a Canadian registered aircraft is contingent upon compliance with all applicable ADs. Failure to comply with the requirements of an AD may invalidate the flight authorization of the aircraft. Alternative means of compliance shall be applied for in accordance with **CAR 605.84** and the above-referenced **Standard**.

This AD has been issued by the Continuing Airworthiness Division (AARDG), Aircraft Certification Branch, Transport Canada, Ottawa, telephone 613 952-4357.

- Number:** CF-2007-16
- Subject:** Disc Assemblies –Tail rotor driveshaft (Thomas Couplings)
- Effective:** 17 September 2007
- Applicability:** Bell Helicopter Textron Canada (BHTC) Model 206 series helicopters S/N up to 4618 and Model 206L series helicopters S/N up to 52340.
- Compliance:** As indicated, unless already accomplished.
- Background:** It has been determined that Disc Assemblies part number (P/N) 32721-1 manufactured between 1 November 2005 through 30 November 2006, may have discs of improper thickness or discs may have been indexed incorrectly.

Corrective Actions: **A. Verification**

As soon as possible, but not later than 25 hours air time or 30 days from the effective date of this directive, verify Disc Assemblies P/N 32721-1 those installed on helicopter and those in the inventory, for manufacturing date, proper thickness and indexing, in accordance with instructions provided in applicable Alert Service Bulletins (ASB) listed below or later revisions approved by the Chief, Continuing Airworthiness, Transport Canada.

Helicopter Model	Alert Service Bulletin
206 series	ASB-206-07-114 dated 28 March 2007
206L series	ASB-206L-07-145 dated 28 March 2007

B. Corrections

1. For Disc Assembly at inventory:

- (a) If manufacturing date is not between 1 November 2005 and 30 November 2006, the Disc Assemblies do not require further action.
- (b) If required, adjust the thickness of Disc Assembly by removing or adding a new disc.
- (c) If required, re-index Disc Assembly as per applicable Maintenance Manual.
- (d) Attach to Disc Assembly a serviceable tag with inscription indicating compliance to applicable ASB.

2. For Disc Assembly installed on aircraft

- (a) Within 10 hours air time, remove Disc Assembly which is not within the required thickness of 0.115 - 0.127 inch (2.921 - 3.225 mm).

Pursuant to **CAR 202.51** the registered owner of a Canadian aircraft shall, within seven days, notify the Minister in writing of any change of his or her name or address.

To request a change of address, contact the **Civil Aviation Communications Centre (AARC)** at Place de Ville, Ottawa, Ontario K1A 0N8, or 1-800-305-2059, or www.tc.gc.ca/civilaviation/communications/centre/address.asp



- (b) Within 300 hours air time or at next scheduled inspection, whichever comes first, remove Disc Assembly which is not properly indexed.
- (c) If Disc Assemblies, as per verification above, do not require any further action, or manufacturing date is not between 1 November 2005 and 30 November 2006, make a log book annotation to this effect.

Authorization: For Minister of Transport, Infrastructure and Communities

P. Tang
Acting Chief, Continuing Airworthiness

Contact: Mr. Bogdan Gajewski, Continuing Airworthiness, Ottawa, telephone (613) 952-4450, facsimile (613) 996-9178 or e-mail: gajewsb@tc.gc.ca or any Transport Canada Centre