



ÚŘAD PRO CIVILNÍ LETECTVÍ
ČESKÁ REPUBLIKA
Sekce technická
letišťe Ruzyně, 160 08 Praha 6
tel: 233320922, fax: 220562270

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

Číslo: 2006-07-02

Datum účinnosti: 21. srpna 2006

EMBRAER

model EMB-135BJ

Tento PZZ je vydáván pro výrobek transferovaný pod působnost EASA

Na základě rozhodnutí EASA je následující Příkaz k zachování letové způsobilosti závazný pro všechny výrobky provozované v EU na které se daný PZZ vztahuje.

Provedení PZZ, který se vztahuje podle typu a výrobního čísla na výrobek je pro provozovatele/vlastníka letadla zapsaného do leteckého rejstříku závazné. Neprovedením PZZ ve stanoveném termínu dojde ke ztrátě letové způsobilosti výrobku.

Poznámky:

- Provedení tohoto PZZ musí být zapsáno do provozní dokumentace letadla.
- Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická.
- Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla.



REPÚBLICA FEDERATIVA DO BRASIL
AGÊNCIA NACIONAL DE AVIAÇÃO CIVIL – ANAC

BRAZILIAN AIRWORTHINESS DIRECTIVE

AD No.: 2006-07-02

Effective Date: 21 Aug. 2006

The following Brazilian Airworthiness Directive (AD), issued by the Agência Nacional de Aviação Civil (ANAC) in accordance with provisions of Chapter IV, Title III of Código Brasileiro de Aeronáutica - Law No. 7,565 dated 19 December 1986 - and Regulamento Brasileiro de Homologação Aeronáutica (RBHA) 39, applies to all aircraft registered in the Registro Aeronáutico Brasileiro. No person may operate an aircraft to which this AD applies, unless it has previously complied with the requirements established herein.

AD No. 2006-07-02 - EMBRAER - Amendment 39-1147.

APPLICABILITY:

This Airworthiness Directive is applicable to Embraer EMB-135BJ aircraft model in operation.

CANCELLATION / REVISION:

Not applicable.

REASON:

It has been found cases in which some wiring harnesses were not protected in accordance with SFAR-88 requirements.

Since this condition may exist in other airplanes of the same model and affects flight safety, a corrective action is required. Thus, sufficient reason exists to request compliance with this AD in the indicated time limit.

REQUIRED ACTION:

Installation of heat shrinkable sleeves and nipples to protect the wiring and their terminals.

COMPLIANCE:

Required as indicated below, unless already accomplished.

Within the next 5000 flight hours after the effective date of this AD, install heat shrinkable sleeves on the inspection and refueling panel illumination lights wiring, as well as nipples to protect the wire terminals.

The detailed instructions and procedures to accomplish this AD are described in the Embraer Service Bulletin No. 145LEG-28-0016 Rev. 01, or further revisions approved by the ANAC.

Record compliance with this AD in the applicable maintenance log book.

CONTACT:

For additional technical information, contact:

National Agency of Civil Aviation (ANAC)

Aeronautical Products Certification Branch (GGCP)

Praça Mal. Eduardo Gomes, Nº 50, Vila das Acácias (Prédio do CTA-IFI)

Fax: 55 (12) 3941-4766

12228-901 – São José dos Campos - SP, BRAZIL

E-mail: pds@ifi.cta.br

For acquisition, contact:

National Agency of Civil Aviation (ANAC)
Publications Branch
R. Santa Luzia, 651, 2º Mezanino, Centro
Fax: 55 (21) 3814-6929
20030-040 – Rio de Janeiro - RJ, BRAZIL.
e-mail: publicacoes@anac.gov.br

APPROVAL:

CLÁUDIO PASSOS SIMÃO
General Manager
GGCP

MILTON ZUANAZZI
Director-President
ANAC

NOTE: Original in Portuguese language signed and available in the files of the Aeronautical Products Certification Branch (GGCP) of the National Agency of Civil Aviation (ANAC).