EASA	PROPOSED AIRWORTHINESS DIRECTIVE			
X	AD No: 2006 - 0167			
×	Date: 14 June 2006			
No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry.				
Type Approval Holder's Name:		Type/Model designation(s):		
Robinson Helicopter Company		R22		
TCDS Number: FAA H10WE Rev. 12				
Foreign AD: None				
Supersedure: CAA Additional Airworthiness Directives 002–10–94				
ATA 52	Doors – Hinges – Modification			
Manufacturer(s):	Robinson Helicopter Company			
Applicability:	All Robinson R22 Helicopters			
Reason:	To reduce the likelihood of an in-flight separation of a door from the helicopter.			
Effective Date:	28 June 2006			
Compliance:		ed within the next 1000 hours time-in-service (TIS) or within 2 years after the /e date of this AD, whichever occurs soonest		
	Replace the left and right hand lower door-mounted hinge parts (Part Nos. A227–3 and A227–4) with parts having the same Part No. but to Revision H or later standard.			
		pin which protrudes only ¼ inch from the hinge nave a clevis pin which protrudes 0.45 inches.		
	Revision G parts, if fitted, are acceptable provided that the hole drilled in the clevis pin is orientated so as to permit installation of a split pin. Install split pins (cotter pins) Part No. MS24665–151 in upper and lower hinges of both left and right hand doors.			
Ref. Publications:	None			
Remarks:		substantiated the responsible EASA manager for thority to accept Alternative Methods of Compliance		
		6-094 for consultation on 06 April 2006 with a 2006. The Comment Response Document can be		

	found at http://ad.easa.eu.int/.
3.	Enquiries regarding this Airworthiness Directive should be referred to Mr. M. Capaccio, Airworthiness Directive Focal Point - Certification Directorate, EASA. E-mail: <u>ADs@easa.eu.int</u>
4.	For questions concerning the technical contents of this AD requirements, contact Robinson Helicopter Company (Ph.: +1 (310) 539 0508; Fax +1 (310) 539 5198).