



ÚŘAD PRO CIVILNÍ LETECTVÍ
ČESKÁ REPUBLIKA
Sekce technická
letišťe Ruzyně, 160 08 Praha 6
tel: 233320922, fax: 220562270

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

Číslo: 2007-0141-E

Datum účinnosti: 23. května 2007

EUROCOPTER

model AS 350, AS 355

Tento PZZ je vydáván pro výrobek transferovaný pod působnost EASA

Na základě rozhodnutí EASA je následující Příkaz k zachování letové způsobilosti závazný pro všechny výrobky provozované v EU, na které se daný PZZ vztahuje.

Provedení PZZ, který se vztahuje podle typu a výrobního čísla na výrobek je pro provozovatele/vlastníka letadla zapsaného do leteckého rejstříku závazné. Neprovedením PZZ ve stanoveném termínu dojde ke ztrátě letové způsobilosti výrobku.

Poznámky:

- Provedení tohoto PZZ musí být zapsáno do provozní dokumentace letadla.
- Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická.
- Pokud to vyžaduje povaha tohoto PZZ, musí být zpracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla.

EASA	EMERGENCY AIRWORTHINESS DIRECTIVE	
	<p>AD No: 2007- 0141-E</p> <p>Date: 21 May 2007</p>	
<p>No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry.</p>		
<p>Type Approval Holder's Name:</p> <p>EUROCOPTER</p>	<p>Type/Model designation(s):</p> <p>AS 350 and AS 355</p>	
<p>TCDS Number: EASA.R.008 & EASA.R.146</p>		
<p>Foreign AD: Not applicable.</p>		
<p>Supersedure: Not applicable</p>		
<p>ATA 67</p>	<p>Rotor Flight Controls - Main & Tail Rotors Servo-Controls - Inspection / Replacement.</p>	
<p>Manufacturer(s):</p>	<p>EUROCOPTER – (formerly EUROCOPTER-FRANCE, AEROSPATIALE)</p>	
<p>Applicability:</p>	<p>EUROCOPTER helicopters models: - AS 350 B, BA, BB, B1, B2, B3 and D - AS 355 E, F, F1, F2 and N, all serial numbers, and equipped with GOODRICH main rotor servo-controls and tail rotor servo-controls with no letter "C" marked in the inspection box of the servo-control identification plate, and with the following Part Numbers (P/N) and Serial Numbers (S/N): - Main rotor servo-controls P/N SC5083 with S/N 270M, 272M, 409M, 423M, 452M or 1573 P/N SC5083-1 with S/N from 2902 to 2921 inclusive P/N SC5084 with S/N 30, 84, 104, 186, 438, 575 or 695 P/N SC5084-1 with S/N from 1462 to 1481 inclusive. And - Tail rotor servo-controls: P/N SC5072 with serial number 222M, 306M or 309.</p>	
<p>Reason:</p>	<p>An internal review revealed that some main and tail rotor servo-controls do not conform to the approved design. This results in a greater play in the input lever bearing which could lead to off-centered lever/distributor slide valve. If not corrected, this condition could jam the distributor slide valve in its sleeve contributing to reduced controllability of the rotors. Such a jamming would be detected during the pre-flight hydraulic check by a "hard point" in the flight controls. This Airworthiness Directive requires identification of the affected main and tail rotor servo-controls and mandates additional attention during the pre flight check and subsequent replacement.</p>	

Effective Date:	23 May 2007
Compliance:	<p>1. Before further flight, verify the Part Number (P/N) and Serial Number (S/N) of the main rotor and tail rotor servo-controls in accordance with paragraph (§) 1.E.2. of EUROCOPTER Alert Service Bulletin (ASB) No. 01.00.58 Revision 1 for AS 350 helicopters and ASB No. 01.00.53 Revision 1 for AS 355 Helicopters</p> <p>Note 1: Instead of inspecting the rotorcraft, a review of the helicopter maintenance records along with any other applicable data (rotorcraft logbook, Components list, etc...) is acceptable if each P/N and S/N can be positively determined from that review.</p> <p>2. When a servo-control whose P/N and S/N are listed in the applicability section of this AD, is identified:</p> <p style="padding-left: 40px;">2.1 During each pre-flight test (see Rotorcraft Flight Manual section 4) and until accomplishment of § 2.2 of this AD, Check thoroughly that no "hard point" exists in the flight controls.</p> <p>If any "hard point" is detected in the flight controls, Prior to next flight replace the defective servo-control(s) as instructed in § 2.B. of EUROCOPTER ASB No. 01.00.58 Revision 1 for AS 350 helicopters and ASB No. 01.00.53 Revision 1 for AS 355 Helicopters.</p> <p style="padding-left: 40px;">2.2 Within the next 50 Flight Hours or 4 months after the effective date of this AD, whichever occurs first, replace all servo-controls that are identified in the Applicability Section of this AD, as instructed in § 2.B. of EUROCOPTER ASB No. 01.00.58 Revision 1 for AS 350 helicopters and ASB No. 01.00.53 Revision 1 for AS 355 Helicopters</p> <p>3. As of the effective date of this AD, no person shall install rotors servo-controls whose P/N and S/N are listed in the applicability section of this AD, on any EUROCOPTER AS 350 and AS 355 helicopters unless they have been previously returned to conformity by the equipment manufacturer as indicated in § 2. of EUROCOPTER ASB No. 01.00.58 Revision 1 for AS 350 helicopters and ASB No. 01.00.53 Revision 1 for AS 355 Helicopters</p>
Ref. Publications:	EUROCOPTER AS 350 Alert Service Bulletin No. 01.00.58 Revision 1 EUROCOPTER AS 355 Alert Service Bulletin No. 01.00.53 Revision 1 or any subsequent approved revision.
Remarks:	<p>1. If requested and appropriately substantiated the responsible EASA manager for the related product has the authority to accept Alternative Methods of Compliance (AMOCs) for this AD.</p> <p>2. The safety assessment has requested not to implement the full consultation process and an immediate publication and notification.</p> <p>3. Enquiries regarding this Airworthiness Directive should be referred to the AD Focal Point - Certification Directorate, EASA. E-mail: ADs@easa.europa.eu .</p> <p>4. For any question concerning the technical content of the requirements in this AD, please contact: EUROCOPTER (STDI) - Aéroport de Marseille Provence 13725 Marignane Cedex - France. Tel: 33 (0) 4 42 85 97 97 - Fax: 33 (0) 4 42 85 99 66. E-mail: Directive.technical-support@eurocopter.com</p>