


EASA	AIRWORTHINESS DIRECTIVE	
	<p>AD No : 2007-0093</p> <p>Date: 11 April 2007</p>	
No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry.		
Type Approval Holder's Name :	Type/Model designation(s) :	
AIRBUS	A300, A310 and A300-600 aircraft	
TCDS Number: France No.145		
Foreign AD: Not applicable		
Supersedure: Not applicable		
ATA 21	Air conditioning – Airplane flight Manual – Emergency Procedure	
Manufacturer(s):	AIRBUS, (formerly AIRBUS INDUSTRIE)	
Applicability:	AIRBUS A300, A310, A300-600 aircraft, all certified models and all serial numbers.	
Reason:	<p>The present AD requires the flight crew to follow the instructions of the “emergency procedure check of delta P = 0” of the Aircraft Flight Manual (AFM) at the latest revision date.</p> <p>This AD falls within the scope of a set of corrective measures developed by AIRBUS subsequent to accidents which occurred to in-service aircraft caused by the violent opening of the passenger door related to excessive residual pressure in the cabin.</p>	
Effective Date:	25 April 2007	
Compliance:	From the effective date of this AD, unless already accomplished, verify that the Aircraft Fight Manual contains the modification of the emergency evacuation procedures as incorporated into Chapter 3.02.00 of the following A300, A310 and A300-600 AFM revisions:	

	A300 aircraft		A310 aircraft		A300-600 aircraft	
	Model	AFM revision number	Model	AFM revision number	Model	AFM revision number
	A300 B2-1C	31	A310-203	28	A300 B4-620	15
	A300 B4-2C	36	A310-221	26	A300 C4-620	16
	A300 B2K-3C	26	A310-222	23	A300 B4-601	14
	A300 B2-203	22	A310-322	17	A300 B4-603	14
	A300 B4-103	24	A310-304	17	A300 B4-605R	12
	A300 B4-203	30	A310-204	15	A300 B4-622	11
	A300 B4-120	21	A310-222	15	A300 B4-622R	11
	A300 B4-220	15	A310-324	14	A300 F4-605R	9
	A300 C4-203	21	A310-308	12	A300 C4-605R-F	8
	A300 F4-203	10	A310-325	11	A300 F4-622R	9
	<p>The flight crew must follow this procedure.</p> <p>It is the operators' responsibility to ensure that their AFM is at a revision number equal to or higher than the one listed above.</p>					
Ref. Publications:	A300, A310 and A300-600 AFM revision numbers as listed in the compliance paragraph, or later approved revisions.					
Remarks :	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated the responsible EASA manager for the related product has the authority to accept Alternative Methods of Compliance (AMOCs) for this AD. 2. This AD was posted on 25 January 2007 as PAD 07-014 for consultation until 20 February 2007. The Comment Response Document can be found at http://ad.easa.europa.eu/. 3. Enquiries regarding this Airworthiness Directive should be referred to the AD Focal Point - Certification Directorate, EASA. E-mail: ADs@easa.europa.eu . 4. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS SAS – EAW Airworthiness Office, telephone:+ 33 5 61 93 36 96, facsimile: + 33 5 61 93 44 51. 					