

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

CAA-AD-004/2000

Datum vydání: 17. ledna 2000

LETADLO - PROTIPOŽÁRNÍ SYSTÉM - VÝMĚNA SIGNALIZÁTORU DÝMU

Týká se: letadel SAAB SF 340A výrobních čísel -004 až -159 a SAAB 340B výrobních čísel -160 až -459.

Datum účinnosti: 24. února 2000

Provést v termínech: Jak je popsáno v SAD č. 1-151 (příloha tohoto PZZ).

Postup provedení prací: Dle SAD č. 1-151.

Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát - Ing. Stibůrek. Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě SAD č. 1-151.

Ing. Pavel MATOUŠEK
Ředitel technického inspektorátu
Úřad pro civilní letectví

SWEDISH AIRWORTHINESS DIRECTIVES (SAD) No: 1-151

AIRCRAFT TYPE: SAAB SF 340A and SAAB 340B

SERIAL No's. AFFECTED: SAAB SF 340A -004 through -159 and SAAB 340B -160 through -459

SUBJECT: Fire Protection - Cargo compartment smoke detectors - Replace Fenwall smoke detector with Cerberus smoke detector

BACKGROUND: Field experience has demonstrated bad reliability with the Fenwall smoke detectors located in the cargo compartment. During high humidity environmental conditions false warnings have occurred causing the flight crew to perform the necessary emergency procedures. New developments in smoke detector technology have made it possible to produce detectors that are substantially less susceptible to humidity and thereby minimizing false warnings. This SAD mandates replacement of the current cargo compartment smoke detectors with new units that have increased reliability and decreased maintenance.

REFERENCE DOCUMENTS: Saab Aircraft AB Mandatory Service Bulletin SAAB 340-26-023 dated 21 Dec.1999 or later revision

ACTIONS: Perform actions described in Saab Aircraft AB Mandatory Service Bulletin SAAB 340-26-023 dated 21 December 1999 or later revision

COMPLIANCE TIME: To be performed within 2 years from effective date of this SAD.

EFFECTIVE DATE: 1999-12-28