



CIVIL AVIATION AUTHORITY
CZECH REPUBLIC
Airworthiness Division

*Airport Ruzyně, 160 08 Prague 6
Tel: 420 233320922, fax: 420 220562270*

AIRWORTHINESS DIRECTIVE

Number: CAA-AD-037/2004

Date of issue: April 19, 2004

BOEING

737-600, -700, -700C, -800, -900

AIRCRAFT - AURAL WARNING FOR THE LANDING GEAR - REPLACEMENT

Applicability: Model 737-600, -700, -700C, -800, and -900 series airplanes, as listed in Boeing Alert Service Bulletin 737-32A1343, dated July 26, 2001; certificated in any category.

Effective date: June 10, 2004

Compliance: Required as indicated FAA AD 2004-07-10.

Remarks: The compliance of this AD must be recorded in Aircraft Logbook, where applicable the requirements of this AD must be integrated into Aircraft Technical Documentation. Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyně Airport, 160 08 Prague 6, Czech Republic, tel.: 420 2 33320922, fax: 420 2 20562270.

Ing. Pavel MATOUŠEK
Director

2004-07-10 Boeing: Amendment 39-13554. Docket 2002-NM-101-AD.

Applicability: Model 737-600, -700, -700C, -800, and -900 series airplanes, as listed in Boeing Alert Service Bulletin 737-32A1343, dated July 26, 2001; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent a malfunction of the aural warning for the landing gear, leading the crew to open the circuit breaker for the aural warning horn which stops the operation of other aural warnings of malfunctions in other systems and, thus, could jeopardize a safe flight and landing, accomplish the following:

Replacement

(a) Within 18 months after the effective date of this AD: Remove the Proximity Switch Electronics Unit (PSEU) having part number 285A1600-2 or 285A1600-3 and replace it with a PSEU having part number 285A1600-4, per the Accomplishment Instructions of Boeing Alert Service Bulletin 737-32A1343, dated July 26, 2001.

Parts Installation

(b) As of the effective date of this AD, no person shall install a PSEU having part number 285A1600-2 or 285A1600-3 on any airplane.

Alternative Methods of Compliance

(c) In accordance with 14 CFR 39.19, the Manager, Seattle Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance (AMOCs) for this AD.

Incorporation by Reference

(d) The actions shall be done in accordance with Boeing Alert Service Bulletin 737-32A1343, dated July 26, 2001. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(e) This amendment becomes effective on May 11, 2004.

Footer Information

Issued in Renton, Washington, on March 22, 2004.
Kalene C. Yanamura,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.
[FR Doc. 04-7127 Filed 4-5-04; 8:45 am]
BILLING CODE 4910-13-P