

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

CAA-AD-044/1999R1

Datum vydání: 20. září 1999

LETADLO - PODVOZEK (BRZDOVÉ SOUPRAVY) - KONTROLA/VÝMĚNA

Týká se: letadel SAAB SF 340A výrobních čísel -004 až -159 a SAAB 340B výrobních čísel -160 až -459, jak je uvedeno v SAD č. 1-139R1 (příloha tohoto PZZ).

Datum účinnosti: 02. prosince 1999

Provést v termínech: Jak je popsáno v SAD č. 1-139R1.

Postup provedení prací: Dle SAD č. 1-139R1.

Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát - Ing. Stibůrek. Pokud to vyžaduje povaha tohoto PZZ musí být zpracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě SAD č. 1-139R1.

Ing. Pavel MATOUŠEK
Ředitel technického inspektorátu
Úřad pro civilní letectví

AIRWORTHINESS DIRECTIVE NO: 1-139R1

AIRCRAFT TYPE: SAAB SF 340A and SAAB 340B

SERIAL No's AFFECTED: SAAB SF340A, S/N 004 through 159 and SAAB 340B S/N 160 through 459 equipped with ABSC Brake Stack or Hitco Technologies, Inc. Brake Stack Kit, FAA STC No. ST00341LA

SUBJECT: Landing Gear - Brakes - Inspection of the installation combination of the brake assemblies.

BACKGROUND: During introduction of ABSC brake assembly 5012589-3 (SB 340-32-113) a restriction regarding the installation combinations of brake assemblies (5012589-1, 5012589-2 and 5012589-3) was found necessary in order to avoid unbalanced aircraft handling situation and degradation of brake performance. Only symmetrical brake assemblies installations are permitted.

Hitco Technologies, Inc Brake Stack Kit part number 3001049, FAA STC No. ST00341LA applies only to ABSC brake assemblies 5012589-1 or 5012589-2.

REFERENCE DOCUMENTS: Saab Aircraft AB Service Bulletin SAAB 340-32-114, dated 4 May 1998 FAA STC No. ST00341LA.

ACTIONS: Perform actions described in SAAB Aircraft Bulletin SAAB 340-32-114, dated 4 May 1998 or later revision. All approved combinations are to be found in table 1 on page 2 in above SB.

COMPLIANCE TIME: To be performed within 2 months after effective date of this SAD.

EFFECTIVE DATE: 1999-10-01