

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

CAA-AD-074/2000

Datum vydání: 03. srpna 2000

LETOUN - ŠTÍTEK - INSTALACE

Týká se: letadel BOEING B 737-600, -700, -800, uvedených v Boeing Alert Service Bulletin 737-23A1170, z 27. dubna 2000, certifikovaných v kterékoliv kategorii..

Datum účinnosti: 07. září 2000

Provést v termínech: Jak je popsáno v FAA AD 2000-14-02 (příloha tohoto PZZ).

Postup provedení prací: Dle FAA AD 2000-14-02.

Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát - Ing. Toman. Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě FAA AD 2000-14-02.

Ing. Pavel MATOUŠEK

Ředitel technického inspektorátu

Úřad pro civilní letectví

2000-14-02 BOEING: Amendment 39-11811. Docket 2000-NM-209-AD.

Applicability: Model 737-600, -700, and -800 series airplanes, as listed in Boeing Alert Service Bulletin 737-23A1170, dated April 27, 2000; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent loss of communication between the flight crew and Air Traffic Control (ATC), which could result in the flight crew being unaware of an unsafe scenario when the airplane is on the ground, accomplish the following:

Installation of Placards

(a) Within 60 days after the effective date of this AD, install placards on the P3-1 panel in accordance with Boeing Alert Service Bulletin 737-23A1170, dated April 27, 2000.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) The installation shall be done in accordance with Boeing Alert Service Bulletin 737-23A1170, dated April 27, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(e) This amendment becomes effective July 28, 2000.

FOR FURTHER INFORMATION CONTACT: Jay Yi, Aerospace Engineer, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1013; fax (425) 227-1181.

Issued in Renton, Washington, on July 3, 2000.

Vi L. Lipski, Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.