

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

CAA-AD-090/2000

Datum vydání: 18. září 2000

KLUZÁK - LETOVÁ PŘÍRUČKA, PŘÍRUČKA PRO ÚDRŽBU A OPRAVY - ZMĚNA

Týká se: kluzáků ASW 27 vyrobených firmou Alexander Schleicher výrobních čísel 27001 až 27104 a 27106 až 27118.

Důvod vydání: pro zachování letové způsobilosti výrobce opravil a modifikoval některé strany letové příručky, příručky pro údržbu a příručky pro opravy.

Datum účinnosti: 02. listopadu 2000.

Provést v termínech: Jak je popsáno v LBA AD 2000-305 (příloha tohoto PZZ).

Postup provedení prací: Dle pokynů v LBA AD 2000-305.

Poznámky: Provedení tohoto PZZ musí být zapsáno do deníku kluzáku. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát - Ing. Shrbený. Pokud to vyžaduje povaha tohoto PZZ, musí být zpracováno do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě LBA AD 2000-305.

Ing. Pavel MATOUŠEK
Ředitel technického inspektorátu
Úřad pro civilní letectví

LBA AD No.: 2000-305

Effective Date: October 05, 2000

Affected:

Kind of aeronautical product: Sailplane

Manufacturer: Alexander Schleicher, Poppenhausen, Germany

Type: ASW 27

Models affected: all

Serial numbers affected 27001 up to 27104 and 27106 up to 27118

German Type Certificate No.: 389

Subject:

Exchange of pages Into the Flight, Maintenance- and Repair Manual.

Reason:

In case of continuous airworthiness the manufacturer corrected and modified some pages of the Flight, Maintenance and Repair Manual.

Action:

Exchange of some pages into the Flight, Maintenance - and Repair Manual In accordance with the instructions given in the Technical Note of the manufacturer (action "B" of the Technical Note).

Compliance:

The exchange of the Aircraft Documents must done before the next annual inspection, but not later than December 31, 2000.

Technical publication of the manufacturer:

Alexander Schleicher ASW 27 Technical Note No. 6 dated May 16. 2000 which becomes herewith part of this AD and may be obtained from Messrs:

Alexander Schleicher

GmbH & Co.

Segelflugzeugbau

D- 36163 Poppenhausen

Federal Republic of Germany

Phone ++ 49 6658 89-0, Fax: ++ 49 6658 89-40

Mail: sales@alexander-schleicher.de

Accomolishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the log book by a licensed inspector.

Holders of affected aircraft registered in Germany have to observe the following:

As a result of the a.m. deficiencies, the airworthiness of the aircraft is affected to such an extent that after the expiry

of the a.m. dates the aircraft may be operated only after proper accomplishment of the prescribed actions. In the interest of aviation safety outweighing the interest of the receiver in a postponement of the prescribed actions, the immediate compliance with this AD is to be directed

Instructions about Available Legal Remedies:

An appeal to this notice may be raised within a period of one month following notification. Appeals must be submitted in writing or registered at the Luftfahrt-Bundesamt,

Hermann-Blenk-Str. 26, 38108 Braunschweig.

Enquiries regarding this Airworthiness Directive should be referred to Mr. Olaf Schneider, Airworthiness Directive Section at the above address, fax-no. 0049 531/2355-720. Please note, that in case of any difficulty, reference should be made to the German issue.

LTA's / AD's and Technical Notes are published on the internet at <http://www.lba.de>