

# PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

**CAA-AD-1-011/98**

Datum vydání: 2.března 1998

## LETADLO - INSTALACE BEZPEČNOSTNÍHO KRYTU PŘEDNÍHO UPÍNACÍHO PÁSU

**Týká se:** letadel typu Extra EA 300/200 od výrobního čísla 01 až do v. č. 15.

**Důvod vydání:** v provozu letadla došlo k zaklínění předního upínacího pásu do pedálů směrového řízení.

**Datum účinnosti:** 26. února 1998

**Provést:** před následujícím letem po datu účinnosti tohoto PZZ.

**Postup provedených prací:** proveďte podle postupu popsaném v Extra EA-300 Service Bulletinu č. 300-1-97/ B vydaném dne 11. června 1997 modifikací předního upínacího pásu. Tento SB je možno obdržet od výrobce na adrese: Extra Flugzeugbau, Flugplatz Dinslaken, D-46569 Hünxe, FRG, fax. +49 (0) 2858 913730

*Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát. Pokud to vyžaduje povaha tohoto PZZ musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě LBA AD 97-203/2, který je přílohou tohoto PZZ.*

**Ing. Pavel MATOUŠEK**

**Ředitel technického inspektorátu**

**Úřad pro civilní letectví**

**Airworthiness Directive 1997-203/2 Extra Flugzeugbau**

Luftfahrt-Bundesamt, Airworthiness Directive Section, Lilienthalplatz 6, 38108 Braunschweig, Federal Republic of Germany

**Effective Date: February 26, 1998**

**Affected:**

Kind of aeronautical product: Aircraft

Manufacturer: Extra, Hünxe, Germany

Type: Extra EA 300

Models affected: Extra EA 300/200

Serial numbers affected: 01 up to and including 15

German Type Certificate No.: 1086

**Subject:** Front seat belt safety cover installation.

**Reason:** A rudder pedal lock due to interference with the front seat belt harness has been reported.

**Action:** Install a front seat belt cover.

Note: If the belt cover was installed in accordance with AD-No. 97-203, check the installation procedure in accordance with Issue B of the Service Bulletin and if all in the new SB listed parts ("List of used Parts") were installed.

**Compliance:** Action must be performed before the next flight.

**Technical publication of the manufacturer:**

Extra EA-300 Service Bulletin No. 300-1-97 Issue B dated June 11,1997 which becomes herewith part of this AD and must be obtained from Messrs.: Extra Flugzeugbau, Flugplatz Dinslaken, D-46569 Hünxe, Federal Republik of Germany, Fax: +49 (0) 2858 913730

**Accomplishment and log book entry:**

Action to be accomplished by an approved service station and to be checked and entered in the log book by a licensed inspector.

**Note:** This AD supersedes the AD-No.1997-203 dated July 03, 1997.

Enquiries regarding this Airworthiness Directive should be referred to Mr. Olaf Schneider, Airworthiness Directive Section at the above address, fax-no. 0049 531/2355-254. Please note, that in case of any difficulty, reference should be made to the German issue!