



ÚŘAD PRO CIVILNÍ LETECTVÍ
ČESKÁ REPUBLIKA
Sekce technická
letišťe Ruzyně, 160 08 Praha 6
tel: 233320922, fax: 220562270

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

Číslo: 2008-0174

Datum účinnosti: 17. září 2008

SPEKON Sächsische Spezialkonfektionen GmbH
RE-5L záchranné padáky


Tento PZZ je vydáván pro výrobek transferovaný pod působnost EASA

Na základě rozhodnutí EASA je následující Příkaz k zachování letové způsobilosti závazný pro všechny výrobky provozované v EU, na které se daný PZZ vztahuje.

Provedení PZZ, který se vztahuje podle typu a výrobního čísla na výrobek je pro provozovatele/vlastníka letadla zapsaného do leteckého rejstříku závazné. Neprovedením PZZ ve stanoveném termínu dojde ke ztrátě letové způsobilosti výrobku.

Poznámky:

- Provedení tohoto PZZ musí být zapsáno do provozní dokumentace letadla.
- Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická.
- Pokud to vyžaduje povaha tohoto PZZ, musí být zpracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla.

EASA	AIRWORTHINESS DIRECTIVE
	<p>AD No.: 2008-0174</p> <p>Date: 15 September 2008</p> <p>Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>
<p>This AD is issued in accordance with EC 1702/2003, Part 21A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].</p>	
<p>Type Approval Holder's Name :</p> <p>SPEKON Sächsische Spezialkonfektionen GmbH</p>	<p>Type/Model designation(s) :</p> <p>RE-5L Emergency Parachutes</p>
<p>JTSO approval : LBA.040.010/89 JTSO</p>	
<p>Foreign AD : Not applicable</p>	
<p>Supersedure : None</p>	
<p>ATA 25 Emergency Parachute - Replacement of the Drogue Parachute.</p>	
<p>Manufacturer(s): SPEKON Sächsische Spezialkonfektionen GmbH</p>	
<p>Applicability: RE-5L Emergency Parachutes series 4 and 5 from serial number (s/n) 72245 up to 72369 inclusive and s/n 72371.</p> <p>NOTE: These parachutes have been manufactured between 21 April 2008 and 21 August 2008.</p>	
<p>Reason: One case of cracked grommet has been found on the pilot chute of a RE-5L parachute. An internal process review has revealed that drogue parachutes installed in RE-5L Emergency Parachutes series 4 and 5 as listed in the applicability of this AD, may present some crack initiations.</p> <p>This condition if left uncorrected could create an obstruction of the closing loop and prevent the main parachute from being pulled out of its storage pack.</p> <p>For the reason described above, this AD mandates the replacement of the identified drogue parachutes.</p>	
<p>Effective Date: 17 September 2008</p>	

<p>Required Action(s) and Compliance Time(s):</p>	<p>Required as indicated, unless accomplished previously:</p> <p>(1) Within 15 days after the effective date of this AD, replace the drogue parachute by a serviceable one as instructed in the SPEKON Safety Bulletin No. 01/2008 Issue 2.</p> <p>(2) After the effective date of this AD, no person shall install drogue parachutes removed per the requirements of paragraph (1) of this AD on any parachutes.</p> <p>To that end, conform to the applicable procedures about the control of unserviceable components.</p>
<p>Ref. Publications:</p>	<p>SPEKON Sicherheitsmitteilung (Safety Bulletin) No. 01/2008 Issue 2</p> <p>The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.</p>
<p>Remarks :</p>	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD. 2. The required actions and the risk allowance have granted the issuance of a Final AD with Request for Comments, postponing the public consultation process after publication. 3. Enquiries regarding this AD should be referred to the Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA. E-mail ADs@easa.europa.eu 4. For any questions concerning the technical content of the requirements in this AD, please contact: <p style="text-align: center;">SPEKON Sächsische Spezialkonfektionen GmbH Nordstraße 40 - 02782 Seifhennersdorf – Germany Phone: +49 (0)3586 456-0 Fax:+49 (0)3586 456 167 E-mail: info@spekon.com</p>