

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

Číslo: CAA-AD-4-068/98

Datum vydání: 01. října 1998

LETADLO - HASICÍ PŘÍSTROJ - KONTROLA

Týká se: letadel SAAB SF340A výrobních čísel -121, -125 až -159 a SAAB 340B výrobních čísel -160 až -360.

Datum účinnosti: 03. prosince 1998

Provést v termínech: jak je popsáno v části "Compliance time" SAD č. 1-106R1 (příloha tohoto PZZ).

Postup provedených prací: dle části "Actions" SAD č. 1-106R1.

Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát - Ing. Stibůrek. Pokud to vyžaduje povaha tohoto PZZ musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě SAD č. 1-106R1.

Ing. Pavel MATOUŠEK
Ředitel technického inspektorátu
Úřad pro civilní letectví

LUFTFARTSVERKET Aviation Safety Department

SWEDISH Airworthiness DIRECTIVES (SAD) **SAD No 1-106R1** Cancels SAD No 1-106

Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS DIRECTIVE NO: 1-106R1

AIRCRAFT TYPE: SAAB SF 340A and SAAB 340B

SERIAL No's: SAAB SF 340A -121, -125 through -159

AFFECTED: SAAB 340B -160 through -360

All aircraft with a fire extinguisher installed in the forward Lavatory Pt. No.55-373 (with external service).

SUBJECT: Equipment/Furnishing - Waste Bin Fire Extinguisher Located in the Forward Lavatory - Inspection and Changed Procedure to Remove and Install it

BACKGROUND: On periodic checks of the forward lavatory waste bin fire - extinguisher the capillary tube has been fractured/bent in the yellow area during maintenance.

This has caused the capillary tube to leak at the head and discharge the contents of the fire extinguisher.

REFERENCE DOCUMENTS: Saab Aircraft AB Service Bulletin SAAB 340-25-235

ACTIONS: Perform actions described in Saab Aircraft AB Service Bulletin SAAB 340-25-235 dated 11 December,1996 or later revision.

COMPLIANCE TIME: To be performed within 3 months after effective date of this SAD

EFFECTIVE DATE: 12 December,1996

(Issued 8 September,1998 to clarify original SAD 1-106)