

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

CAA-AD-4-069/98

Datum vydání: 01. října 1998

LETADLO - NOUZOVÝ VÝCHOD

Týká se: letadel A310 všech typů a výrobních čísel.

Datum účinnosti: 03. prosince 1998

Provést v termínech: Jak je popsáno v části "Action" DGAC AD č. 98-340-254(B) (příloha tohoto PZZ).

Postup provedených prací: Dle části "Action" DGAC AD č. 98-340-254(B).

Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát - Ing.Toman. Pokud to vyžaduje povaha tohoto PZZ musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě DGAC AD č. 98-340-254(B).

Ing. Pavel MATOUŠEK
Ředitel technického inspektorátu
Úřad pro civilní letectví

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this

Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 98-340-254(B)

In case of any difficulty, reference should be made to the French original issue.

AIRBUS INDUSTRIE

A310 Aircraft

Emergency exits-

Replacement of the bearings of the emergency exit opening mechanism (ATA 52)

APPLICABILITY :

AIRBUS INDUSTRIE A310 aircraft, all certified models and all serial numbers, on which :

- neither AIRBUS INDUSTRIE modification No 11680 in production,
- nor AIRBUS INDUSTRIE Service Bulletin A310-52-2061 Revision 1, have been embodied.

REASON :

Some cases of seizure of the bearings of the emergency exit opening mechanism were noticed, which therefore require an excessive force to obtain the opening of the associated door and could lead to critical situations, should an emergency evacuation of the aircraft be necessary.

ACTION :

Before October 31,1999, replace the bearings of the emergency exit opening mechanism, in accordance with the instructions of AIRBUS INDUSTRIE Service Bulletin A310-52-2061 Rev.1.

REF. : AIRBUS INDUSTRIE Service Bulletin A310-52-2061 Rev.1

(or any other later approved revision).

EFFECTIVE DATE :

SEPTEMBER 05, 1998