



CIVIL AVIATION AUTHORITY  
CZECH REPUBLIC  
Airworthiness Division

Airport Ruzyne, 160 08 Prague 6  
Tel: 420 233320922, fax: 420 220562270

## AIRWORTHINESS DIRECTIVE

**Number: CAA-AD-098/2002**

Date of issue: October 24, 2002

**MORAVAN-AEROPLANES a.s.**  
Z 242L

---

### AIRCRAFT – AIRCRAFT OIL SYSTEM – INSPECTION/CORRECTION

---

**Applicability:** All Z 242L aircraft produced by MORAVAN-AEROPLANES a.s. certificated in any category.

**Reason:** Possibility of loosening of adhesive joint of tube in “Tee” assembly and in “Elbow” assembly in aircraft oil system. Loose tube can obstruct oil flow in the engine, which can lead to stoppage of the engine.

**Effective date:** November 28, 2002.

**Compliance:**

Perform inspection of above mentioned adhesive joints and in case of loosening of adhesive joint perform bonding of this joint, execute regular annual inspections of mentioned adhesive joints in accordance with Mandatory Bulletin No.: Z 242L/42a (can be obtained from MORAVAN-AEROPLANES a.s., Obchodně technické služby, 765 81 Otrokovice, Czech Republic). Perform change in the Maintenance Manual of the Z 242 L Aircraft (Doc. No. 003.021.1-Czech version, Doc. No. 003.022.1-English version).

---

*Remarks: The compliance of this AD must be recorded in Aircraft Logbook, where applicable the requirements of this AD must be integrated into Aircraft Technical Documentation. Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyne Airport, 160 08 Prague 6, Czech Republic, tel: 420 233320922, fax: 420 220562270.*

**Ing. Pavel MATOUŠEK**  
director