



CIVIL AVIATION AUTHORITY  
CZECH REPUBLIC

*Airport Ruzyne, 160 08 Prague 6  
tel: 420 02/324086, fax: 420 02/364112*

---

## AIRWORTHINESS DIRECTIVE

**Number: CAA-T -AD-1-024/98**

Date of issue: March 23, 1998

**LET Kunovice Inc.**  
L 33 SOLO

---

### SAILPLANE - WING MAIN HINGES - REPLACEMENT

---

**Applicable:** L 33 SOLO, S/N: 930101-930205; 940206-940308; 940310-940316; 950318-950401;  
960402-940404; 950405-950406; 960407-960408; 960410.

**Reason for issuance:**

Fatigue of wing attachment discovered by fatigue testing

**Effective date:** May 1, 1998

**Apply until:**

After AD receipt, not later than 1 500 hours TIS (time in service)

**Accomplishment Procedure:**

L-33 SOLO sailplane operators shall replace main wing attachment and wing spar root pins according to the Mandatory Bulletin L-33/008a .

---

**Remarks:**

- Where applicable, the requirements of this AD must be integrated into the aircraft's log
- Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyne Airport, 160 08 Prague 6, Czech Republic, tel: 420 2 324086, fax: 420 2 364112
- Operators of affected sailplanes obtain copies of mandatory service bulletin No. L-33/008a directly from manufacturer. Contact address: LET Inc., 686 04 Kunovice, CZECH REPUBLIC

**Ing. Pavel MATOUŠEK**  
**Director of Airworthiness Division**  
**CAA CZ**