

airport Ruzyne, 160 08 Prague 6 tel: 420 02/324086, fax: 420 02/364112

AIRWORTHINESS DIRECTIVE

Number: CAA - AD-2- 029/97

Date of issue: May 29, 1997

MORAVAN Inc. ZLIN 2421

AIRCRAFT - the sludge valve of the oil system - check for proper locking

Applicable:

All Zlín 242L aircraft up to S/N 0708 and S/N 0727 and 0728 with the sludge valve of the oil system Drwg. No. L 242L.7100-04.00 installed.

Reason for issuance:

Manufacturer found out that the sludge valve of the oil system Drwg. No. L 242L.7100-04.00 installed on the forementioned aircraft may cause the oil leakage from the engine.

Effective date: June 5, 1997

Apply until:

Prior next flight after effective date of this AD.

Accomplishment Procedure:

Perform proper locking of the nut in assembly of the lifter and the valve sealing disc in accordance with Mandatory Service Bulletin No. Z 242L/25a.

Remarks:

- Where applicable, the requirements of this AD must be integrated into the aircraft log book
- Address inquiries this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyne Airport, 160 08 Prague 6, Czech Republic, tel: 420 2 324086, fax: 420 2 364112
- -Operators of affected aircraft obtain copies of mandatory service bulletin No. Z 242L/25a directly from manufacturer. Contact address: MORAVAN, Inc., 765 81 Otrokovice, CZECH REPUBLIC

Ing. Pavel MATOUŠEK
Director of Airworthiness Division
Civil Aviation Authority