

## CIVIL AVIATION AUTHORITY CZECH REPUBLIC

### **Airworthiness Division**

Airport Ruzyne, 160 08 Prague 6 Tel: 420 233320922, fax: 420 220562270

# AIRWORTHINESS DIRECTIVE

**Number: CAA-AD-T-070/2003R1** 

Supersedes CAA-AD-T-070/2003

Date of issue: August 25, 2003

Schempp-Hirth výroba letadel spol. s r.o.

Duo Discus C

### SAILPLANE - WING - INSPECTION/REPAIR

**Applicability:** for Duo Discus C sailplanes, all serial numbers produced by Schempp-Hirth výroba letadel spol. s r.o. Company.

**Reason:** defects in the bonding of the spar cap and the shear web have been identified, which could lead to destruction of the wing and lost of the airplane control.

Effective date: Upon receipt

### **Compliance:**

Before the next flight perform for renewal of airworthiness above mentioned sailplanes inspection of the bonding of the spar cap and the shear web and subsequent works in accordance with Mandatory Bulletin No.: DDC/2a., which can be obtained from: Schempp-Hirth výroba letadel spol. s r.o., P.O.BOX 19, 565 01 Choceň, Czech Republic.

Remarks: The compliance of this AD must be recorded in Sailplane Logbook, where applicable the requirements of this AD must be integrated into Aircraft Technical Documentation. Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyne Airport, 160 08 Prague 6, Czech Republic, tel: 420 233320922, fax: 420 220562270.

Ing. Pavel MATOUŠEK director