

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

CAA-AD-T-113/2001

Datum vydání: 11. prosince 2001

LETADLOVÉ ZAŘÍZENÍ - SEDADLA CESTUJÍCÍCH - KONTROLA

Týká se: sedadel cestujících Skyluxe II (AA2) vyrobených firmou B/E Aerospace (UK), která mohou být zabudována v letadlech - Airbus A300, A300-600, A320, A321, A330 a A340, Boeing 737-800, Boeing 747-200, -300 a -400, Boeing 767-200 a -300, Boeing 777-200 a -300 a McDonnell Douglas MD-11.

Datum účinnosti: ihned po obdržení

Provést v termínech: Jak je popsáno v UK AD 002-11-2001, od data účinnosti tohoto PZZ.

Postup provedení prací: Dle UK AD 002-11-2001 (příloha tohoto PZZ).

Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická - Ing. Toman. Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě UK AD 002-11-2001.

Ing. Pavel MATOUŠEK
Ředitel sekce technické
Úřad pro civilní letectví

CAA Airworthiness Directive 002-11-2001

Applicability

B/E Aerospace (UK) Skyluxe II (AA2) Passenger Seats. Known to be fitted in Airbus A300, A300-600, A320, A321, A330 and A340 Series aircraft, Boeing 737-800 Series aircraft, Boeing 747-200, -300 a -400 Series aircraft, Boeing 767-200 a -300 Series aircraft, Boeing 777-200 and -300 Series aircraft and McDonnell Douglas MD-11 Series aircraft.

Subject - Description

Hydrolok pin orientation.

Compliance - Requirement (Summary)

Compliance is required with B/E Aerospace Alert Service Bulletin 25-20-2658 not later than one month from receipt of the bulletin. The Alert Service Bulletin requires inspection and re-orientation of the Hydrolok retaining pin. This action is required because under certain conditions the Hydrolok pin can migrate and disconnect from the seat structure, resulting in the seat back having no rearward restraint and allowing it to rotate aft into the seat or exit pathway behind.

Reference must be made to the Alert Service Bulletin for full details. A copy of the ASB can be obtained from B/E Aerospace (UK) Ltd, Seating Aftermarket Operations, Leighton Buzzard, Bedfordshire, LU7 8TB, United Kingdom.