



ÚŘAD PRO CIVILNÍ LETECTVÍ
ČESKÁ REPUBLIKA
Sekce technická
letišťe Ruzyně, 160 08 Praha 6
tel: 233320922, fax: 220562270

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

Číslo: 2006- 0220

Datum účinnosti: 31. července 2006

Recaro Aircraft Seating GmbH & Co. KG

Sedačky pro cestující typ 3410, 3510 (A,B,C,D), 4400, 4420, 6510

instalované v letadlech:

A318-100, A319-100, A320-200, A321-200,

A330-200, A330-300, A340-200, A340-300,

A340-600,

B737-300, B737-400, B737-500, B737-700, B737-800,

B737-900, B747-300, B747-400, B767-300, B777-200,

B777-300.

Tento PZZ je vydáván pro výrobek transferovaný pod působnost EASA

Na základě rozhodnutí EASA je následující Příkaz k zachování letové způsobilosti závazný pro všechny výrobky provozované v EU na které se daný PZZ vztahuje.


Provedení PZZ, který se vztahuje podle typu a výrobního čísla na výrobek je pro provozovatele/vlastníka letadla zapsaného do leteckého rejstříku závazné. Neprovedením PZZ ve stanoveném termínu dojde ke ztrátě letové způsobilosti výrobku.

Poznámky:

- Provedení tohoto PZZ musí být zapsáno do provozní dokumentace letadla.

- Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická.

- Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla.

EASA	AIRWORTHINESS DIRECTIVE	
	<p style="text-align: center;">AD No.: 2006 - 0220</p> <p style="text-align: center;">Date: 19 July 2006</p>	
<p>No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry.</p>		
<p>Type Approval Holder's Name :</p> <p>Recaro Aircraft Seating GmbH & Co. KG</p>	<p>Type/Model designation(s) :</p> <p>3410, 3510(A,B,C,D), 4400, 4420, 6510</p>	
<p>ETSO Number : LBA: 30.131/26, EASA.21O.0153, EASA.21O.0172, EASA.21O.249, EASA.21O.306, LBA: 30.131/118 JTSS, LBA.O.11.111/3 JTSS, LBA.O.11.111/2 JTSS</p>		
<p>Foreign AD : None</p>		
<p>Supersedure : None</p>		
ATA 25	Equipment – Passenger Seats - Inspection of Seatbelt Shackle	
<p>Manufacturer:</p>	<p>Recaro Aircraft Seating GmbH & Co. KG</p>	
<p>Applicability:</p>	<p>Passenger Seats Type 3410, 3510 (A,B,C,D), 4400, 4420 and 6510 delivered after 1st November 2005 and before 5th May 2006.</p> <p>This equipment is known to be installed on but not limited to the following aircraft: A318-100, A319-100, A320-200, A321-200, A330-200, A330-300, A340-200, A340-300, A340-600, B737-300, B737-400, B737-500, B737-700, B737-800, B737-900, B747-300, B747-400, B767-300, B777-200, B777-300</p>	
<p>Reason:</p>	<p>During incoming inspection an improperly riveted seat belt shackle has been determined. This could lead to a malfunction of the seat belt attachment. The cause could be tracked down to an improper process at the shackle supplier ANCRA. The existence of similar occurrences can not be excluded.</p>	
<p>Effective Date:</p>	<p>31 July 2006</p>	
<p>Compliance:</p>	<p>The following measures are rendered mandatory from the effective date of this AD:</p> <p>Unless already accomplished,</p> <ul style="list-style-type: none"> - perform a one time detailed visual inspection of the seat shackles of the related seats within the next 8 weeks following the effective date of this AD. - if necessary apply the associated corrective actions. 	

	<p>The inspection results, if defects are found, must be reported to Recaro</p> <p>The occurrence of similar cases on seats from other manufacturers must be reported to the Agency.</p>
Ref. Publications:	<p>Recaro Service Bulletin:</p> <p>3410-25BQ555, Original Issue, dated 19 May 2006</p> <p>3510-25BQ073, Original Issue, dated 18 May 2006</p> <p>4400-25BQ046, Original Issue, dated 19 May 2006</p> <p>4420-25BQ128, Original Issue, dated 19 May 2006</p> <p>6510-25BQ115, Original Issue, dated 19 May 2006</p> <p>or later approved revisions.</p>
Remarks :	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated the responsible EASA manager for the related product has the authority to accept Alternative Methods of Compliance (AMOCs) for this AD. 2. This AD was posted as PAD 06-138, -139, -140, -141 and -142 for consultation on 02 June 2006 with a comment period until 16 June 2006. The Comment Response Document can be found at http://ad.easa.eu.int/ . 3. Enquiries regarding this Airworthiness Directive should be referred to Mr. M. Capaccio, Airworthiness Directive Focal Point - Certification Directorate, EASA. E-mail: ADs@easa.europa.eu . 4. For any question concerning the technical content of the requirements in this AD, please contact Recaro Aircraft Seating GmbH & Co, Technical Publications, Daimlerstrasse 21, 74523 Schwaebisch Hall, Germany, phone +49 791 5037185, fax: +49 791 5037211.