



ÚŘAD PRO CIVILNÍ LETECTVÍ
ČESKÁ REPUBLIKA
Sekce technická
letišťe Ruzyně, 160 08 Praha 6
tel: 233320922, fax: 220562270

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

Číslo: 2006-0065

Datum účinnosti: 6. dubna 2006

Robinson Helicopter Company
model R 22


Tento PZZ je vydáván pro výrobek transferovaný pod působnost EASA

Na základě rozhodnutí EASA je následující Příkaz k zachování letové způsobilosti závazný pro všechny výrobky provozované v EU na které se daný PZZ vztahuje.

Provedení PZZ, který se vztahuje podle typu a výrobního čísla na výrobek je pro provozovatele/vlastníka letadla zapsaného do leteckého rejstříku závazné. Neprovedením PZZ ve stanoveném termínu dojde ke ztrátě letové způsobilosti výrobku.

Poznámky:

- Provedení tohoto PZZ musí být zapsáno do provozní dokumentace letadla.
- Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická.
- Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla.

EASA	AIRWORTHINESS DIRECTIVE	
	AD No.: 2006-0065 Date: 23 March 2006	
No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry.		
Type Approval Holder's Name:		Type/Model designation(s):
Robinson Helicopter Company		R22
TCDS Number: FAA H10WE Rev. 12		
Foreign AD: None		
Supersedure: None		
ATA 32	Landing Gear – Skids – Modification	
Manufacturer(s):	Robinson Helicopter Company	
Applicability:	All Robinson R22 Helicopters	
Reason:	For helicopters with original shorter skid configuration, handling is considered to be excessively demanding for autorotative landings on to surfaces other than paved surfaces.	
Effective Date:	06 April 2006.	
Compliance:	Required within the next 1000 hours time-in-service (TIS) or within 2 years after the effective date of this AD, whichever occurs soonest Install landing skid extensions, part numbers A937-1 and A937-2, and improved landing skid shoes A667-5 (4 per helicopter) and A667-6 (2 per helicopter).	
Ref. Publications:	None	
Remarks:	1. If requested and appropriately substantiated the responsible EASA manager for the related product has the authority to accept Alternative Methods of Compliance (AMOCs) for this AD. 2. This AD was posted as PAD 06-030 for consultation on 13 February 2006 with a comment period until 14 March 2006. No comment was raised during the consultation period.	

- | | |
|--|--|
| | <ol style="list-style-type: none">3. Enquiries regarding this Airworthiness Directive should be referred to Mr. M. Capaccio, Airworthiness Directive Focal Point - Certification Directorate, EASA.
E-mail: ADs@easa.eu.int4. For questions concerning the technical contents of this AD requirements, contact Robinson Helicopter Company (Ph.: +1 (310) 539 0508; Fax +1 (310) 539 5198). |
|--|--|