



CIVIL AVIATION AUTHORITY  
CZECH REPUBLIC

*Airport Ruzyně, 160 08 Prague 6*  
*tel: 420-2-33320922, fax: 420-2-20562270*

## AIRWORTHINESS DIRECTIVE

**Number: CAA-AD-042/1999**

Supersedes: CAA-AD-2-012/96

CAA-AD-2-012R1/96

Date of issue: August 18, 1999

**MORAVAN-AEROPLANES Inc.**

Z 242L, Z 143L

---

### AIRCRAFT - ENGINE VENT LINE - MODIFICATION

---

- Applicability:** All Zlin 242L aircraft produced by Moravan-Aeroplanes Inc. Up to S/N 0730 incl., all Zlin 143L aircraft up to S/N 0029 incl., except S/N 0025 and 0027, certified in any category.
- Reason:** The following measures are rendered mandatory in order to prevent the oil leakage from the engine during cold weather operation (winter operation).
- Effective date:** October 7, 1999
- Compliance :** Engine vent adaptation of the Z 242L, Z 143L aircraft and corresponding revision of the Maintenance Manual of the Z 242L aircraft - Vol. I. in accordance with Mandatory Service Bulletin Z 242L/19a - Rev.3, Z 143L/20a at the next 100-hour inspection or at annual inspection, not later than at preparation for winter operation. Corresponding revision of the Flight Manual issued by the Mandatory Service Bulletin Z 242L/19a - Rev.2 remains effective.

---

*Remarks: - Where applicable, the requirements of this AD must be integrated into the Aircraft's Logbook(s).*  
*- Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyně Airport, 160 08 Prague 6, Czech Republic, tel: 420 2 33320922, fax: 420 2 20562270.*  
*- Contact address for order Mandatory Service Bulletin: MORAVAN-AEROPLANES Inc. ZLIN Service, 765 81 OTROKOVICE, Czech Republic.*

**Ing. Pavel MATOUŠEK**  
**Director of Airworthiness Division**  
**CAA CZ**