



ÚŘAD PRO CIVILNÍ LETECTVÍ
ČESKÁ REPUBLIKA
Sekce technická
letišťe Ruzyně, 160 08 Praha 6
tel: 233320922, fax: 220562270

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

Číslo: 2008-0186-E
Nahrazuje LBA LTA-Nr.D-2008-330
Datum účinnosti: 13. října 2008

STEMME GmbH & Co. KG
S10 a S10-V


Tento PZZ je vydáván pro výrobek transferovaný pod působnost EASA

Na základě rozhodnutí EASA je následující Příkaz k zachování letové způsobilosti závazný pro všechny výrobky provozované v EU, na které se daný PZZ vztahuje.

Provedení PZZ, který se vztahuje podle typu a výrobního čísla na výrobek je pro provozovatele/vlastníka letadla zapsaného do leteckého rejstříku závazné. Neprovedením PZZ ve stanoveném termínu dojde ke ztrátě letové způsobilosti výrobku.

Poznámky:

- Provedení tohoto PZZ musí být zapsáno do provozní dokumentace letadla.
- Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická.
- Pokud to vyžaduje povaha tohoto PZZ, musí být zpracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla.

EASA	EMERGENCY AIRWORTHINESS DIRECTIVE	
	<p>AD No.: 2008-0186-E</p> <p>Date: 09 October 2008</p> <p>Note: This Emergency Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation</p>	
<p>This AD is issued in accordance with EC 1702/2003, Part 21A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].</p>		
Type Approval Holder's Name :		Type/Model designation(s) :
STEMME GmbH & Co. KG		S10 and S10-V sailplanes
TCDS Number :	EASA.A.054	
Foreign AD :	Not applicable	
Supersedure :	This directive supersedes LBA LTA-Nr.D-2008-330	
ATA 73	Engine Fuel & Control - Pressed Fuel Lines - Inspection/Replacement	
Manufacturer(s):	STEMME GmbH & Co. KG, STEMME AG.	
Applicability:	Model S10 and S10-V powered-sailplanes, with serial numbers 10-32, 10-53, 14-025 and 14-027.	
Reason:	<p>Investigations performed following a report about a fuel leakage in a Stemme S10-V powered-sailplane revealed that some fuel lines fabricated between March 2008 and May 2008, after the introduction of a new pressing tool, present a manufacturing defect which could lead to the puncture of the fuel lines.</p> <p>For the reason stated above, this Airworthiness Directive (AD) mandates, as an initial phase, repetitive inspections of the fuel lines until their replacement, by new ones which conform to the approved original specifications, is implemented as a final fix.</p>	
Effective Date:	13 October 2008	
Required Action(s) and Compliance Time(s):	<p>Required as indicated, unless accomplished previously:</p> <p>(1) Before every flight after the effective date of this AD and until accomplishment of paragraph (2) of this AD, check the fuel lines as instructed in the STEMME Service Bulletin (SB) No. A31-10-084.</p> <p style="text-align: center;">If any damage is found, before further flight replace all the fuel lines as instructed in the STEMME SB No. A31-10-084</p> <p>(2) Within 25 days after the effective date of this AD, replace all the fuel lines in accordance with the STEMME SB No. A31-10-084.</p>	

Ref. Publications:	STEMME Service Bulletin No. A31-10-084 initial issue. The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.
Remarks :	<ol style="list-style-type: none">1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.2. The safety assessment has requested not to implement the full consultation process and an immediate publication and notification.3. Enquiries regarding this AD should be referred to the Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA. E-mail: ADs@easa.europa.eu.4. For any questions concerning the technical content of the requirements in this AD, please contact: <p style="text-align: center;">STEMME GmbH & Co. KG Flugplatzstraße F 2, Nr. 7 - 15344 Strausberg Federal Republic of Germany Phone: + 49-33-41-3612-0 Fax: + 49-33- 41-3612-30 E-Mail: P.Ellwanger@stemme.de</p>