



CIVIL AVIATION AUTHORITY
CZECH REPUBLIC
Airworthiness Division

*Airport Ruzyně, 160 08 Prague 6
Tel: 420 233320922, fax: 420 220562270*

AIRWORTHINESS DIRECTIVE

Number: CAA-AD-027/2004

Date of issue: March 29, 2004

**BOEING
737-200**

AIRCRAFT - INFLIGHT ENTERTAINMENT - REMOVAL

Applicability: Model 737-200 series airplanes modified by Supplemental Type Certificate (STC) ST00516AT, certificated in any category.

Effective date: May 13, 2004

Compliance: Required as indicated FAA AD 2004-05-27.

Remarks: The compliance of this AD must be recorded in Aircraft Logbook, where applicable the requirements of this AD must be integrated into Aircraft Technical Documentation. Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyně Airport, 160 08 Prague 6, Czech Republic, tel.: 420 2 33320922, fax: 420 2 20562270.

Ing. Pavel MATOUŠEK
Director

2004-05-27 Boeing: Amendment 39-13522. Docket 2002-NM-238-AD.

Applicability: Model 737-200 series airplanes modified by Supplemental Type Certificate (STC) ST00516AT, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To eliminate the possibility that the airplane crew could be unable to remove power from the in-flight entertainment (IFE) system during a non-normal or emergency situation, which could result in the airplane crew's inability to control smoke or fumes in the airplane flight deck or cabin, accomplish the following:

Removal of IFE System

(a) Within 18 months after the effective date of this AD, remove the IFE system installed by STC ST00516AT per the procedure in Kosola and Associates Service Bulletin 2002-1, dated July 16, 2003. The procedure includes disconnecting the power line that leads from the IFE system control unit to the P6 panel, capping and stowing all related wiring or removing related wiring from the airplane, removing the IFE system circuit breaker from the P6 panel, and removing all components of the IFE system from the airplane.

Inspections Accomplished per Previous Issue of Service Bulletin

(b) Removal of the IFE system installed by STC ST00516AT before the effective date of this AD per Kosola and Associates Service Bulletin 2002-1, dated June 5, 2002, is considered acceptable for compliance with paragraph (a) of this AD.

Parts Installation

(c) As of the effective date of this AD, no person may install an IFE system approved by STC ST00516AT on any airplane.

Alternative Methods of Compliance

(d) In accordance with 14 CFR 39.19, the Manager, Atlanta Aircraft Certification Office (ACO), FAA, is authorized to approve alternative methods of compliance (AMOCs) for this AD.

Incorporation by Reference

(e) Unless otherwise specified by this AD, the actions shall be done in accordance with Kosola and Associates Service Bulletin 2002- 1, dated July 16, 2003. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Kosola and Associates, Inc., 5601 Newton Road, P.O. Box 3529, Albany, Georgia 31706. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(f) This amendment becomes effective on April 19, 2004.

Footer Information

Issued in Renton, Washington, on March 2, 2004.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. 04-5432 Filed 3-12-04; 8:45 am]

BILLING CODE 4910-13-P