



ÚŘAD PRO CIVILNÍ LETECTVÍ  
ČESKÁ REPUBLIKA  
Sekce technická

letišťe Ruzyně, 160 08 Praha 6  
tel: 233320922, fax: 220562270

## PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

Číslo: CAA-AD-T-046/2004

Datum vydání: 26. května 2004

PZL KANIA

### VRTULNÍK – ŠROUBY V SESTAVĚ LISTU VYROVNÁVACÍHO ROTORU – KONTROLA/VÝMĚNA

---

**Týká se:** vrtulníků PZL Kania všech výrobních čísel, vyrobených firmou PZL-SWIDNIK S.A.

**Důvod vydání:** předejít poškození šroubů 50.39.100.25.03 v sestavě listu vyrovnávacího rotoru vrtulníku.

**Datum účinnosti:** Ihned po obdržení.

**Provést v termínech:**

Jak je popsáno v GILC AD SP-0039-2004-A, od data účinnosti tohoto PZZ.

**Postup provedení prací:**

Dle GILC AD SP-0039-2004-A (příloha tohoto PZZ).

---

*Poznámky:*

- Provedení tohoto PZZ musí být zapsáno do letadlové knihy.
- Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická - Ing. Shrbený.
- Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla.
- Tento PZZ byl vypracován na základě GILC AD SP-0039-2004-A.

**Ing. Pavel MATOUŠEK**  
ředitel

**REPUBLIC OF POLAND CIVIL AVIATION OFFICE**

ul. Zelazna 9, 00-848 Warszawa, tel. (4822) 5207 374, fax (4822) 5207 373  
Warsaw, 17.05.2004. day/month/year

**AIRWORTHINESS DIRECTIVE**

**Nr SP-0039-2004-A**

**1. Product:** All Series PZL Kania Helicopters.

**2. Type: Certificate/Approval Number:** GILC / GICA, BC-147

**3. Subject:** Check of melt number and replacement of bolts 50.39.100.25.03 securing pitch links in tail rotor feathering hinges.

**4. Reason for the issuance Of this AD:** During repairs of Mi-2 helicopter tail rotors, bolts 50.39.100.25.03 securing the pitch link in the rotor feathering hinge casing were found to be fractured. The detected damages occurred on the bolts made of the material melt lot No. 65816A, and were located on the cylindrical section of bolt in place where it mates with the pitch link.

**5. Corrective action:** As in Mandatory Bulletin No. BO-90-04-33.

**6. Name Of Aviation Authority that issued AD:** -----

**7. Ref. Publications:** Mandatory Bulletin No. BO-90-04-33.

**Effectivity date of this AD: Immediately after receiving.**