

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

CAA-AD-110/2000

Datum vydání: 8. prosince 2000

LETOUN - BRZDY - LETOVÁ PŘÍRUČKA (ATA 04, 32) - DOPLNĚNÍ

Týká se: letadel A300, A310, A300-600 vyrobených firmou AIRBUS INDUSTRIE, všech verzí a výrobních čísel vybavených uhlíkovými brzdami MESSIER, mimo těch vybavených uhlíkovými brzdami MESSIER MB M318 (sestava osmi brzd na letadle).

Letadel na kterých byla provedena ve výrobě AIRBUS INDUSTRIE modifikace No.: 10848 nebo 10849 (AIRBUS INDUSTRIE Service Bulletin (SB) A300-32-0410 nebo A310-32-2082 nebo A310-32-2084 nebo A300-32-6050 v provozu) se požadavky tohoto PZZ netýkají.

Datum účinnosti: 25. ledna 2001

Provést v termínech: Jak je popsáno v DGAC AD 1992-156-133(B) R1 (příloha tohoto PZZ).

Postup provedení prací: Dle DGAC AD 1992-156-133(B) R1.

Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát - Ing. Toman. Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě DGAC AD 1992-156-133(B) R1, který nahrazuje DGAC AD 1992-156-133(B).

Ing. Pavel MATOUŠEK

Ředitel technického inspektorátu

Úřad pro civilní letectví

DGAC AD No.: 1992-156-133(B) R1

AIRBUS INDUSTRIE

A300, A310 and A300-600 aircraft

Brakes- Flight Manual (ATA 04, 32)

APPLICABILITY:

AIRBUS INDUSTRIE A300, A310 and A300-600 aircraft, all certified models, all serial numbers equipped with MESSIER carbon brakes, except for aircraft entirely equipped with MESSIER carbon brakes MB M318 (8 brake assemblies per aircraft).

Aircraft on which AIRBUS INDUSTRIE modification No.10848 or 10849 has been entirely embodied in production (AIRBUS INDUSTRIE Service Bulletin (SB) A300-32-0410 or A310-32-2082 or A310-32-2084 or A300-32-6050 in service) are no longer concerned by the requirements of this Airworthiness Directive (AD).

REASONS:

In order to cover the brake performance loss of different aircraft models equipped with "old generation" MESSIER carbon brakes and pending corrective measures, the

original issue of this Airworthiness Directive had required the incorporation of temporary revisions (T.R.) into the Flight Manuals (AFM) of the aircraft concerned.

Revision 1 of this AD takes account of the introduction of "new generation" MESSIER carbon brakes - type MB M318 -and requires the incorporation of the new T.R.s into the AFMs of the aircraft concerned in the case of mixed installation, i.e. old generation brakes - new generation brakes.

ACTIONS:

1) On the effective date of this AD at Revision 1, unless already accomplished, incorporate the following T.R.s into the Flight Manuals of the concerned aircraft and comply with the associated performance limitations :

-A300 B2K and B4 on which modification 6409 has been embodied: A300 Flight Manual Temporary Revision 5-02-00/1 and 5-02-00/2.

- A310-304, -322, -324, -308, -204 and -222 Var 100 with a maximum take-off weight lower than or equal to 157 T. and on which modification 5443 has been embodied: A310 Flight Manual Temporary Revision 5-04-00/3 and 5-04-00/06.

-A310-200 on which modification 6591 has been embodied: A310 Flight Manual Temporary Revision 5-04-00/3 and 5-04-00/06.

- A310-308 [...] on which modification 8244 has been embodied: A310 Flight Manual Temporary Revision 5-04-00/1 and 5-04-00/05.

- A310-325 equipped with carbon brakes MHB 81 MJ: A310 Flight Manual Temporary Revision 5-04-00/4 and 5-04-00/07.

- A300 B4-600 and B4-600R all certified models except for B4-601, on which modification 5670 has been embodied: A300-600 Flight Manual Temporary Revision 5-04-00/1 and 5-04-00/04.

- A300 B4-601 on which modification 5670 has been embodied: A300-600 Flight Manual Temporary Revision 5-04-00/2 and 5-04-00/03.

2) The AFM Temporary Revisions mentioned above are no longer applicable in accordance with this AD when the eight brake assemblies of the concerned aircraft are equipped with carbon brakes MB M318.

REF.: Flight Manual A300 Temporary Revision 5-02-00/1 and 5-02-00/2.

A310 Temporary Revision 5-04-00/3 and 5-04-00/06.

A310 Temporary Revision 5-04-00/1 and 5-04-00/06.

A310 Temporary Revision 5-04-00/4 and 5-04-00/05.

A300-600 Temporary Revision 5-04-00/1 and 5-04-00/04.

A300-600 Temporary Revision 5-04-00/2 and 5-04-00/03.

This Revision 1 supersedes AD 92-156-133(B) dated July 22, 1992.

EFFECTIVE DATES:

Original AD : JULY 22,1992

Revision 1 : Upon receipt from NOVEMBER 15, 2000

