

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

CAA-AD-128/1999

Datum vydání: 8. prosince 1999

MOTOR - STARTÉR - KONTROLA/MODIFIKACE

Týká se: motorů L2000EA, vyrobených firmou Limbach Flugmotoren GmbH, všech výrobních čísel, vybavených elektrickým startérem SJCE 0,9kW katalogového čísla P/N 202.143.020.000.

Důvod vydání: možnost prasknutí krytu pastorku starteru v oblasti přechodu do příruby.

Datum účinnosti: 27. ledna 2000.

Provést v termínech: Jak je popsáno v LBA AD 97-003 (příloha tohoto PZZ).

Postup provedení prací: Dle pokynů v LBA AD 97-003.

Poznámky: Provedení tohoto PZZ musí být zapsáno do motorové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát - Ing. Beneš. Pokud to vyžaduje povaha tohoto PZZ musí být zapracováno do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě LBA AD 97-003.

Ing. Pavel MATOUŠEK
Ředitel technického inspektorátu
Úřad pro civilní letectví

LBA AD 97-003

Limbach L2000

Effective Date:16 January 1997

Affected:

Kind of aeronautical product: Motorglider Engine

Manufacturer: Limbach Flugmotoren GmbH, Königswinter, Germany

Type: L2000

Models affected: L2000EA

Serial numbers affected: all, equipped with electric starter SJCE 0.9kW P/N 202.143.020.000

German Type Certificate No.: 4597

Subject:

Starter shaft support case of electric starter SJCE 0.9kW P/N 202.143.020.000

Reason:

Broken starter shaft support case.

Action:

The following actions are required in the scope of this AD:

- Inspection of starter shaft support case. If a reinforced starter shaft support case is already installed, no further actions are required.
- Installation of modified starter shaft support case.

All necessary inspections and replacement of parts must be performed on the basis of the Limbach Technical Bulletin No.52.

Compliance (for the mentioned actions):

Before next flight.

Technical publication of the manufacturer:

Limbach Technical Bulletin No.52, date of issue 6 September 1996.

This Technical Bulletin can be obtained from:

Limbach Flugmotoren GmbH

Kotthausener Strasse 5

53639 Königswinter

Fax-No. 0049 2244 6976

Germany

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the log book by a licensed inspector.