



ÚŘAD PRO CIVILNÍ LETECTVÍ

SEKCE TECHNICKÁ

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

Číslo: EASA AD 2011-0082

Účinnost od: 24. května 2011

BRP-Powertrain GmbH & Co. KG

Rotax 914 F


Tento PZZ je vydáván pro výrobek transferovaný pod působnost EASA.

Na základě rozhodnutí EASA je následující Příkaz k zachování letové způsobilosti závazný pro všechny výrobky provozované v EU, na které se daný PZZ vztahuje.

Provedení PZZ, který se vztahuje podle typu a výrobního čísla na výrobek je pro provozovatele/vlastníka letadla zapsaného do leteckého rejstříku závazné. Neprovedením PZZ ve stanoveném termínu dojde ke ztrátě letové způsobilosti výrobku.

Poznámky:

- Provedení tohoto PZZ musí být zapsáno do provozní dokumentace letadla.
- Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická.
- Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla.

EASA	AIRWORTHINESS DIRECTIVE	
	<p>AD No.: 2011-0082</p> <p>Date: 10 May 2011</p> <p>Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>	
<p>This AD is issued in accordance with EC 1702/2003, Part 21A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].</p>		
Type Approval Holder's Name:		Type/Model designation(s):
BRP-Powertrain GmbH & Co. KG		Rotax 914 F series engines
TCDS Number:	EASA.E.122	
Foreign AD:	Not applicable	
Supersedure :	None	
ATA 73	Engine Fuel & Control – Fuel Pressure Regulator – Identification / Replacement	
Manufacturer(s):	BRP-Powertrain GmbH & Co. KG, BRP-Rotax GmbH & Co. KG; Bombardier-Rotax GmbH & Co. KG; Bombardier-Rotax GmbH	
Applicability:	<p>Rotax 914 F2, 914 F3 and 914 F4 engines, all serial numbers.</p> <p>These engines are known to be installed on, but not limited to, the following types of aeroplanes (mostly powered sailplanes): Aeromot AMT-300 Turbo Super Ximango, Aircraft Philipp (formerly Alpha-Werke; Nitsche) AVO 68 series Samburo, Diamond (formerly HOAC) HK 36 series Super Dimona, Scheibe SF 25C and Stemme S10-VT.</p> <p>Note: The installation of these engines was either done by the respective aeroplane manufacturer or through modification of the aeroplane by Supplemental Type Certificate.</p>	
Reason:	<p>Isolated manufacturing deviations have been reportedly found on the threads of a certain batch of Fuel pressure Regulators, Part Number (P/N) 887130, installed on Rotax 914 F series engines.</p> <p>This condition, if not corrected, could lead to a fuel leak and in-flight fire which would necessitate an engine shut-down, possibly resulting in a forced landing, with consequent damage to the aeroplane and injury to occupants.</p> <p>For the reasons describe above, this AD requires the replacement of all affected P/N 887130 Fuel Pressure Regulators with serviceable parts.</p>	
Effective Date:	24 May 2011	

<p>Required Action(s) and Compliance Time(s)</p>	<p>Required as indicated, unless accomplished previously:</p> <p>(1) Within 100 flight hours or 6 months, whichever occurs first after the effective date of this AD, accomplish the following actions:</p> <p>(1.1) Identify the serial number (s/n) of the P/N 887130 Fuel Pressure Regulator installed on the aeroplane.</p> <p>(1.2) If the s/n of the P/N 887130 Fuel Pressure Regulator, identified as required by paragraph (1.1) of this AD, is listed in Appendix 1 of this AD, replace the P/N 887130 Fuel Pressure Regulator, in accordance with the instructions of BRP-Powertrain Mandatory Service Bulletin (SB) SB-914-040, with a serviceable unit, having a s/n not listed in Appendix 1 of this AD.</p> <p>(2) From the effective date of this AD, do not install a P/N 887130 Fuel Pressure Regulator on an engine, unless it has been determined that the s/n is not listed in Appendix 1 of this AD.</p> <p>(3) From the effective date of this AD, do not install a Rotax 914 F series engine on an aeroplane, unless it has been determined that the s/n of the P/N 887130 Fuel Pressure Regulator installed on that engine is not listed in Appendix 1 of this AD.</p>
<p>Ref. Publications:</p>	<p>BRP-Powertrain Mandatory SB-914-040 dated 10 March 2011.</p> <p>The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.</p>
<p>Remarks:</p>	<p>1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.</p> <p>2. This AD was posted on 24 March 2011 as PAD 11-033 for consultation until 21 April 2011 and republished on 04 April 2011 as PAD 11-033R1. No comments were received during the consultation period.</p> <p>3. Enquiries regarding this AD should be referred to the Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA. E-mail ADs@easa.europa.eu.</p> <p>4. For any question concerning the technical aspects of the requirements in this AD, please contact: BRP-Powertrain GmbH & Co. KG Telephone: +43 7246 601 0; Fax: +43 7246 601 9130; E-mail: airworthiness@brp.com, Website www.rotax-aircraft-engines.com.</p>

Appendix 1 – Serial Numbers of affected P/N 887130 Fuel Pressure Regulators

Note: Some of the listed components have been delivered as spares; others are known to be currently installed on 914 UL2 engines, which are non-certified engines and intended for installation on non-certified aeroplanes, e.g. Microlight- or Kit (i.e. home-built) aeroplanes.

100200 through 100246 inclusive
100248 through 100280 inclusive
100282 through 100293 inclusive
100295 through 100314 inclusive
100316 and 100317
100319 through 100326 inclusive
100330
100332 and 100333
100338 through 100340 inclusive
100342 through 100345 inclusive
100348
100350 through 100355 inclusive
100357 through 100363 inclusive
100365 through 100368 inclusive
100371 and 100372
100374 through 100376 inclusive
100379 and 100380
100395 and 100396