

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

CAA-AD-027/2001

Datum vydání: 28. března 2001

VRTULNÍK - POLSTROVÁNÍ ZADNÍ LAVICE (ATA 25)

Týká se: vrtulníků AS 355 E, F, F1, F2 a N vyrobených firmou EUROCOPTER, vybavených zadní lavicí všech typů. Tento PZZ je určen pro personál údržby a posádky.

Důvod vydání: byly hlášeny dva případy ztráty polstrování zadní lavice za letu při konfiguraci s otevřenými dveřmi. Polstrování se pak následně může dostat do kontaktu s hlavním nebo vyrovnávacím rotorem, což může vést ke ztrátě ovladatelnosti vrtulníku.

Datum účinnosti: 29. března 2001.

Provést v termínech: Jak je popsáno v DGAC AD 2001-087-062(A) od data účinnosti tohoto PZZ.

Postup provedení prací: Dle pokynů v DGAC AD 2001-087-062(A) (příloha tohoto PZZ).

Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát – Ing. B. Fiala. Pokud to vyžaduje povaha tohoto PZZ, musí být zpracováno do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě DGAC AD 2001-087-062(A).

Ing. Pavel MATOUŠEK
Ředitel technického inspektorátu
Úřad pro civilní letectví

DGAC AD No.: 2001-087-062(A)
EUROCOPTER
AS 355 Helicopters – Rear bench cushions (ATA 25)

1. EFFECTIVITY

This Airworthiness Directive applies to AS 355 helicopters, versions E, F, F1, F2 and N equipped with all rear bench models.

Caution: This Airworthiness Directive is intended for maintenance personnel and crews.

2. REASON

This Airworthiness Directive is issued subsequent to two reports of in-flight loss of the rear bench cushion in doors-removed configurations. The cushions thus lost might come into contact with the main rotor or the tail rotor might result in loss of helicopter control.

3. MANDATORY ACTIONS AND COMPLIANCE TIME

The following actions are rendered mandatory from the effective date of this Airworthiness Directive:

Remove the cushions from the rear benches before you perform a flight with the door(s) removed and/or the sliding door(s) in the open position.

EFFECTIVE DATE: ON RECEIPT FROM MARCH 21, 2001