



CIVIL AVIATION AUTHORITY  
CZECH REPUBLIC  
Airworthiness Division  
Airport Ruzyně, 160 08 Prague 6  
Tel: 420 233320922, fax: 420 220562270

## AIRWORTHINESS DIRECTIVE

**Number: CAA-AD-T-005/2004**

Date of issue: January 16, 2004

**Letecké závody a.s. (formerly LET a.s.)**  
L 23 Super-Blaník

---

### SAILPLANE – ELEVATOR – ROCKER LEVER - INSPECTION

---

**Applicability:** for L 23 Super-Blaník sailplanes, serial numbers up to S/N 039019, produced by Letecké závody a.s. (formerly LET a.s.) Company.

**Reason:** during investigation of accident of the sailplane was discovered damage of elevator rocker lever. This failure could lead to lost of the sailplane control and subsequent to the accident of the sailplane.

**Effective date:** Upon receipt

**Compliance:**

Before the next flight the NDT (magnetic testing) inspection of elevator rocker lever must be performed in accordance with Mandatory Bulletin No.: L23/48a dated January 16, 2004, which becomes herewith part of this AD and may be obtained from: LETECKÉ ZÁVODY a.s., 686 04 Kunovice, Czech Republic.

---

*Remarks: The compliance of this AD must be recorded in Sailplane Logbook, where applicable the requirements of this AD must be integrated into Aircraft Technical Documentation. Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyně Airport, 160 08 Prague 6, Czech Republic, tel: 420 233320922, fax: 420 220562270.*

**Ing. Pavel MATOUŠEK**  
director