



CIVIL AVIATION AUTHORITY
CZECH REPUBLIC
Airworthiness Division
Airport Ruzyne, 160 08 Prague 6
Tel: 420 233320922, fax: 420 220562270

AIRWORTHINESS DIRECTIVE

Number: CAA-AD-T-022/2004R1
Supersedes CAA-AD-T-022/2004
Date of issue: March 29, 2004
JIHOSTROJ a.s.
LUN 6285.84

APPLIANCE – FUEL PUMP – TEMPERATURE TEST

Applicability: to airplanes equipped with fuel pumps LUN 6285.84 serial numbers listed in Attachment No.:1 of Mandatory Service Bulletin No.: 01-JSV-04a, produced by JIHOSTROJ a.s. Velešín Company.

Reason: Operation of above mentioned fuel pumps indicates that is not possible to ensure during low temperatures safety function of these fuel pumps.

Effective date: May 13, 2004

Compliance:

For renewal of airworthiness of above mentioned fuel pumps in ambient temperature to -55°C is necessary to perform temperature test of fuel pump in accordance with Mandatory Service Bulletin No.: 01-JSV-04a which becomes herewith part of this AD and can be obtained from: JIHOSTROJ a.s., 382 32 VELEŠÍN, Czech Republic. Fuel pump must be sent to the producer to perform temperature test at -55°C .

Remarks: The compliance of this AD must be recorded in Aircraft Logbook, where applicable the requirements of this AD must be integrated into Aircraft Technical Documentation. Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyne Airport, 160 08 Prague 6, Czech Republic, tel: 420 233320922, fax: 420 220562270.

Ing. Pavel MATOUŠEK
director