



CIVIL AVIATION AUTHORITY  
CZECH REPUBLIC  
Airworthiness Division  
Airport Ruzyně, 160 08 Prague 6  
Tel: 420 233320922, fax: 420 220562270

## AIRWORTHINESS DIRECTIVE

**Number: CAA-AD-T-074/2003R1**  
Supersedes CAA-AD-T-074/2003  
Date of issue: October 03, 2003  
**Schempp-Hirth výroba letadel spol. s r.o.**  
**(formerly Orličan s.p. Choceň, Orličan**  
**a.s. Choceň)**  
Discus CS

---

### SAILPLANE - WING - INSPECTION/REPAIR

---

**Applicability:** for Discus CS sailplanes, all serial numbers produced by Schempp-Hirth výroba letadel spol. s r.o. (formerly Orličan s.p. Choceň, Orličan a.s. Choceň) Company.

**Reason:** defects in the bonding of the spar cap and the spar web have been identified, which could lead to destruction of the wing and lost of the airplane control.

**Effective date:** Upon receipt

**Compliance:**

Before the next flight perform for renewal of airworthiness above mentioned sailplanes inspection of the bonding of the spar cap and the spar web and subsequent works in accordance with Mandatory Bulletin No.: DCS/6a., which can be obtained from: Schempp-Hirth výroba letadel spol. s r.o., P.O.BOX 19, 565 01 Choceň, Czech Republic.

---

*Remarks: The compliance of this AD must be recorded in Sailplane Logbook, where applicable the requirements of this AD must be integrated into Aircraft Technical Documentation. Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyně Airport, 160 08 Prague 6, Czech Republic, tel: 420 233320922, fax: 420 220562270.*

**Ing. Pavel MATOUŠEK**  
director