

SWEDISH AIRWORTHINESS DIRECTIVES (SAD)

Section 1. Swedish Manufactured Aeronautical Products

**AIRWORTHINESS
DIRECTIVE NO:** 1-201

APPLICABILITY: FOLA Airsafe life vests type A-190 or A-290

**SERIAL No:s
AFFECTED:** ALL

SUBJECT: Inspection of the zipper on the life vest valise

BACKGROUND: Valises for life vests of type Airsafe A-190 and Airsafe A-290 may have an error on the zippers from assemble at factory. If an incorrect zipper is installed this could lead to an uncontrolled inflation of the life vest.

**REFERENCE
DOCUMENTS:** FOLA Airsafe Service Bulletin 9-387 rev. A or later revision

ACTIONS: Perform actions described in FOLA Airsafe Service Bulletin 9-387 rev. A or later revision

**COMPLIANCE
TIME:** To be performed within three months from the effective date of this Airworthiness Directive

EFFECTIVE DATE: 1 March 2008

DECISION: LS 2008-0762

LUFTFARTSSTYRELSEN / Swedish Civil Aviation Authority

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register

Mail address
SE-601 73 NORRKÖPING
SWEDEN

Office address
Vikboplan 7
Norrköping

Telephone number
+46 11 415 21 00

Fax number
+46 11 415 22 50

E-mail
luffarstsstyrelsen@luffartsstyrelsen.se