



ÚŘAD PRO CIVILNÍ LETECTVÍ  
ČESKÁ REPUBLIKA  
**Sekce technická**  
*letišťe Ruzyně, 160 08 Praha 6*  
*tel: 233320922, fax: 220562270*

## PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

**Číslo: 2006-0092R1 Rušící**

Datum účinnosti: 16. ledna 2007

**Toto AD ruší EASA AD 2006-0092  
vydané 3. května 2006, včetně jeho  
opravy ze 7. září 2006**

**Hartzell Propeller Inc.**

Vrtule model ( )HC-( )2Y( )-( )

---

Tento PZZ je vydáván pro výrobek transferovaný pod působnost EASA


Na základě rozhodnutí EASA je následující Příkaz k zachování letové způsobilosti závazný pro všechny výrobky provozované v EU, na které se daný PZZ vztahuje.

Provedení PZZ, který se vztahuje podle typu a výrobního čísla na výrobek je pro provozovatele/vlastníka letadla zapsaného do leteckého rejstříku závazné. Neprovedením PZZ ve stanoveném termínu dojde ke ztrátě letové způsobilosti výrobku.

---

*Poznámky:*

- Provedení tohoto PZZ musí být zapsáno do provozní dokumentace letadla.
- Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická.
- Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla.

<b>EASA</b>	<b>AIRWORTHINESS DIRECTIVE CANCELLATION NOTICE</b>	
	<p style="text-align: center;"><b>AD No.: 2006-0092R1</b></p> <p style="text-align: center;"><b>Date: 16 January 2007</b></p>	
No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry.		
<b>Type Approval Holder's Name:</b>		<b>Type/Model designation(s):</b>
Hartzell Propeller Inc.		Model ( )HC-( )2Y( )-( ) series
TCDS Numbers: FAA P-920, P9EA, P27EA, P42GL, P37EA, P39EA and P43GL.		
Foreign AD: FAA AD 2006-18-15, issued September 8, 2006.		
Cancellation/Supersedure: <b>This Notice cancels EASA AD 2006-0092 dated 03 May 2006, including the 'correction' dated 07 September 2006.</b>		
<b>ATA 61</b>	<b>Propellers – Propeller Hub – Inspection</b>	
Manufacturer:	Hartzell Propeller Inc.	
Applicability:	<p>Hartzell two blade, aluminum hub, "compact" ( )HC-( )2Y( )-( ) series propellers manufactured before December 1991 that do not have an "A" or "B" suffix letter at the end of the hub and propeller serial numbers and are installed on Lycoming ( )-360 series engines.</p> <p>These engines and propellers could be installed on, but not limited to, various Part (CS) 23 certificated aircraft.</p>	
Reason:	<p>The Agency has reviewed the referenced FAA Airworthiness Directive 2006-18-15 that addresses the same unsafe condition that was addressed by the original issue of this directive. The actions required by the FAA AD are almost identical to the ones required by EASA AD 2006-0092. They are adequate to correct the unsafe condition and therefore that AD is considered 'accepted' under the provisions of Executive Decision (ED) No. 02/2003.</p> <p>For the reasons described above, EASA AD 2006-002 is hereby cancelled.</p>	
Effective Date:	16 January 2007	
Compliance	Not applicable	
Ref. Publications:	Hartzell Propeller Inc. Service Bulletin HC-SB-61-269, dated April 18, 2005	

Remarks:	<ol style="list-style-type: none"><li data-bbox="555 174 1417 235">1. Enquiries regarding this Notice should be referred to the AD Focal Point - Certification Directorate, EASA. E-mail: <a href="mailto:ADs@easa.europa.eu">ADs@easa.europa.eu</a></li><li data-bbox="555 280 1417 403">2. For any questions concerning the content of this cancellation notice, please contact Hartzell Propeller Inc. Technical Publications Department, One Propeller Place, Piqua, OH 45356; telephone (937) 778-4200; fax (937) 778-4391; E-Mail: <a href="mailto:techsupport@hartzellprop.com">techsupport@hartzellprop.com</a></li></ol>
----------	---