

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

CAA-AD-3-066R1/97

Datum vydání: 16. listopadu 1998

LETADLO - VSTUP VZDUCHU DO MOTORU - MODIFIKACE

Týká se: letadel vyrobených firmou SAAB typů SAAB SF340A výrobních čísel -004 až -159 a SAAB 340B výrobních čísel -160 až -219 a -402 až -436 vybavených vstupů do motoru "Aerospace Composite Technologies".

Datum účinnosti: 31. prosince 1998

Provést v termínech: jak je popsáno v SAD AD č. 1-119R1 (příloha tohoto PZZ).

Postup provedených prací: dle SAD AD č. 1-119R1.

Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát - Ing. Stibůrek. Pokud to vyžaduje povaha tohoto PZZ musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě SAD AD č. 1-119R1, které ruší č. 1-119.

Ing. Pavel MATOUŠEK
Ředitel technického inspektorátu
Úřad pro civilní letectví

LUFTFARTSVERKET Aviation Safety Department SWEDISH AIRWORTHINESS DIRECTIVES (SAD)

SAD No 1-119R1 Cancels SAD No 1-119

Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS DIRECTIVE NO: 1-119R1

AIRCRAFT TYPE: SAAB SF 340A and SAAB 340B

SERIAL No's AFFECTED: SAAB SF 340A -004 through -159 and SAAB 340B -160 through -219 and -402 through -436 equipped with Aerospace Composite Technologies (ACT) Engine Air Intakes.

Note: Effectivity changed

SUBJECT: Ice & Rain Protection - Engine Air Intake -Modification of the Detachable Center Inlet.

BACKGROUND: The design and manufacturing method of the detachable center inlet produces two apertures at the rear of the component. These holes must be closed to fully comply with fire resistance regulations.

REFERENCE DOCUMENTS: Saab AB Service Bulletin SAAB 340-30-073 Revision 1 dated October 1, 1998 and Attachment 1.

ACTIONS: Perform actions described in Saab AB Service Bulletin SAAB 340-30-073 Revision 1, dated October 1,1998, and Attachment 1, or later revision.

COMPLIANCE TIME: To be performed within two years from the effective date of this SAD.

EFFECTIVE DATE: 8 October, 1998