

PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

CAA-AD-063/2002

Datum vydání: 12. června 2002

VRTULNÍK - NAVIGACE - NAVIGAČNÍ UKAZATEL HORIZONTÁLNÍ SITUACE KI 525A (ATA 34) - KONTROLA

Týká se: vrtulníků AS 355 E, F, F1, F2 a N vyrobených firmou EUROCOPTER, vybavených navigačním ukazatelem horizontální situace HSI KI 525A.

Důvod vydání: objeveny případy nesprávné instalace HSI KI 525A katalogového čísla P/N 066-3046-07 (která nebyla provedena v souladu s ALLIEDSIGNAL Service Bulletin No. 341), což může vést k chybám při navigaci.

Datum účinnosti: 08. srpna 2002.

Provést v termínech: Jak je popsáno v DGAC AD 2002-280-068(A) od data účinnosti tohoto PZZ.

Postup provedení prací: Dle DGAC AD 2002-280-068(A) (příloha tohoto PZZ).

Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL sekce technická – Ing. B. Fiala. Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě DGAC AD 2002-280-068(A).

Ing. Pavel MATOUŠEK
ředitel sekce technické
DGAC AD No.: 2002-280-068(A)

EUROCOPTER

AS 355 helicopters Navigation - Horizontal situation indicator KI 525A (ATA 34)

1. EFFECTIVITY

AS 355 helicopters versions E, F, F1, F2 and N equipped with HSI KI 525A.

2. REASON

This Airworthiness Directive is issued following the discovery of incorrect installation of HSI KI 525A P/N 066-3046-07 (non-compliance with equipment manufacturer ALLIEDSIGNAL Service Bulletin No. 341), which might result in navigation errors.

3. MANDATORY ACTIONS AND COMPLIANCE TIME

The following measures are rendered mandatory from the effective date of this Airworthiness Directive.

- No later than within the next 100 flight hours or within 1 month (whichever limit is reached first):

- a) Check the part number of HSI KI 525A installed on aircraft.
- b) If the part number read is 066-3046-07 comply with the instructions given in paragraph 2.A.1 or paragraph 2.A.2 of referenced EUROCOPTER AS 355 Alert Telex No. 34.00.09 according to aircraft installation.

REF.: EUROCOPTER AS 355 Alert Telex No. 34.00.09.

EFFECTIVE DATE: JUNE 08, 2002