

# PŘÍKAZ K ZACHOVÁNÍ LETOVÉ ZPŮSOBILOSTI

**CAA-AD-077/2001**

Datum vydání: 30. srpna 2001

## LETADLOVÉ ZAŘÍZENÍ - "DĚTSKÉ POSTÝLKY" (ATA 25) - INSTALACE

**Týká se:** dětských sedaček vyrobených firmou INNOVINT AIRCRAFT INTERIOR, základní model PNR: 7250-XXA, 7250-XXB, 7253-XXB, všech výrobních čísel.

Tyto dětské sedačky mohou být nainstalovány na letadlech AIRBUS, BOEING, DOUGLAS a FOKKER, ale nejen na těchto.

**Datum účinnosti:** 04. října 2001

**Provést v termínech:** Jak je popsáno v DGAC AD 2001-351(B), od data účinnosti tohoto PZZ.

**Postup provedení prací:** Dle DGAC AD 2001-351(B) (příloha tohoto PZZ).

Poznámky: Provedení tohoto PZZ musí být zapsáno do letadlové knihy. Případné dotazy týkající se tohoto PZZ adresujte na ÚCL technický inspektorát - Ing. Toman. Pokud to vyžaduje povaha tohoto PZZ, musí být zapracován do příslušné části dokumentace pro obsluhu, údržbu a opravy letadla. Tento PZZ byl vypracován na základě DGAC AD 2001-351(B).

**Ing. Pavel MATOUŠEK**  
**Ředitel technického inspektorátu**  
**Úřad pro civilní letectví**

**DGAC AD No.: 2001-351(B)**  
**INNOVINT AIRCRAFT INTERIOR**

Equipment: babies bassinets

PIP pins protection flap assy installation and installation of a set screw (ATA 25)

### 1. APPLICABILITY:

INNOVINT AIRCRAFT INTERIORS baby bassinets model basic PNR: 7250-XXA, 7250-XXB, 7253-XXB, all serial numbers.

These baby bassinets can be installed, but not limited to, AIRBUS, BOEING, DOUGLAS and FOKKER aircraft.

### 2. REASONS:

Due to unprotected PIP-pin, Innovint baby bassinets can be unintentionally released by passengers or attendants and fall to the cabin floor. This situation, if left uncorrected, can lead to serious injury to baby during the fall.

### 3. COMPLIANCE:

Before December 31, 2002, to prevent the PIP-pin against inadvertent release, modify pin installation as per Service Bulletin INNOVINT AIRCRAFT INTERIOR 7250-25-002 and Service Bulletin INNOVINT AIRCRAFT INTERIOR 7250-25-003.

### REF.:

Service Bulletin INNOVINT AIRCRAFT INTERIOR 7250-25-002

Service Bulletin INNOVINT AIRCRAFT INTERIOR 7250-25-003

**EFFECTIVE DATE:** AUGUST 18, 2001