

Registration mark:	LN
Type of main parachute:	peregrine 75
Type of backup parachute:	wp 110
Type of carrying harness with packing:	real x 02
Type of safety device:	m2 multi
Parachute's owner:	
Skydiver's name:	
- Nationality:	
- Category:	D
Number of jumps (last 3 months):	670
Number of jumps (total):	17000+
Instructor's name (cat. S, A, B only):	
Tandem passenger's name:	
- Nationality:	
Event date:	2.8.2019
Time (local):	14.00
Site of last takeoff:	LKKT
Jump landing area:	LKKT
Number of fatalities:	0
Number of seriously injuries:	0
Number of minor injuries:	0
No injuries:	0
Event description:	<p>po otevreni hlavniho padaku zustal slider zachyceny ve vetveni nosnych snur cca. 1m pod vrchlikem a nasledne doslo k prudke leve rotaci vrchliku. Pokus o odstraneni zavady pomoci zadnich popruhu, pripadne snizit rotaci vrchliku se nepodarilo. Po odhozeni nefunkcniho hlavniho padaku, srovnani polohy byl otevren zalozni padak. Zalozni padak byl plne nafouknuty a odbrzdeny ve vysce 680m. Pristani probehlo na hlavni pristavaci plochu DZ Klatovy, nedoslo k zadnemu zraneni ani skode na majetku. Odhozeny vrchlik byl nalezen a predan majiteli:))</p>
Damage description and scope:	