

**MAINTENANCE ORGANISATION TERMS OF APPROVAL
PODMÍNKY OPRÁVNĚNÍ ORGANIZACE ÚDRŽBY**

Reference / Číslo osvědčení:

CZ.145.0054

Organisation / Organizace:

JOB AIR Technic a.s., Mošnov, Gen. Fajtla 370, PSČ 742 51

CLASS / TŘÍDA	RATING / KVALIFIKACE	LIMITATION / OMEZENÍ	LINE / TRÁŤ	BASE / ZÁKL.
AIRCRAFT LETADLA	A	Boeing 737 (CFM 56, CFM LEAP-1B engines) Series / Řada AIRBUS A318 - A319 - A320 - A321 (CFM 56, IAE V2500 engines) Series / Řada; AIRBUS A319 - A320 - A321 (CFM LEAP-1A, PW1100G engines) Series / Řada; AIRBUS A330 (GE CF6, PW 4000, RR Trent 700 engines) Series / Řada	YES / ANO	YES / ANO
	Privilege acc. to M.A.901(I): NO Právo dle M.A.901(I): NE			
ENGINES MOTORY	B	B1 Turbine / Turbínové	Borecope inspection of engines and APU according to the MOE JAT - QA – 006, chap. 1.9 / Boroskopická kontrola motorů a APU dle MOE JAT - QA – 006, kap. 1.9	
		B3 APU / APU		
COMPONENTS OTHER THAN COMPLETE ENGINES OR APUs LETADLOVÉ CELKY JINÉ NEŽ KOMPLETNÍ MOTORY NEBO APU	C	C1 Air Condit. & Pressur. / Klimatizace a přetlakování	Components according to the CL JAT - QA - 009 / Letadlové celky v souladu se seznamem LC JAT - QA - 009	
		C2 Auto Flight. / Automatické řízení letu		
		C3 Comms and Nav. / Spojení a navigace		
		C4 Doors - Hatches / Dveře – Přístupové otvory		
		C5 Electrical Power & Lights / Elektrické zdroje a osvětlení		
		C6 Equipment / Vybavení		
		C7 Engine - APU / Motor - APU		
		C8 Flight Controls / Řízení letadla		
		C9 Fuel / Palivo		
		C12 Hydraulic Power / Hydraulika		
		C13 Indicating – Recording Systems / Indikační a záznamové systémy		
		C14 Landing Gear / Přistávací zařízení		
		C15 Oxygen / Kyslík		
		C17 Pneumatic & Vacuum / Pneumatické a podtlakové systémy		
		C18 Protection from ice / rain / fire / Ochrana proti námraze / dešti / požáru		
		C19 Windows / Okna		
		C20 Structural / Konstrukce draku		

SPECIALISED SERVICES SPECIALIZOVANÉ SLUŽBY	D1	Non destructive testing / Nedestruktivní zkoušení	VT (Visual, Borescopic and Endoscopic Testing / Vizuální, boroskopická a endoskopická metoda) PT (Penetrant Testing / Kapilární metoda) ET (Eddy Current Testing / Metoda vířivých proudů) MT (Magnetic Particle Testing / Magnetická prášková metoda) UT (Ultrasonic Testing / Ultrazvuková metoda) RT (Radiographic Testing / Radiografická metoda) TT (Thermographic Testing / Termografická metoda)
---	----	--	---

These terms of approval are limited to those products, parts and appliances and to the activities specified in the scope of work section of the approved maintenance organisation exposition,
 Toto podmínky oprávnění jsou omezeny na výrobky, letadlové části a zařízení a na činnosti stanovené v části uvádějící rozsah prací ve schváleném výkladu organizace údržby,

Maintenance Organisation Exposition reference / Číslo výkladu organizace údržby: JAT - QA - 006

Date of original issue / Datum původního vydání: 1.1.2008

Date of last revision approved / Datum poslední schválené změny: 6.12.2021

Revision No / Změna č.: 42

For the Competent Authority / Za příslušný úřad:
CAA CZ / Úřad pro civilní letectví

Ing. Vít Zárybnický
 Director of Technical Division / Ředitel Sekce technické

Signed / Podpis: _____

13 1.9 Zamýšlený rozsah práce / ORGANIZATION INTENDED SCOPE OF WORK

Společnost Job Air Technic a.s. smí provádět pouze práce, které jsou uvedeny v oprávnění dle EASA Part 145. Podrobnosti o schváleném rozsahu práce jsou uvedeny v tabulce níže.

The organization Job Air Technic a.s. may only perform work specified in the approval in accordance with EASA Part 145. For the details of the approved scope of works, see the table below.

AIRCRAFT /LETADLA					
CLASS / TRÍDA	RATING / KVALIFIKACE		LIMITATION / OMEZENÍ	LINE / TRATOVÁ	BASE / ZÁKL.
AIRCRAFT LETADLA	A1	Aeroplanes above 5700kg/Letouny nad 5700 kg	Boeing 737-300/400/500 (CFM56) Series/Rada Boeing 737-600/700/800/900 (CFM56) Series/Rada Boeing 737-7/8/9 (CFM LEAP-1B) Series/Rada Airbus A318-A319-A320-A321 (CFM56, IAE V2500) Series/Rada Airbus A319-A320-A321 (CFM LEAP-1A, PW1100G) Series/Rada Airbus A330 (GECF6, PW4000, RRTrent 700) Series/Rada	YES / ANO	YES / ANO
ENGINES MOTORY	B1	Turbine/Turbínové	Boroscope inspection CFM56 Family Boroscope inspection IAE V2500 Boroscope inspection CFM LEAP Family		
	B3	APU	Boroscope inspection Honeywell 131-9		

COMPONENTS OTHER THAN COMPLETE ENGINES OR APUs LETADLOVÉ CELKY JINÉ NEŽ KOMPLETELNÍ MOTOR NEBO APU	C1	Air cond. & Press / Klimatizace a přetlakování	Aircraft Components i.a.w. Capability List / Letadlové celky podle seznamu udržovaných celků JAT-QA-009
	C2	Autopilot / Automatické řízení letu	
	C3	COMMs and NAV / Spojení a navigace	
	C4	Dveře, otvory /Doors	
	C5	Electrical Power / Elektrické napájení a osvětlení	
	C6	Equipment / Vybavení	
	C7	Engine – APU / Motor – APU	
	C8	Flight Controls / Řízení letadla	
	C9	Fuel – Airframe / Palivo – Drak	
	C12	Hydraulic / Hydraulika	
	C13	Instruments / Indikátory – záznamový systém	
	C14	Landing Gear / Přistávací zařízení	
	C15	Oxygen / Kyslík	
	C17	Pneumatic and Vacuum/Pneumatické a podtlakové systémy	
	C18	Protection Ice, Rain, Fire / Ochrana proti	

		dešti, námraze, požáru	
	C19	Windows / Okna	
	C20	Structure / Konstrukce draku	
SPECIALISED SERVICES SPECIALIZOVANÉ SLUŽBY	D1	Non Destructive Inspection / Nedestruktivní prohlídky	VT (Visual, Boroscopic and Endoscopic Testing / Vizuální boroskopická a endoskopická metoda) PT (Penetrant Testing / Kapilární metoda) ET (Eddy Curent Testing / Metoda vířivých proudů) MT (Magnetic Particle Testing / Magnetická prášková metoda) UT (Ultrasonic Testing / Ultrazvuková metoda) RT (Radiographic Tesning / Radiografická metoda) TT (Thermographic Tesning / Termografická metoda)

1.9.1 Rozsah údržby

- Údržba letecké techniky na základně dle schváleného rozsahu a platné dokumentace k údržbě
- Zástavby a modifikace dle platné dokumentace k údržbě
- Údržba leteckých komponentů dle Capability listu JAT-QA-009
- Traťová údržba
- Organizace je oprávněná provádět činnosti, které jsou uvedeny Part 145.A.75 a jsou v souladu s oprávněním organizace a tímto Výkladem organizace údržby
- NDT služby
- Organizace smí provádět podporu během lakování letounů v organizaci International Aerospace Coating Czech Republic a.s. na adrese Gen. Fajtla 371, 742 51 Mošnov. Technická podpora je omezena na úkoly údržby, které nevyžadují rozsáhlou demontáž a mohou být provedeny jednoduchými prostředky
- Organizace je oprávněná vyrobit omezený počet dílů, který je možné použít pro zamýšlený rozsah práce dle Part 145.A.42.b(iii), na základě schválené dokumentace. Takto

1.9.1 Maintenance Scope

- Aircraft maintenance based on approved maintenance documentation
- Modifications based on approved maintenance documentation
- Aircraft components maintenance I.A.W. Capability list JAT-QA-009
- Line maintenance
- The organization is authorized to perform the activities listed in Part 145.A.75 and that are in accordance with the organization's approval and this Maintenance Organization Exposition.
- NDT services
- The organization is approved to perform technical support during aircraft painting procedure at International Aerospace Coating Czech Republic a.s., Gen. Fajtla 371, 742 51 Mošnov. The technical support is limited to maintenance tasks which do not require extensive, in-depth disassembly of the aircraft or its parts
- The organization is approved to produce limited amount of spare parts based on approved documentation. The spare parts can be used for mentioned scope of work I.A.W. Part

Job Air Technic a.s.

JAT-QA-006

Strana: 13-3

Dokument zobrazený na intranetu JOB AIR je řízen správcem dokumentace JOB AIR.
PO VYTÍSTĚNÍ JE VÝTISK NEŘÍZENÝ A POUZE PRO INFORMACI, pokud není barevně označen stanoveným razítkem.
The document published on the JOB AIR Intranet is controlled by the Document System Manager.
A PRINTED DOCUMENT IS UNCONTROLLED AND FOR INFORMATION ONLY, unless identified by a given stamp

vyrobené díly mohou být použity pouze organizací Job Air Technic a.s. při údržbě letadel nebo letadlových celků. Takto vyrobené díly nesmí být prodávány nebo jinak poskytovány třetím osobám.

145.A.42.b(iii). Produced parts cannot be sold separately or otherwise provided to third parties.

1.9.2 Omezení

N/A

1.9.2 Limitation

N/A



CAPABILITY LIST

Email
contracts@jobair.cz

Phone
+420 556 789 111

Note:

Only last revision of technical documentation (CMM) can be used for maintenance of aircraft components mentioned in the Capability List JAT-QA-009.
Customer/Operator is responsible for current revision of technical documentation if the technical documentation is provided by Customer/Operator as per MOE JAT-QA-006, Chapter 2.8.

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
----	-------------	--------------	--------------------

C1 Air Cond & Press

ATA: 21

20790-20BA	Outflow valve	Inspected/Tested Repaired	CMM-21-31-33 CMM-21-31-33
749A0000-02	PLENUM CHAMBER-AIR COOLIN	Inspected/Tested	CMM 21-52-07

C3 Comms and Nav

ATA: 34

E0052R18B32PNE	Connector	Inspected/Tested	AMM 34-52-00-860-001-A
----------------	-----------	------------------	------------------------

C4 Doors - Hatches

ATA: 52

H414-67	Latch assy	Inspected/Tested Repaired	CMM 52-36-15 CMM 52-36-15
---------	------------	------------------------------	------------------------------

C5 Electrical Power & Lights

ATA: 24

024147-000	MAIN BATTERY	Inspected/Tested Overhauled	CMM 24-31-07 CMM 24-31-07
27478	BATTERY,MAIN	Inspected/Tested Overhauled	CMM 24-32-02 CMM 24-32-02
2758	BATTERY	Inspected/Tested Overhauled	CMM 24-38-51 CMM 24-38-51
4078-7	BATTERY AY-43AH	Inspected/Tested Repaired Overhauled	CMM 24-34-00 CMM 24-34-00 CMM 24-34-00
416526	BATTERY	Inspected/Tested Overhauled	CMM 24-38-58 CMM 24-38-58
447CH7	MAIN BATTERY	Inspected/Tested Overhauled	CMM 24-34-10 CMM 24-34-10
4579	BATTERY MAIN	Inspected/Tested Overhauled	CMM 24-31-05 CMM 24-31-05

ATA: 33

31-9292-1	LENS ASSY	Inspected/Tested	CMM 33-43-21
3214-31	BATTERY	Inspected/Tested	AMM 33-51-00-710-003
3214-54-10	EPSU	Overhauled	CMM 33-51-12
3214-54-20	EPSU Battery	Overhauled	CMM 33-51-12
3214-55-10	EPSU Battery	Overhauled	CMM 33-51-12
3214-62-10	EPSU	Overhauled	CMM 33-51-12
3214-62-20	EPSU Battery	Overhauled	CMM 33-51-12

C6 Equipment

ATA: 25

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
1009692-001	SEAT	Inspected/Tested	CMM 25-28-50
		Repaired	CMM 25-28-50
		Overhauled	CMM 25-28-50
1009692-004	SEAT	Inspected/Tested	CMM 25-28-50
		Repaired	CMM 25-28-50
		Overhauled	CMM 25-28-50
1009692-005	SEAT	Inspected/Tested	CMM 25-28-50
		Repaired	CMM 25-28-50
		Overhauled	CMM 25-28-5
1009692-008	SEAT	Inspected/Tested	CMM 25-28-50
		Repaired	CMM 25-28-50
		Overhauled	CMM 25-28-50
1011658-001	SEAT	Inspected/Tested	CMM 25-22-53
		Repaired	CMM 25-22-53
		Overhauled	CMM 25-22-53
1011658-003	SEAT	Inspected/Tested	CMM 25-22-53
		Repaired	CMM 25-22-53
		Overhauled	CMM 25-22-53
1011658-101	SEAT	Inspected/Tested	CMM 25-22-53
		Repaired	CMM 25-22-53
		Overhauled	CMM 25-22-53
1011659-002	SEAT	Inspected/Tested	CMM 25-22-53
		Repaired	CMM 25-22-53
		Overhauled	CMM 25-22-53
1011659-004	SEAT	Inspected/Tested	CMM 25-22-53
		Repaired	CMM 25-22-53
		Overhauled	CMM 25-22-53
1011659-102	SEAT	Inspected/Tested	CMM 25-22-53
		Repaired	CMM 25-22-53
		Overhauled	CMM 25-22-53
1011886-001	SEAT	Inspected/Tested	CMM 25-25-74
		Repaired	CMM 25-25-74
		Overhauled	CMM 25-25-74
1011886-002	SEAT	Inspected/Tested	CMM 25-25-74
		Repaired	CMM 25-25-74
		Overhauled	CMM 25-25-74
1011886-003	SEAT	Inspected/Tested	CMM 25-25-74
		Repaired	CMM 25-25-74
		Overhauled	CMM 25-25-74
1011886-101	SEAT	Inspected/Tested	CMM 25-25-74
		Repaired	CMM 25-25-74
		Overhauled	CMM 25-25-74
1011886-102	SEAT	Inspected/Tested	CMM 25-25-74
		Repaired	CMM 25-25-74
		Overhauled	CMM 25-25-74
1011886-103	SEAT	Inspected/Tested	CMM 25-25-74
		Repaired	CMM 25-25-74
		Overhauled	CMM 25-25-74
1011886-201	SEAT	Inspected/Tested	CMM 25-25-74
		Repaired	CMM 25-25-74
		Overhauled	CMM 25-25-74
1011886-202	SEAT	Inspected/Tested	CMM 25-25-74

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
1011886-203	SEAT	Repaired	CMM 25-25-74
		Overhauled	CMM 25-25-74
		Inspected/Tested	CMM 25-25-74
1014026-019KF02	TABLE ASSEMBLY	Repaired	CMM 25-25-74
		Overhauled	CMM 25-25-74
		Inspected/Tested	CMM 25-22-57
1014716-001	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
1014716-002	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
1014716-003	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
1014716-005	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
1014716-006	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
1014716-101	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
1014716-102	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
1014716-103	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
1014716-201	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
1014716-202	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
1014716-203	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
1014716-501	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
1014716-502	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
1014716-503	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
1014716-505	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
1014716-506	SEAT	Inspected/Tested	CMM 25-26-79

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
1014716-601	SEAT	Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
		Inspected/Tested	CMM 25-26-79
1014716-602	SEAT	Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
		Inspected/Tested	CMM 25-26-79
1014716-603	SEAT	Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
		Inspected/Tested	CMM 25-26-79
1014716-701	SEAT	Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
		Inspected/Tested	CMM 25-26-79
1014716-702	SEAT	Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
		Inspected/Tested	CMM 25-26-79
1014716-703	SEAT	Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
		Inspected/Tested	CMM 25-26-79
1015770-001JM04	SEAT	Repaired	CMM 25-25-70
		Overhauled	CMM 25-25-70
		Inspected/Tested	CMM 25-25-70
1015770-002JM04	SEAT	Repaired	CMM 25-25-70
		Overhauled	CMM 25-25-70
		Inspected/Tested	CMM 25-25-70
1015770-003JM04	SEAT	Repaired	CMM 25-25-70
		Overhauled	CMM 25-25-70
		Inspected/Tested	CMM 25-25-70
1015770-005JM04	SEAT	Repaired	CMM 25-25-70
		Overhauled	CMM 25-25-70
		Inspected/Tested	CMM 25-25-70
1015770-006JM04	SEAT	Repaired	CMM 25-25-70
		Overhauled	CMM 25-25-70
		Inspected/Tested	CMM 25-25-70
1015770-201JM04	SEAT	Repaired	CMM 25-25-70
		Overhauled	CMM 25-25-70
		Inspected/Tested	CMM 25-25-70
1015770-202JM04	SEAT	Repaired	CMM 25-25-70
		Overhauled	CMM 25-25-70
		Inspected/Tested	CMM 25-25-70

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
1015770-203JM04	SEAT	Inspected/Tested	CMM 25-25-70
		Repaired	CMM 25-25-70
		Overhauled	CMM 25-25-70
1016190-001	SEAT	Inspected/Tested	CMM 25-23-62
		Repaired	CMM 25-23-62
		Overhauled	CMM 25-23-62
1016190-002	SEAT	Inspected/Tested	CMM 25-23-62
		Repaired	CMM 25-23-62
		Overhauled	CMM 25-23-62
1016190-003	SEAT	Inspected/Tested	CMM 25-23-62
		Repaired	CMM 25-23-62
		Overhauled	CMM 25-23-62
1016190-004	SEAT	Inspected/Tested	CMM 25-23-62
		Repaired	CMM 25-23-62
		Overhauled	CMM 25-23-62
1016190-005	SEAT	Inspected/Tested	CMM 25-23-62
		Repaired	CMM 25-23-62
		Overhauled	CMM 25-23-62
1016190-006	SEAT	Inspected/Tested	CMM 25-23-62
		Repaired	CMM 25-23-62
		Overhauled	CMM 25-23-62
1016190-007	SEAT	Inspected/Tested	CMM 25-23-62
		Repaired	CMM 25-23-62
		Overhauled	CMM 25-23-62
1016190-008	SEAT	Inspected/Tested	CMM 25-23-62
		Repaired	CMM 25-23-62
		Overhauled	CMM 25-23-62
1016190-101	SEAT	Inspected/Tested	CMM 25-23-62
		Repaired	CMM 25-23-62
		Overhauled	CMM 25-23-62
1016190-102	SEAT	Inspected/Tested	CMM 25-23-62
		Repaired	CMM 25-23-62
		Overhauled	CMM 25-23-62
1016190-103	SEAT	Inspected/Tested	CMM 25-23-62
		Repaired	CMM 25-23-62
		Overhauled	CMM 25-23-62
1016190-104	SEAT	Inspected/Tested	CMM 25-23-62
		Repaired	CMM 25-23-62
		Overhauled	CMM 25-23-62
1016706-001JM06	SEAT	Inspected/Tested	CMM 25-23-58
		Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
1016706-002JM06	SEAT	Inspected/Tested	CMM 25-23-58
		Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
1016706-005JM06	SEAT	Inspected/Tested	CMM 25-23-58
		Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
1016706-006JM06	SEAT	Inspected/Tested	CMM 25-23-58
		Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
1016706-007JM06	SEAT	Inspected/Tested	CMM 25-23-58
		Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
1016706-008JM06	SEAT	Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
		Inspected/Tested	CMM 25-23-58
1016706-101JM06	SEAT	Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
		Inspected/Tested	CMM 25-23-58
1016706-102JM06	SEAT	Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
		Inspected/Tested	CMM 25-23-58
1016706-103JM06	SEAT	Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
		Inspected/Tested	CMM 25-23-58
1016706-104JM06	SEAT	Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
		Inspected/Tested	CMM 25-23-58
1016708-001JM06	SEAT	Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
		Inspected/Tested	CMM 25-23-58
1016708-002JM06	SEAT	Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
		Inspected/Tested	CMM 25-23-58
1016708-005JM06	SEAT	Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
		Inspected/Tested	CMM 25-23-58
1016708-006JM06	SEAT	Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
		Inspected/Tested	CMM 25-23-58
1016708-007JM06	SEAT	Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
		Inspected/Tested	CMM 25-23-58
1016708-008JM06	SEAT	Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
		Inspected/Tested	CMM 25-23-58
1016708-101JM06	SEAT	Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
		Inspected/Tested	CMM 25-23-58
1016708-102JM06	SEAT	Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
		Inspected/Tested	CMM 25-23-58
1016710-001JM06	SEAT	Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
		Inspected/Tested	CMM 25-23-58
1016710-005JM06	SEAT	Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
		Inspected/Tested	CMM 25-23-58
1016710-101JM06	SEAT	Repaired	CMM 25-23-58
		Overhauled	CMM 25-23-58
		Inspected/Tested	CMM 25-23-58
1046540-001	SEAT	Repaired	CMM 25-23-055
		Overhauled	CMM 25-23-055
		Inspected/Tested	CMM 25-23-055

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
1046540-002	SEAT	Inspected/Tested	CMM 25-23-055
		Repaired	CMM 25-23-055
		Overhauled	CMM 25-23-055
1046540-003	SEAT	Inspected/Tested	CMM 25-23-055
		Repaired	CMM 25-23-055
		Overhauled	CMM 25-23-055
1046540-004	SEAT	Inspected/Tested	CMM 25-23-055
		Repaired	CMM 25-23-055
		Overhauled	CMM 25-23-055
1046540-005	SEAT	Inspected/Tested	CMM 25-23-055
		Repaired	CMM 25-23-055
		Overhauled	CMM 25-23-055
1046540-008	SEAT	Inspected/Tested	CMM 25-23-055
		Repaired	CMM 25-23-055
		Overhauled	CMM 25-23-055
1046540-009	SEAT	Inspected/Tested	CMM 25-23-055
		Repaired	CMM 25-23-055
		Overhauled	CMM 25-23-055
1046540-017	SEAT	Inspected/Tested	CMM 25-23-055
		Repaired	CMM 25-23-055
		Overhauled	CMM 25-23-055
1046540-018	SEAT	Inspected/Tested	CMM 25-23-055
		Repaired	CMM 25-23-055
		Overhauled	CMM 25-23-055
1046540-019	SEAT	Inspected/Tested	CMM 25-23-055
		Repaired	CMM 25-23-055
		Overhauled	CMM 25-23-055
1046540-020	SEAT	Inspected/Tested	CMM 25-23-055
		Repaired	CMM 25-23-055
		Overhauled	CMM 25-23-055
1046540-111	SEAT	Inspected/Tested	CMM 25-23-055
		Repaired	CMM 25-23-055
		Overhauled	CMM 25-23-055
1046540-114	SEAT	Inspected/Tested	CMM 25-23-055
		Repaired	CMM 25-23-055
		Overhauled	CMM 25-23-055
1046540-115	SEAT	Inspected/Tested	CMM 25-23-055
		Repaired	CMM 25-23-055
		Overhauled	CMM 25-23-055
1046540-116	SEAT	Inspected/Tested	CMM 25-23-055
		Repaired	CMM 25-23-055
		Overhauled	CMM 25-23-055
1046542-122	SEAT	Inspected/Tested	CMM 25-23-055
		Repaired	CMM 25-23-055
		Overhauled	CMM 25-23-055
1079833-001JM03	SEAT	Inspected/Tested	CMM 25-20-70
		Repaired	CMM 25-20-70
		Overhauled	CMM 25-20-70
1079833-002JM03	SEAT	Inspected/Tested	CMM 25-20-70
		Repaired	CMM 25-20-70
		Overhauled	CMM 25-20-70
1079833-003JM03	SEAT	Inspected/Tested	CMM 25-20-70

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
1079833-101JM03	SEAT	Repaired	CMM 25-20-70
		Overhauled	CMM 25-20-70
		Inspected/Tested	CMM 25-20-70
1079833-102JM03	SEAT	Repaired	CMM 25-20-70
		Overhauled	CMM 25-20-70
		Inspected/Tested	CMM 25-20-70
1079833-103JM03	SEAT	Repaired	CMM 25-20-70
		Overhauled	CMM 25-20-70
		Inspected/Tested	CMM 25-20-70
1079833-201JM03	SEAT	Repaired	CMM 25-20-70
		Overhauled	CMM 25-20-70
		Inspected/Tested	CMM 25-20-70
1079833-202JM03	SEAT	Repaired	CMM 25-20-70
		Overhauled	CMM 25-20-70
		Inspected/Tested	CMM 25-20-70
1079833-203JM03	SEAT	Repaired	CMM 25-20-70
		Overhauled	CMM 25-20-70
		Inspected/Tested	CMM 25-20-70
1082756-001JM11	SEAT	Repaired	CMM 25-26-082
		Overhauled	CMM 25-26-082
		Inspected/Tested	CMM 25-26-082
1082756-002JM11	SEAT	Repaired	CMM 25-26-082
		Overhauled	CMM 25-26-082
		Inspected/Tested	CMM 25-26-082
1082756-011JM11	SEAT	Repaired	CMM 25-26-082
		Overhauled	CMM 25-26-082
		Inspected/Tested	CMM 25-26-082
1082756-014JM11	SEAT	Repaired	CMM 25-26-082
		Overhauled	CMM 25-26-082
		Inspected/Tested	CMM 25-26-082
1082756-101JM11	SEAT	Repaired	CMM 25-26-082
		Overhauled	CMM 25-26-082
		Inspected/Tested	CMM 25-26-082
1082756-102JM11	SEAT	Repaired	CMM 25-26-082
		Overhauled	CMM 25-26-082
		Inspected/Tested	CMM 25-26-082
1082757-001JM11	SEAT	Repaired	CMM 25-26-082
		Overhauled	CMM 25-26-082
		Inspected/Tested	CMM 25-26-082
1082757-011JM11	SEAT	Repaired	CMM 25-26-082
		Overhauled	CMM 25-26-082
		Inspected/Tested	CMM 25-26-082
1082757-101JM11	SEAT	Repaired	CMM 25-26-082
		Overhauled	CMM 25-26-082
		Inspected/Tested	CMM 25-26-082
1083417-001JM09	SEAT	Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
		Inspected/Tested	CMM 25-21-45
1083417-002JM09	SEAT	Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
		Inspected/Tested	CMM 25-21-45

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
1083417-003JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-004JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-005JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-006JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-007JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-008JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-009JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-010JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-011JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-012JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-013JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-014JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-015JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-016JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-017JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-018JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-031JM09	SEAT	Inspected/Tested	CMM 25-21-45
		Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
1083417-033JM09	SEAT	Inspected/Tested	CMM 25-21-45

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
1083417-035JM09	SEAT	Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
		Inspected/Tested	CMM 25-21-45
1083417-037JM09	SEAT	Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
		Inspected/Tested	CMM 25-21-45
1083417-101JM09	SEAT	Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
		Inspected/Tested	CMM 25-21-45
1083417-102JM09	SEAT	Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
		Inspected/Tested	CMM 25-21-45
1083417-103JM09	SEAT	Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
		Inspected/Tested	CMM 25-21-45
1083417-104JM09	SEAT	Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
		Inspected/Tested	CMM 25-21-45
1083417-131JM09	SEAT	Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
		Inspected/Tested	CMM 25-21-45
1083417-133JM09	SEAT	Repaired	CMM 25-21-45
		Overhauled	CMM 25-21-45
		Inspected/Tested	CMM 25-21-45
1098062-001JM14	SEAT	Repaired	CMM 25-22-51
		Overhauled	CMM 25-22-51
		Inspected/Tested	CMM 25-22-51
		Repaired	CMM 25-22-051
		Overhauled	CMM 25-22-051
1098062-005JM14	SEAT	Repaired	CMM 25-22-51
		Overhauled	CMM 25-22-51
		Inspected/Tested	CMM 25-22-051
		Repaired	CMM 25-22-051
		Overhauled	CMM 25-22-051
1098062-101JM14	SEAT	Repaired	CMM 25-22-51
		Overhauled	CMM 25-22-51
		Inspected/Tested	CMM 25-22-051
		Repaired	CMM 25-22-051
		Overhauled	CMM 25-22-051
1098063-004JM14	SEAT	Repaired	CMM 25-22-51
		Overhauled	CMM 25-22-51
		Inspected/Tested	CMM 25-22-51
1098063-008JM14	SEAT	Repaired	CMM 25-22-51
		Overhauled	CMM 25-22-51
		Inspected/Tested	CMM 25-22-51
1098063-104JM14	SEAT	Repaired	CMM 25-22-51
		Overhauled	CMM 25-22-51
		Inspected/Tested	CMM 25-22-51

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
2218-N-37	WHEEL CHAIR ON-BOARD	Inspected/Tested	CMM 25-20-00
2842T100-1	LATCH-XZ SINGLE	Repaired	CMM 25-52-04
2842T100-3	XZ SINGLE LATCH	Repaired	CMM 25-52-04
3510A383-21-211	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-21-212	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-22-211	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-22-212	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-011	SEAT TRIPLE	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-012	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-021	SEAT TRIPLE	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-022	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-031	SEAT TRIPLE	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-032	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-041	SEAT TRIPLE	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-042	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-051	SEAT TRIPLE	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-052	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-061	SEAT TRIPLE	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-062	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
		Overhauled	CMM 25-25-63
3510A383-31-071	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-072	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-081	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-082	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-091	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-092	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-101	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-111	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-121	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-211	TRIPLE SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-212	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-231	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-232	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-241	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-242	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-31-311	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-011	SEAT TRIPLE	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-012	SEAT	Inspected/Tested	CMM 25-25-63

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-021	SEAT TRIPLE	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-022	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-031	SEAT TRIPLE	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-032	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-041	SEAT TRIPLE	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-042	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-051	SEAT TRIPLE	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-052	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-061	SEAT TRIPLE	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-062	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-071	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-072	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-081	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-082	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-091	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-092	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-101	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
3510A383-32-111	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-121	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-211	TRIPLE SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-212	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-231	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-232	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-241	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-242	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3510A383-32-311	SEAT	Inspected/Tested	CMM 25-25-63
		Repaired	CMM 25-25-63
		Overhauled	CMM 25-25-63
3517200-102	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517200-104	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517200-106	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517200-108	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517200-10A	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517200-10B	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517200-10F	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517200-10G	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517200-110	SEAT	Inspected/Tested	CMM 25-01-44

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
3517200-114	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44
3517200-116	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44
3517200-118	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44
3517200-120	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44
3517200-12A	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44
3517200-12F	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44
3517200-136	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44
3517200-14A	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44
3517200-14B	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44
3517200-14F	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44
3517200-14G	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44
3517200-16A	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44
3517200-16B	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44
3517200-16C	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44
3517200-16F	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44
3517200-16G	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44
3517200-18A	SEAT	Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
		Inspected/Tested	CMM 25-01-44

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
3517200-18B	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517200-18F	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517200-18G	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517201-12C	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517201-12H	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517201-132	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517201-134	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517201-14C	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517201-14H	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-101	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-103	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-105	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-107	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-109	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-113	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-115	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-117	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-119	SEAT	Inspected/Tested	CMM 25-01-44

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-11A	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-11F	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-135	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-13A	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-13B	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-13F	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-13G	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-15A	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-15B	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-15C	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-15F	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-15G	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-17A	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-17B	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-17F	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-17G	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-19A	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
3517210-19B	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-19F	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517210-19G	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517211-11C	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517211-11H	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517211-131	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517211-133	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517211-13C	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517211-13H	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517220-12D	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517220-142	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517220-18H	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517221-146	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517221-16D	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517221-16H	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517230-11D	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517230-141	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517230-17H	SEAT	Inspected/Tested	CMM 25-01-44

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517231-145	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517231-15D	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517231-15H	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517340-10E	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517340-10J	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517340-155	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517340-157	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517340-158	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517340-159	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517340-15E	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517340-160	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517340-17E	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517340-17J	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517340-18E	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517340-18J	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517340-19E	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517340-19J	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
3517341-156	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517341-16E	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517440-10D	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517440-11E	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517440-12E	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517440-144	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517440-14D	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517440-150	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517440-151	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517440-152	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3517440-153	SEAT	Inspected/Tested	CMM 25-01-44
		Repaired	CMM 25-01-44
		Overhauled	CMM 25-01-44
3530A977-22-221	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-31-011	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-31-021	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-31-031	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-31-041	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-31-051	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-31-061	SEAT	Inspected/Tested	CMM 25-26-59

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-31-071	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-31-081	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-31-121	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-31-211	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-31-221	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-32-011	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-32-021	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-32-031	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-32-041	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-32-051	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-32-061	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-32-071	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-32-081	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-32-111	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-32-121	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3530A977-32-211	SEAT	Inspected/Tested	CMM 25-26-59
		Repaired	CMM 25-26-59
		Overhauled	CMM 25-26-59
3710 CV 29 - 21 - 151	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
3710 CV 29 - 22 - 151	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 31 - 011	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 31 - 021	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 31 - 031	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 31 - 041	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 31 - 051	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 31 - 061	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 31 - 071	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 31 - 081	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 31 - 091	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 31 - 101	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 31 - 111	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 31 - 121	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 31 - 131	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 31 - 141	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 31 - 161	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 31 - 171	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 32 - 011	SEAT	Inspected/Tested	CMM 25-28-86

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 32 - 021	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 32 - 031	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 32 - 041	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 32 - 051	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 32 - 061	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 32 - 071	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 32 - 081	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 32 - 091	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 32 - 101	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 32 - 111	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 32 - 121	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 32 - 131	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 32 - 141	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 32 - 161	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
3710 CV 29 - 32 - 171	SEAT	Inspected/Tested	CMM 25-28-86
		Repaired	CMM 25-28-86
		Overhauled	CMM 25-28-86
4360004-85-0018	HEATER WATER	Inspected/Tested	CMM 25-33-49
4400B420-21-011	SEAT	Inspected/Tested	CMM 25-26-60
		Repaired	CMM 25-26-60
		Overhauled	CMM 25-26-60
4400B420-21-021	SEAT	Inspected/Tested	CMM 25-26-60

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
		Repaired	CMM 25-26-60
		Overhauled	CMM 25-26-60
4400B420-21-031	SEAT	Inspected/Tested	CMM 25-26-60
		Repaired	CMM 25-26-60
		Overhauled	CMM 25-26-60
4400B420-22-011	SEAT	Inspected/Tested	CMM 25-26-60
		Repaired	CMM 25-26-60
		Overhauled	CMM 25-26-60
4400B420-22-021	SEAT	Inspected/Tested	CMM 25-26-60
		Repaired	CMM 25-26-60
		Overhauled	CMM 25-26-60
4400B420-22-031	SEAT	Inspected/Tested	CMM 25-26-60
		Repaired	CMM 25-26-60
		Overhauled	CMM 25-26-60
4710 AY 09 - 21 - 011	SEAT	Inspected/Tested	CMM 25-28-84
		Repaired	CMM 25-28-84
		Overhauled	CMM 25-28-84
4710 AY 09 - 21 - 021	SEAT	Inspected/Tested	CMM 25-28-84
		Repaired	CMM 25-28-84
		Overhauled	CMM 25-28-84
4710 AY 09 - 21 - 031	SEAT	Inspected/Tested	CMM 25-28-84
		Repaired	CMM 25-28-84
		Overhauled	CMM 25-28-84
4710 AY 09 - 21 - 041	SEAT	Inspected/Tested	CMM 25-28-84
		Repaired	CMM 25-28-84
		Overhauled	CMM 25-28-84
4710 AY 09 - 22 - 011	SEAT	Inspected/Tested	CMM 25-28-84
		Repaired	CMM 25-28-84
		Overhauled	CMM 25-28-84
4710 AY 09 - 22 - 021	SEAT	Inspected/Tested	CMM 25-28-84
		Repaired	CMM 25-28-84
		Overhauled	CMM 25-28-84
4710 AY 09 - 22 - 031	SEAT	Inspected/Tested	CMM 25-28-84
		Repaired	CMM 25-28-84
		Overhauled	CMM 25-28-84
4710 AY 09 - 22 - 041	SEAT	Inspected/Tested	CMM 25-28-84
		Repaired	CMM 25-28-84
		Overhauled	CMM 25-28-84
5077501-001JM10	SEAT	Inspected/Tested	CMM 25-29-062
		Repaired	CMM 25-29-062
		Overhauled	CMM 25-29-062
5077501-003JM10	SEAT	Inspected/Tested	CMM 25-29-062
		Repaired	CMM 25-29-062
		Overhauled	CMM 25-29-062
5077501-005JM10	SEAT	Inspected/Tested	CMM 25-29-062
		Repaired	CMM 25-29-062
		Overhauled	CMM 25-29-062
550MBB1	HANDLE	Repaired	AMM 25-20-00-370-003-A - Airbus
5834201-02	SEATS RH STC	Inspected/Tested	CMM 25-00-13
		Repaired	CMM 25-00-13
		Overhauled	CMM 25-00-13
5834201-06	SEAT	Inspected/Tested	CMM 25-00-13

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
		Repaired	CMM 25-00-13
		Overhauled	CMM 25-00-13
5834201-12	BC Seats, RH	Inspected/Tested	CMM 25-00-13
		Repaired	CMM 25-00-13
		Overhauled	CMM 25-00-13
5834201-16	SEAT	Inspected/Tested	CMM 25-00-13
		Repaired	CMM 25-00-13
		Overhauled	CMM 25-00-13
5834201-22	SEAT	Inspected/Tested	CMM 25-00-13
		Repaired	CMM 25-00-13
		Overhauled	CMM 25-00-13
5834211-01	SEATS LH 1STC	Inspected/Tested	CMM 25-00-13
		Repaired	CMM 25-00-13
		Overhauled	CMM 25-00-13
5834211-03	SEATS LH 1STC	Inspected/Tested	CMM 25-00-13
		Repaired	CMM 25-00-13
		Overhauled	CMM 25-00-13
5834211-05	SEAT	Inspected/Tested	CMM 25-00-13
		Repaired	CMM 25-00-13
		Overhauled	CMM 25-00-13
5834211-11	BC Seat,LH	Inspected/Tested	CMM 25-00-13
		Repaired	CMM 25-00-13
		Overhauled	CMM 25-00-13
5834211-15	SEAT	Inspected/Tested	CMM 25-00-13
		Repaired	CMM 25-00-13
		Overhauled	CMM 25-00-13
5834211-21	SEAT	Inspected/Tested	CMM 25-00-13
		Repaired	CMM 25-00-13
		Overhauled	CMM 25-00-13
850576-406-02	Passenger seat	Inspected/Tested	CMM 25-24-76
		Repaired	CMM 25-24-76
		Overhauled	CMM 25-24-76
865209-401	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865209-402	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865210-401	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865210-402	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865210-403	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865210-404	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865211-401	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
865211-402	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865212-401	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865212-402	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865213-401	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865213-402	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865214-401	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865214-402	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865214-403	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865214-404	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865214-405	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865214-406	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865215-401	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865215-402	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865216-401	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865217-401	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865217-403	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865218-401	SEAT	Inspected/Tested	CMM 25-28-59
		Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
865219-401	SEAT	Inspected/Tested	CMM 25-28-59

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
865220-401	SEAT	Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
		Inspected/Tested	CMM 25-28-59
865221-401	SEAT	Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
		Inspected/Tested	CMM 25-28-59
865-221-401	SEAT	Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
		Inspected/Tested	CMM 25-28-59
865222-401	SEAT	Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
		Inspected/Tested	CMM 25-28-59
865-222-401	SEAT	Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
		Inspected/Tested	CMM 25-28-59
865223-401	SEAT	Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
		Inspected/Tested	CMM 25-28-59
865-223-401	SEAT	Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
		Inspected/Tested	CMM 25-28-59
865224-401	SEAT	Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
		Inspected/Tested	CMM 25-28-59
865-224-401	SEAT	Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
		Inspected/Tested	CMM 25-28-59
865225-401	SEAT	Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
		Inspected/Tested	CMM 25-28-59
865-225-401	SEAT	Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
		Inspected/Tested	CMM 25-28-59
865271-401	SEAT	Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
		Inspected/Tested	CMM 25-28-59
865271-403	SEAT	Repaired	CMM 25-28-59
		Overhauled	CMM 25-28-59
		Inspected/Tested	CMM 25-28-59
869853-401	SEAT ASSY	Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
		Inspected/Tested	CMM 25-29-67
869853-402	SEAT ASSY	Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
		Inspected/Tested	CMM 25-29-67
869853-403	SEAT ASSY	Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
		Inspected/Tested	CMM 25-29-67
869853-404	SEAT ASSY	Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
		Inspected/Tested	CMM 25-29-67

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
869853-405	SEAT ASSY	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-406	SEAT ASSY	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-407	SEAT ASSY	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-408	SEAT ASSY	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-410	SEAT	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-411	SEAT	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-412	SEAT	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-413	SEAT	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-414	SEAT	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-415	SEAT	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-416	SEAT	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-417	SEAT	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-418	SEAT	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-419	SEAT	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-420	SEAT	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-421	SEAT	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-422	SEAT	Inspected/Tested	CMM 25-29-67
		Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
869853-423	SEAT	Inspected/Tested	CMM 25-29-67

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
869853-424	SEAT	Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
		Inspected/Tested	CMM 25-29-67
869853-425	SEAT	Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
		Inspected/Tested	CMM 25-29-67
869853-427	SEAT	Repaired	CMM 25-29-67
		Overhauled	CMM 25-29-67
		Inspected/Tested	CMM 25-29-67
873719-401	SEAT ASSY	Repaired	CMM 25-20-121
		Overhauled	CMM 25-20-121
		Inspected/Tested	CMM 25-20-121
873719-402	SEAT ASSY	Repaired	CMM 25-20-121
		Overhauled	CMM 25-20-121
		Inspected/Tested	CMM 25-20-121
873719-403	SEAT ASSY	Repaired	CMM 25-20-121
		Overhauled	CMM 25-20-121
		Inspected/Tested	CMM 25-20-121
873719-404	SEAT ASSY	Repaired	CMM 25-20-121
		Overhauled	CMM 25-20-121
		Inspected/Tested	CMM 25-20-121
873719-405	SEAT ASSY	Repaired	CMM 25-20-121
		Overhauled	CMM 25-20-121
		Inspected/Tested	CMM 25-20-121
873719-406	SEAT ASSY	Repaired	CMM 25-20-121
		Overhauled	CMM 25-20-121
		Inspected/Tested	CMM 25-20-121
873719-407	SEAT ASSY	Repaired	CMM 25-20-121
		Overhauled	CMM 25-20-121
		Inspected/Tested	CMM 25-20-121
873719-408	SEAT ASSY	Repaired	CMM 25-20-121
		Overhauled	CMM 25-20-121
		Inspected/Tested	CMM 25-20-121
873719-409	SEAT ASSY	Repaired	CMM 25-20-121
		Overhauled	CMM 25-20-121
		Inspected/Tested	CMM 25-20-121
873719-410	SEAT ASSY	Repaired	CMM 25-20-121
		Overhauled	CMM 25-20-121
		Inspected/Tested	CMM 25-20-121
873719-411	SEAT ASSY	Repaired	CMM 25-20-121
		Overhauled	CMM 25-20-121
		Inspected/Tested	CMM 25-20-121
873719-412	SEAT ASSY	Repaired	CMM 25-20-121
		Overhauled	CMM 25-20-121
		Inspected/Tested	CMM 25-20-121
873719-413	SEAT ASSY	Repaired	CMM 25-20-121
		Overhauled	CMM 25-20-121
		Inspected/Tested	CMM 25-20-121
873719-414	SEAT ASSY	Repaired	CMM 25-20-121
		Overhauled	CMM 25-20-121
		Inspected/Tested	CMM 25-20-121

PN	Description	Cert. Status	Documentation/Note
9580201-32	SEAT	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580211-31	SEAT	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580300-02	SEAT TRIPPLE RH	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580300-08	SEATS RH	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580300-18	SEAT - TRIPLE RH	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580300-20	SEAT - TRIPLE RH	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580300-22	SEAT - TRIPLE RH	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580300-24	SEATS	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580300-26	SEATS	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580300-28	SEAT TRIPPLE R/H	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580300-38	SEAT	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580301-14	SEATS RH	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580301-30	SEAT	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580301-44	SEAT	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580310-01	SEAT TRIPPLE LH	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580310-03	SEAT TRIPPLE LH	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580310-05	SEAT - TRIPLE LH	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580310-09	SEAT - TRIPLE LH	Inspected/Tested	CMM 25-00-08

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580310-15	SEAT - TRIPLE LH	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580310-19	SEATS LH	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580310-21	SEATS LH	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580310-23	SEAT - TRIPLE LH	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580310-25	SEAT - TRIPLE LH	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580310-27	setas	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580310-35	SEAT	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580311-11	SEATS LH	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580311-13	SEAT TRIPPLE	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580311-29	SEAT	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
9580311-43	SEAT	Inspected/Tested	CMM 25-00-08
		Repaired	CMM 25-00-08
		Overhauled	CMM 25-00-08
A225400414-700	CABINET SERVICE CTR PART	Repaired	AMM 25-20-00-370-003-A - Airbus
A225400434-562	HOLDER ASSY	Repaired	AMM 25-20-00-370-003-A - Airbus
A225406414-726	CABINET SERVICE	Repaired	AMM 35-20-00-370-003-A - Airbus
A2527576120800	HANDLE UPER	Repaired	AMM 25-20-00-370-005-A - Airbus
A2527576301200	ADAPTER-HANDLE	Repaired	AMM 25-20-00-370-005-A - Airbus
D2527076200600	HANDLE-LWR	Repaired	AMM 25-20-00-370-005-A - Airbus
D252-73600-000	HANDRAIL	Repaired	AMM 25-20-00-370-001-A - Airbus
D252-73600-004	HANDRAIL	Repaired	AMM 25-20-00-370-001-A - Airbus
D252-73600-006	HANDRAIL	Repaired	AMM 25-20-00-370-001-A - Airbus

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
D252-73600-007	HANDRAIL	Repaired	AMM 25-20-00-370-001-A - Airbus
D252-73600-008	HANDRAIL	Repaired	AMM 25-20-00-370-001-A - Airbus
D252-73600-012	HANDRAIL	Repaired	AMM 25-20-00-370-001-A - Airbus
D2527363000400A	HANDRAIL	Repaired	AMM 25-20-00-370-001-A - Airbus
D2527363000600A	HANDRAIL	Repaired	AMM 25-20-00-370-001-A - Airbus
D2527363000800C	HANDRAIL	Repaired	AMM 25-20-00-370-001-A - Airbus
D2527363001200A	HANDRAIL	Repaired	AMM 25-20-00-370-001-A Airbus
D2527363001400C	HANDRAIL	Repaired	AMM 25-20-00-370-001-A - Airbus
D31516-101	FWD Escape Slide	Overhauled	CMM 25-60-56
D31516-103	FWD Escape Slide	Overhauled	CMM 25-60-56
D31516-105	FWD Escape Slide	Overhauled	CMM 25-60-56
FJEV3-01SU01-01	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
FJEV3-01SU02-01	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
FJEV3-01SU03-01	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
FJEV3-01SU04-01	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
FJEV3-01SU05-01	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
FJEV3-01SU06-01	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
FJEV3-01SU07-01	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
FJEV3-01SU08-01	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
FJEV3-01SU09-01	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
FJEV3-01SU10-01	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
FJEV3-01SU11-01	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
FJEV3-01SU12-01	SEAT	Inspected/Tested	CMM 25-26-79

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
FJEV3-01SU13-01	SEAT	Inspected/Tested	CMM 25-26-79
		Repaired	CMM 25-26-79
		Overhauled	CMM 25-26-79
S1818502-02	ELT	Inspected/Tested	Kannad e-Prog V1.3.5.
S1819502-02	ELT	Inspected/Tested	Kannad e-Prog V1.3.5.
S1820502-01/-02	ELT	Inspected/Tested	Kannad e-Prog V1.3.5.
S1820502-04	ELT	Inspected/Tested	Kannad e-Prog V1.3.5.
S1820514-01	DONGLE , PROGRAMMING	Inspected/Tested	Kannad e-Prog V1.3.5.
S1820514-04	PROGRAMMING DONGLE	Inspected/Tested	Kannad e-Prog V1.3.5.
S1820514-05	PROGRAMMING DONGLE	Inspected/Tested	Kannad e-Prog V1.3.5.
S1820514-06	PROGRAMMING DONGLE	Inspected/Tested	Kannad e-Prog V1.3.5.
S1821502-01/-02/-06	ELT	Inspected/Tested	Kannad e-Prog V1.3.5.
S1822502-01/-02	ELT	Inspected/Tested	Kannad e-Prog V1.3.5.
S1823502-01/-02	ELT	Inspected/Tested	Kannad e-Prog V1.3.5.
S1823502-03	Portable ELT	Inspected/Tested	Kannad e-Prog V1.3.5.
S1823502-04	ELT	Inspected/Tested	Kannad e-Prog V1.3.5.
S1824502-01/-02	ELT	Inspected/Tested	Kannad e-Prog V1.3.5.
S1826502-02	ELT	Inspected/Tested	Kannad e-Prog V1.3.5.
Y4727DA7-25	DRAWER	Repaired	AMM 25-20-00-370-003-A - Airbus
ATA: 38			
24E50700PG01	WATER HEATER	Inspected/Tested	CMM 38-12-16
		Repaired	CMM 38-12-16
24E50700PG02	WATER HEATER	Inspected/Tested	CMM 38-12-16
		Repaired	CMM 38-12-16
24E50700PG03	WATER HEATER	Inspected/Tested	CMM 38-12-16
		Repaired	CMM 38-12-16

C7 Engine – APU

ATA: 49

D4918529700000	AIR INTAKE DUCT	Repaired	CMM 49-16-45
----------------	-----------------	----------	--------------

ATA: 71

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
740-3000-601	NOSE COWLING ASSEMBLY	Inspected/Tested Repaired	CMM 71-11-00 CMM 71-11-00

ATA: 72

340-001-036-0	BLADE FAN	Inspected/Tested	AMM TASK 72-21-02-200-801-F00
---------------	-----------	------------------	-------------------------------

C8 Flight Controls

ATA: 27

D2727000700200	ROD SPRING	Inspected/Tested Repaired	CMM 27-26-41 CMM 27-26-41
D2727000700600	YAW DAMPER SPRING ROD	Inspected/Tested Repaired	CMM 27-26-41 CMM 27-26-41

ATA: 57.50

113A2700-21	FLAP AFT	Inspected/Tested Repaired	CMM-57-53-09 CMM-57-53-09
-------------	----------	------------------------------	------------------------------

C14 Landing Gear

ATA: 32

3-1530-2	WHEEL ASSY	Inspected/Tested Repaired	CMM 32-41-20 CMM 32-41-20
3-1531-1	NLG - WHEEL ASSY	Inspected/Tested Repaired	CMM-32-41-13 CMM-32-41-13
3-1531-3	NLG - WHEEL ASSY	Inspected/Tested Repaired	CMM-32-41-13 CMM-32-41-13

C15 Oxygen

ATA: 35

89710015	Crew Oxy Cylinder	Overhauled	CMM 35-21-93
89713015	Crew Oxy Cylinder	Overhauled	CMM 35-21-93

C17 Pneumatic & Vacuum

ATA: 36

6773E010000	BLEED,HP REGULATOR VALVE	Inspected/Tested	CMM 36-11-05
6774E010000	BLEED, PRESS REG VALVE	Inspected/Tested	CMM 36-11-06

C18 Protection ice/rain/fire

ATA: 26

34600017	CARGO FIRE EXTINGUISHER B	Inspected/Tested	CMM 26-20-06
----------	---------------------------	------------------	--------------

Valid to Date:
25.2.2022

PN	Description	Cert. Status	Documentation/Note
74-20	PORTABLE FIRE EXT	Inspected/Tested	CMM 26-24-05
BA24320A-1	FIRE EXTINGUISHER	Inspected/Tested	CMM 26-25-36

C19 Windows

ATA: 56

141A4810-3	COCPIT WINDOW NO. 2 L/H	Inspected/Tested	CMM 56-10-02
------------	-------------------------	------------------	--------------

C20 Structural

ATA: 54

D0001039000000	MOVABLE FAIRING	Inspected/Tested	CMM 54-55-11
D0001039000100	FAIRING ASSY-MOVABLE	Inspected/Tested	CMM 54-55-11

ATA: **STRUCTURE**

STRUCTURE	STRUCTURE	Repaired	Repairs I.A.W. SRM or equivalent documentation
-----------	-----------	----------	--

D1

ATA: **NDT**

EDDY CURRENT TESTING	NDT	Inspected/Tested	LII
MAGNETIC PARTICLE TESTING	NDT	Inspected/Tested	LII
PENETRANT TESTING	NDT	Inspected/Tested	LII
RADIOGRAPHIC TESTING	NDT	Inspected/Tested	LII
TERMOGRAPHY TESTING	NDT	Inspected/Tested	LII
ULTRASONIC TESTING	NDT	Inspected/Tested	LII
VISUAL TESTING	NDT	Inspected/Tested	LII